

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-029420-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

RECEIVED

2. NAME OF OPERATOR

Texaco Producing Inc.

OCT 23 '90

3. ADDRESS OF OPERATOR

P.O. Box 730 Hobbs, New Mexico 88240

O.C.D.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface

ARTESIA, OFFICE

Letter K

7. UNIT AGREEMENT NAME

Skelly Unit

8. FARM OR LEASE NAME

Skelly Unit

9. WELL NO.

155

10. FIELD AND POOL, OR WILDCAT

Fren Seven Rivers

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 28, T-17-S, R-31-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DP, RT, OR, etc.)

3765' GL

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \* 9-19-90 thru 9-21-90

1. MIRU PU POH w/ rods & pump install BOP
2. POH w/ tbg
3. GIH w/ CIBP on 2 3/8 tbg set @ 2320'
4. Pump 35 on top of CIBP
5. Load hole with salt gel mud
6. Pull up hole spot 25 sx f/1810-1625 WOC
7. Tag plug, pull up & spot 25 sx f/ 700-515 WOC
8. Tag plug, spot 7 sx 50' to surface
9. Cut off wellhead & install marker

Post ID-2  
11-9-90  
Y & H

RECEIVED  
OCT 18 10 54 AM '90

18. I hereby certify that the foregoing is true and correct

SIGNED Richard Decker

TITLE Engineering Technician

DATE 10-16-90

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE 10 19 90

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side