

RECEIVED BY

MAY 27 1985

O.C.D.

ARTESIAN OFFICE

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

NM OIL CONS. COMMISSION

Drawer DD

Alamosa, NM 88210

Form Approved.  
Budget Bureau No. 42-R1424

93F

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☒2. NAME OF OPERATOR ARCO Oil and Gas Company  
Division of Atlantic Richfield Company

3. ADDRESS OF OPERATOR

P. O. Box 1710, Hobbs, New Mexico 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1100' FNL &amp; 1200' FWL

AT TOP PROD. INTERVAL: as above

AT TOTAL DEPTH: as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐CHANGE ZONES ☐ABANDON\* ☒(other) ☐5. LEASE  
LC-067858

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME  
Empire Abo Pressure  
Maintenance Project8. FARM OR LEASE NAME  
Empire Abo Unit "M"

9. WELL NO.

131

10. FIELD OR WILDCAT NAME

Empire Abo

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

11-18S-27E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

14. API NO.

30-015-22556

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3568.3' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Propose to plug and abandon in the following manner:

1. RU, install BOP &amp; POH w/WS, tag PBD 5983'. Circ hole w/25#/bbl gel.

2. Dump 10 sx Cl H Neat cmt on top of cmt retr @ 5983'.

3. Spot 100' cmt plug 3350-3450'.

4. Spot 100' cmt plug 920-1020'. - tag

5. Cut off wellhead below GL.

6. Spot 10' cmt plug @ surf. Weld steel plate on csg and install regulation dry hole marker.

7. Clean and restore location per BLM stipulation for abandonment.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Robert E. Balling*

TITLE Drlg. Engr.

DATE 4/10/85

(This space for Federal or State office use)

APPROVED BY

*Don Ward*

TITLE

APCA MANAGER  
LEADS RESOURCE AREA

DATE

5-24-85

CONDITIONS OF APPROVAL, IF ANY: