	<i></i>		\cap `o	100	
) NS. - Dist 2 FOR	CI51
Form 3160-5		TED STATES	1301 W. Grar		Bureau No. 1004-0135
(June 1990)		LAND MANAGEMEN			ation and Serial No.
_			, , , , , , , , , , , , , , , , ,	NM0557371	
		REPORTS ON WELLS	a different reconvoir	6. If Indian Mi	SIRE ABO UNIT
	• •	or to deepen or reentry to 			NM-70945
Use				7. If Unit or CA	, Agreement Designation
	SUBMIT			8910138010	
1. Type of Well Y Oil Gas			100 10117273,	8. Well Name a	nd No.
2. Name of Operator	Other	· · · · · · · · · · · · · · · · · · ·	A 7		Unit "K" 184
BP America Produc	ction Company			9. API Well No	
3. Address and Telephone No).		RE0 2002	3 30-015-225	
<u>P.O. Box 1089, Eu</u>		505-394	-16490 RECEIVED	10. Field and Po	ool, or exploratory Area
	Sec., T., R., M., or Survey Descri	iption)	ARTESIA	ଞ୍ଚ/Empire Abo	
Unit K, 2290' FSL Sec. 1, T18S, R27				11. County or H	Parish, State
Jec. 1, 1103, (AL)	E		229707+7.ELLO	Eddy	NM
12. CHECK AF	PROPRIATE BOX() TO INDICATE NATU	RE OF NOTICE, REF	PORT, OR OTH	ER DATA
TYPE OF SU		•	TYPE OF ACTIO		
		Abandon	nent		of Plans
Notice of Intent		Recomplet		n ř	nstruction
Subsequent Report				Non-Ro	utine Fracturing
LX_] Subsequer					
		Plugging I		Water Si	•
	ndonment Notice		pair	Water Sl	•
	_	Casing Re	pair	Water Sl	nut-Off ion to Injection Water
Final Abar	ndonment Notice	Casing Re Altering C Other	pair asing Workover	Water Sl Water Sl Convers Dispose (Note: Report r Completion or	nut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log for</u> m.)
Final Abar	ndonment Notice	Casing Re Altering C Other	pair asing Workover	Water SI Converse Note: Report r Completion or ate of starting any prop	nut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log for</u> m.) osed work. If well is directionally
Final Abar 3. Describe Proposed or Comple give subsurfacelocat	ndonment Notice eted Operations (Clearly state a ionsand measuredand true verti	Casing Re Altering C Other all pertinent details, and give pertine cal depthsfor all markersand zonesp	pair asing Workover nt dates, including estimated da ertinentio this work.)*	Water SI Converse Note: Report r Completion or ate of starting any prop	nut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log for</u> m.) osed work. If well is directionally
Final Abar	ndonment Notice eted Operations (Clearly state a ionsand measuredand true verti	Casing Re Altering C Other	pair asing Workover nt dates, including estimated da ertinentio this work.)*	Water SI Converse Note: Report r Completion or ate of starting any prop	nut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log for</u> m.)
Final Abaa 3. Describe Proposed or Comple give subsurfacelocat TD: 6200' PBD: 01.17.02: MIRUPU	ndonment Notice eted Operations (Clearly state a ionsand measured and true verti 6188' PERFS: 597 J. NDWH. NUBOP. U	Casing Re Altering C Other	pair asing Workover nt dates, including estimated da ertinentto this work.)* 930' (old) 11.	Water SI Converse Note: Report r Completion or ate of starting any prop	hut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log form.</u>) osed work. If well is directionally PIEDFOR RECOM
Final Abau 3. Describe Proposed or Comple give subsurfacelocat TD: 6200' PBD: 01.17.02: MIRUPU 01.21.02: POH w/	ndonment Notice eted Operations (Clearly state a ionsand measuredand true verti 6188' PERFS: 597 J. NDWH. NUBOP. U 'tbg & pkr. RIH w/t	Casing Re Altering C Other all pertinent details, and give pertine ical depthsfor all markersand zonesp 79-6139' (new), 5792-59 Juset pkr. Tag for fi poit & scraper to 5980'	pair asing <u>Workover</u> nt dates, including estimated da ertinentto this work.)* 930' (old) 11.	Water SI Converse Note: Report r Completion or ate of starting any prop	nut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log for</u> m.) osed work. If well is directionally
Final Abau 3. Describe Proposed or Comple give subsurfacelocat TD: 6200' PBD: 01.17.02: MIRUPU 01.21.02: POH w/ 01.22.02: RIH w/	ndonment Notice eted Operations (Clearly state a ionsand measured and true verti 6188' PERFS: 597 J. NDWH. NUBOP. U 'tbg & pkr. RIH w/b 'sand line bailer.	Casing Re Altering C Other	pair asing <u>Workover</u> Int dates, including estimated da ertinentto this work.)* 930' (old) 11. Dock out to 6121'.	Water SI Converse Dispose (Note: Report n Completion or ate of starting any prop	hut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log for</u> m.) osed work. If well is directionally <u>PTED FOR RECOR</u> MAR 8
Final Abau 3. Describe Proposed or Comple give subsurfacelocat TD: 6200' PBD: 01.17.02: MIRUPU 01.21.02: POH w/ 01.22.02: RIH w/ 01.23.02: RU to	ndonment Notice eted Operations (Clearly state a ionsand measured and true verti 6188' PERFS: 597 J. NDWH. NUBOP. U 'tbg & pkr. RIH w/b 'sand line bailer. perf & tagged @ 564	Casing Re Altering C Other all pertinent details, and give pertine ical depthsfor all markersand zonesp 79-6139' (new), 5792-59 Juset pkr. Tag for fi poit & scraper to 5980'	pair asing <u>Workover</u> Int dates, including estimated da ertinentto this work.)* 930' (old) 11. Dock out to 6121'.	Water SI Converse Note: Report r Completion or ate of starting any propu	nut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log for</u> m.) osed work. If well is directionally <u>PTEDFOR RECOR</u> MAR S
Final Abau 3. Describe Proposed or Comple give subsurfacelocat TD: 6200' PBD: 01.17.02: MIRUPU 01.21.02: POH w/ 01.22.02: RIH w/ 01.23.02: RU to plug c	ndonment Notice eted Operations (Clearly state a ionsand measured and true verti 6188' PERFS: 597 J. NDWH. NUBOP. U 'tbg & pkr. RIH w/b 'sand line bailer. perf & tagged @ 564 lown. Stuck.	Casing Re Altering C Other	pair asing <u>Workover</u> Int dates, including estimated da ertinentto this work.)* 930' (old) 11. Dock out to 6121'.	Water SI Converse Note: Report r Completion or ate of starting any propu	hut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log for</u> m.) osed work. If well is directionally <u>PTED FOR RECOR</u> MAR 8
Final Abau 3. Describe Proposed or Comple give subsurfacelocat TD: 6200' PBD: 01.17.02: MIRUPU 01.21.02: POH w/ 01.22.02: RIH w/ 01.23.02: RU to plug c 01.29.02: Drill	ndonment Notice eted Operations (Clearly state a ionsand measured and true verti 6188' PERFS: 597 J. NDWH. NUBOP. U 'tbg & pkr. RIH w/b 'sand line bailer. perf & tagged @ 564 lown. Stuck. out CIBP.	Casing Re Altering C Other	pair asing Workover nt dates, including estimated da ertinentio this work.)* 930' (old) 11. ock out to 6121'. d line bailer to kno	Water SI Convers Note: Report r Completion or ate of starting any propu	nut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log for</u> m.) osed work. If well is directionally PTED FOR RECOR MAR S
Final Abau 3. Describe Proposed or Comple give subsurfacelocat TD: 6200' PBD: 01.17.02: MIRUPU 01.21.02: POH w/ 01.22.02: RIH w/ 01.23.02: RU to plug c 01.29.02: Drill 01.30.02: RU & p RIH w/	ndonment Notice ted Operations (Clearly state a ionsand measured and true verti 6188' PERFS: 597 J. NDWH. NUBOP. U 'tbg & pkr. RIH w/l 'sand line bailer. perf & tagged @ 564 lown. Stuck. out CIBP. perf 2 JSPF 5979-599 'pkr & tbg to 6139'	Casing Re Altering C Other	pair asing <u>Workover</u> Int dates, including estimated da ertinentto this work.)* 930' (old) 11. Dock out to 6121'. d line bailer to kno 22, 6128-6139'. RDW	Water SI Convers Dispose (Note: Report n Completion or ate of starting any propu ACCE OCK UL.	nut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log for</u> m.) osed work. If well is directionally <u>PTEDFOR RECOR</u> MAR <u>S</u>
Final Abau 3. Describe Proposed or Comple give subsurfacelocat TD: 6200' PBD: 01.17.02: MIRUPU 01.21.02: POH w/ 01.22.02: RIH w/ 01.23.02: RU to plug c 01.29.02: Drill 01.30.02: RU & p RIH w/ 01.31.02: Acidiz	ndonment Notice ted Operations (Clearly state a ionsand measured and true verti 6188' PERFS: 597 J. NDWH. NUBOP. U 'tbg & pkr. RIH w/k 'sand line bailer. perf & tagged @ 564 lown. Stuck. out CIBP. perf 2 JSPF 5979-599 'pkr & tbg to 6139' ze w/500 gals 15% H0	Casing Re Altering C Other	pair asing <u>Workover</u> Int dates, including estimated da ertinentto this work.)* 930' (old) 11. bock out to 6121'. d line bailer to kno 22, 6128-6139'. RDW r @ 5879'. Pmp 6500	Water SI Convers Dispose (Note: Report r Completion or ale of starting any prop ACCE ock	nut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log for</u> m.) osed work. If well is directionally <u>PTEDFOR RECOR</u> MAR 8
Final Abau 3. Describe Proposed or Comple give subsurfacelocat TD: 6200' PBD: 01.17.02: MIRUPU 01.21.02: POH w/ 01.22.02: RIH w/ 01.23.02: RU to plug co 01.29.02: Drill 01.30.02: RU & p RIH w/ 01.31.02: Acidiz HCL w/	ndonment Notice eted Operations (Clearly state a ionsand measuredand true verti 6188' PERFS: 597 J. NDWH. NUBOP. U 'tbg & pkr. RIH w/k 'sand line bailer. perf & tagged @ 564 iown. Stuck. out CIBP. perf 2 JSPF 5979-599 'pkr & tbg to 6139' ze w/500 gals 15% H0 '1.1 ball sealers, 2	Casing Re Altering C Other	pair asing <u>Workover</u> Int dates, including estimated da ertinentto this work.)* 930' (old) 11. bock out to 6121'. d line bailer to kno 22, 6128-6139'. RDW r @ 5879'. Pmp 6500	Water SI Convers Dispose (Note: Report r Completion or ale of starting any prop ACCE ock	nut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log for</u> m.) osed work. If well is directionally <u>PTEDFOR RECOR</u> MAR 8
Final Abau 3. Describe Proposed or Comple give subsurfacelocat TD: 6200' PBD: 01.17.02: MIRUPU 01.21.02: POH w/ 01.22.02: RIH w/ 01.23.02: RU to plug co 01.29.02: Drill 01.30.02: RU & p RIH w/ 01.31.02: Acidiz HCL w/ recover	ndonment Notice eted Operations (Clearly state a ionsand measured and true verti 6188' PERFS: 597 J. NDWH. NUBOP. U 'tbg & pkr. RIH w/b 'sand line bailer. perf & tagged @ 564 iown. Stuck. out CIBP. perf 2 JSPF 5979-599 'pkr & tbg to 6139' ze w/500 gals 15% H0 (1.1 ball sealers, 2 er 213 bbls.	Casing Re Altering C Other	pair asing Workover Int dates, including estimated da ertinentto this work.)* 930' (old) 11.	Water SI Converse Dispose (Note: Report r Completion or ate of starting any propu- ate of starting any propu- difference occk	hut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log form.</u>) osed work. If well is directionally <u>PTEDFOR RECOR</u> MAR 8
Final Abau 3. Describe Proposed or Comple give subsurfacelocat TD: 6200' PBD: 01.17.02: MIRUPU 01.21.02: POH w/ 01.22.02: RIH w/ 01.23.02: RU to plug c 01.29.02: Drill 01.30.02: RU & p RIH w/ 01.31.02: Acidiz HCL w/ recove 02.01.02: RIH w/	ndonment Notice eted Operations (Clearly state a ionsand measured and true verti 6188' PERFS: 597 J. NDWH. NUBOP. U 'tbg & pkr. RIH w/b 'sand line bailer. perf & tagged @ 564 iown. Stuck. out CIBP. perf 2 JSPF 5979-599 'pkr & tbg to 6139' ze w/500 gals 15% H0 (1.1 ball sealers, 2 er 213 bbls.	Casing Re Altering C Other	pair asing Workover Int dates, including estimated da ertinentto this work.)* 930' (old) 11.	Water SI Converse Dispose (Note: Report r Completion or ate of starting any propu- ate of starting any propu- difference occk	nut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log for</u> m.) osed work. If well is directionally PTED FOR RECOR MAR S
Final Abau 3. Describe Proposed or Comple give subsurfacelocat TD: 6200' PBD: 01.17.02: MIRUPL 01.21.02: POH w/ 01.22.02: RIH w/ 01.23.02: RU to plug c 01.29.02: Drill 01.30.02: RU & p RIH w/ 01.31.02: Acidiz HCL w/ recove 02.01.02: RIH w/	ndonment Notice eted Operations (Clearly state a ionsand measured and true verti 6188' PERFS: 597 J. NDWH. NUBOP. U 'tbg & pkr. RIH w/l 'sand line bailer. perf & tagged @ 564 lown. Stuck. out CIBP. perf 2 JSPF 5979-599 'pkr & tbg to 6139' te w/500 gals 15% HG '1.1 ball sealers, 2 er 213 bbls. '194 jts 2-3/8" tbg	Casing Re Altering C Other	pair asing Workover Int dates, including estimated da ertinentto this work.)* 930' (old) 11.	Water SI Converse Dispose (Note: Report r Completion or ate of starting any propu- ate of starting any propu- difference occk	nut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log for</u> m.) osed work. If well is directionally PTED FOR RECOR MAR S
Final Abau 3. Describe Proposed or Comple give subsurfacelocat TD: 6200' PBD: 01.17.02: MIRUPU 01.21.02: POH w/ 01.22.02: RIH w/ 01.23.02: RU to plug c 01.29.02: Drill 01.30.02: RU & p RIH w/ 01.31.02: Acidiz HCL w/ recove 02.01.02: RIH w/	ndonment Notice eted Operations (Clearly state a ionsand measured and true verti 6188' PERFS: 597 J. NDWH. NUBOP. U 'tbg & pkr. RIH w/l 'sand line bailer. perf & tagged @ 564 lown. Stuck. out CIBP. perf 2 JSPF 5979-599 'pkr & tbg to 6139' te w/500 gals 15% HG '1.1 ball sealers, 2 er 213 bbls. '194 jts 2-3/8" tbg	Casing Re Altering C Other	pair asing Workover Int dates, including estimated da ertinentto this work.)* 930' (old) 11.	Water SI Converse Dispose (Note: Report r Completion or ate of starting any propu- ate of starting any propu- difference occk	nut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log for</u> m.) osed work. If well is directionally PTED FOR RECOR MAR S
Final Abau 3. Describe Proposed or Comple give subsurfacelocat TD: 6200' PBD: 01.17.02: MIRUPU 01.21.02: POH w/ 01.22.02: RIH w/ 01.23.02: RU to plug c 01.29.02: Drill 01.30.02: RU & p RIH w/ 01.31.02: Acidiz HCL w/ recove 02.01.02: RIH w/ 02.08.02: In 24	ndonment Notice eted Operations (Clearly state a ionsandmeasuredand true verti 6188' PERFS: 597 J. NDWH. NUBOP. U 'tbg & pkr. RIH w/l 'sand line bailer. perf & tagged @ 564 iown. Stuck. out CIBP. perf 2 JSPF 5979-599 'pkr & tbg to 6139' ze w/500 gals 15% HG '1.1 ball sealers, 2 er 213 bbls. ' 194 jts 2-3/8" tbg hrs pmp'd 1 BO, 1 f	Casing Re Altering C Other	pair asing Workover Int dates, including estimated da ertinentto this work.)* 930' (old) 11.	Water SI Converse Note: Report r Completion or ate of starting any propu- ate of starting any propu- a	Aut-Off ion to Injection Water esults of multiple completion on Well Recompletion Report and Log form.) osed work. If well is directionally PTEDFOR RECOR MAR 8 LES BABYAK ETROL LUM ENGINEER
Final Abau 3. Describe Proposed or Comple give subsurfacelocat TD: 6200' PBD: 01.17.02: MIRUPU 01.21.02: POH w/ 01.22.02: RIH w/ 01.23.02: RU to plug c 01.29.02: Drill 01.30.02: RU & p RIH w/ 01.31.02: Acidiz HCL w/ recove 02.01.02: RIH w/ 02.08.02: In 24	ndonment Notice eted Operations (Clearly state a ionsandmeasuredand true verti 6188' PERFS: 597 J. NDWH. NUBOP. U 'tbg & pkr. RIH w/l 'sand line bailer. perf & tagged @ 564 iown. Stuck. out CIBP. perf 2 JSPF 5979-599 'pkr & tbg to 6139' ze w/500 gals 15% HG '1.1 ball sealers, 2 er 213 bbls. ' 194 jts 2-3/8" tbg hrs pmp'd 1 BO, 1 f	Casing Re Altering C Other	pair asing Workover Int dates, including estimated da ertinentto this work.)* 930' (old) 11.	Water SI Converse Note: Report r Completion or ate of starting any propu- ate of starting any propu- a	nut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log for</u> m.) osed work. If well is directionally PTED FOR RECOR MAR S
Final Abau 3. Describe Proposed or Comple give subsurfacelocat TD: 6200' PBD: 01.17.02: MIRUPU 01.21.02: POH w/ 01.22.02: RIH w/ 01.23.02: RU to plug c 01.29.02: Drill 01.30.02: RU & p RIH w/ 01.31.02: Acidiz HCL w/ recove 02.01.02: RIH w/ 02.08.02: In 24	ndonment Notice eted Operations (Clearly state a ionsandmeasuredand true verti 6188' PERFS: 597 J. NDWH. NUBOP. U 'tbg & pkr. RIH w/k 'sand line bailer. perf & tagged @ 564 lown. Stuck. out CIBP. perf 2 JSPF 5979-599 'pkr & tbg to 6139' te w/500 gals 15% HG '1.1 ball sealers, 2 er 213 bbls. '194 jts 2-3/8" tbg hrs pmp'd 1 BO, 1 f pregoing & true and correct	Casing Re Altering C Other	pair asing Workover Int dates, including estimated da ertinentto this work.)* 930' (old) 11.	Water SI Converse Note: Report r Completion or ate of starting any propu- ate of starting any propu- a	Aut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log form.</u>) osed work. If well is directionally PTED FOR RECOR MAR 8 LES BABYAK ETROL LUM ENGINEER
Final Abau 3. Describe Proposed or Comple give subsurfacelocat TD: 6200' PBD: 01.17.02: MIRUPU 01.21.02: POH w/ 01.22.02: RIH w/ 01.23.02: RU to plug c 01.29.02: Drill 01.30.02: RU & g RIH w/ 01.31.02: Acidiz HCL w/ recove 02.01.02: RIH w/ 02.08.02: In 24	ndonment Notice eted Operations (Clearly state a ionsand measured and true verti 6188' PERFS: 597 J. NDWH. NUBOP. U 'tbg & pkr. RIH w/l 'sand line bailer. perf & tagged @ 564 lown. Stuck. out CIBP. perf 2 JSPF 5979-599 'pkr & tbg to 6139' te w/500 gals 15* H0 '1.1 ball sealers, 2 er 213 bbls. ' 194 jts 2-3/8" tbg hrs pmp'd 1 B0, 1 M regoing & true and correct State office (use)	Casing Re Altering C Other	pair asing Workover Int dates, including estimated da ertinentto this work.)* 930' (old) 11.	Water SI Converse Note: Report r Completion or ate of starting any propu- ate of starting any propu- a	Aut-Off ion to Injection Water esults of multiple completion on Well <u>Recompletion Report and Log form.</u>) osed work. If well is directionally PTED FOR RECOR MAR 8 LES BABYAK ETROL LUM ENGINEER

BECEINED

2002 MAR - 4 PM IS: 40

BOBERT CELICE BOBERG CHIEMO MONT

: · · · · · · · ·