Hondo Drilling Company Fed. Alscott Com. Well No. 4 Page 3

T18S-R29E.

- 7. METHODS OF HANDLING WASTE DISPOSAL.
 - A. Drill cuttings will be disposed of in the reserve pits.
 - B. Drilling fluids will be allowed to evaporate in the reserve pits until the pits are dry.
 - C. Water produced during operations will be collected in tanks until hauled to an approved disposal system, or separate disposal application will be submitted to the U.S.G.S. for appropriate approval.
 - D. Oil produced during operations will be stored in tanks until sold.
 - E. Current laws and regulations pertaining to the disposal of human waste will be complied with.
 - F. Trash, waste paper, garbage and junk will be buried in a separate trash pit and covered with a minimum of 24 inches of dirt. All waste material will be contained to prevent scattering by the wind.
 - G. All trash and debris will be buried or removed from the wellsite within 30 days after finishing drilling and/or completion operations.
- 8. ANCILLARY FACILITIES.
 - A. None required.
- 9. WELLSITE LAYOUT.
 - A. Exhibit D shows the relative location and dimensions of the well pad, reserve pits, and major rig components.
 - B. A moderate amount of levelling will be necessary to construct the location. The ground surface at the wellsite rises gradually to the north, with minor undulations of approximately two feet or less. The north west corner of the drilling pad area will require a small amount of cut, and a small amount of fill will be necessary at the southwest corner. The pad surface will be covered with six inches of compacted caliche.
 - C. The reserve pits will be plastic lined.
 - D. The pad and pit area has been staked and flagged.
- 10. PLANS FOR RESTORATION OF THE SURFACE.
 - A. After finishing drilling and/or completion operations, all equipment and other materials not needed for further operations will be removed. Pits will be filled and the location cleaned of all trash and junk to leave the wellsite in as aesthetically pleasing a con-