

NEW MEXICO OIL CONSERVATION COMPUSITOR DRAWER DD ARTESIA, NEW MEXICO

Г		FIELD REPORT	FOR CEN	IENTING OF	WELLS							
0	Operator fetre	Corp.	Lease	en my	<u></u>	Well #	1					
	Location of Well	UnitZ Section		Township	Range 26	County Elley						
Drilling Contractor Cartur Prily 6,				Township Range County 26 Eddy approved 2-6-80 Type of Equipment Fotary to start tot soor-								
	* Witness											
	Size of Hole	Size of Casing	Weigl For	1	ew or Used	Depth	Sacks Come					
/	91/2"	7"	20		an a	1120	550 cin					
	6 14	7" 412"	9.5		· ·	3200	550 cinc.					
	¥											
-	Casing Data:		-l			L	<u></u>					
	Inspected by											
-1		Type of Shoe used <u>Guide</u> Float collar used <u>Insert</u> Btm 3 jts welded <u>yes</u>										
- 1				The states in the second se		TD of hole <u>//68</u> Set <u>//70</u> Fact of 7 Inch 20 [#] Grade <u>K-55</u> New-used csg. @ <u>//70</u> with <u>150</u> sacks near coment around shoe						
	TD of hole //	168 Set 11.70 Fe										
	TD of hole <u>//</u> New-used csg.	08 Set 11.70 Fe 0 11.70 with	150 s	acks neat	coment ar							
A REAL PARTY AND A REAL PROPERTY OF A REAL PROPERTY AND A REAL PROPERTY	TD of hole <u>//</u> New-used csg. + <u>400</u> sax Plug down @	Get J170 Ea @ //70 with	<u>150</u> s _additi) Date	acks neat ves <u>2-16-</u> 2	coment ar	ound she)e					
	TD of hole <u>//</u> New-used csg. + <u>400</u> sax Plug down @ Cement circul	(68 Set 11.70 Fe @ 11.70 with ± 65-35 Pos Mix ± 4:00 (A=) ated ↓ 5	<u>150</u> s _additi) Date	acks neat ves <u>2-16-1</u> No. of	comont ar <mark>81</mark> Sacks 33	ound sho)e					
	TD of hole <u>//</u> New-used csg. + <u>400</u> sax Plug down @ Cement circul Cemented by	(68 Set 11.70 Fa @ 11.70 with	<u>150</u> s _additi 1) Date	acks neat ves <u>2-/6-</u> No. of Witness	cement ar 81 Sacks 34 ed by <u>B1</u>	ound she 5 SX N Weave)e :y					
	TD of hole <u>//</u> New-used csg. + <u>400</u> sax Plug down @ Cement circul Cemented by Temp. Survey	(68 Set 1.70 Fe @ /170 with 65-35 Pos Mix 4:00 (AM) (<u>150</u> s _additi) Date PM) Da	acks neat ves No. of Vitness te	coment ar 81 Sacks 3 ed by <u>B1</u> top ce	ound she 5 <u>SX</u> VWeave ment@_)e 'Y					
	TD of hole <u>J</u> New-used csg. + <u>400</u> sax Plug down @ Cement circul Cemented by Temp. Survey Casing test @	168 Set 11.70 Ea @ 11.70 with 2 65-35 Pos Mix 44:00 (Am) (PM) ated 9 9 Dow (AM) (AM)	<u>150</u> s _additi) Date PM) Da PM) Da	acks neat ves No. of Witness te te	comont an 81 Sacks 34 ed by <u>B1</u> top ce	ound she 5 <u>5 X</u> N Weave ment @)e :v					
	TD of hole <u>//</u> New-used csg. + <u>400</u> sax Plug down @ Cement circul Cemented by Temp. Survey Casing test @ Method Used	(68 Set 1.70 Fa @ /170 with 65-35 Pos Mix 4100 (Am) ated (Am) Dowe/I ran @ (AM)	<u>150</u> s _additi) Date PM) Da PM) Da	acks neat ves No. of Witness te Witness	coment an <u>81</u> Sacks <u>3</u> ed by <u>B1</u> top ce ed by	ound she 5 <u>SX</u> VWeave ment@_	e יע י					
	TD of hole <u>//</u> New-used csg. + <u>400</u> sax Plug down @ Cement circul Cemented by Temp. Survey Casing test @ Method Used Checked for s	(68 Set 1.70 Ea @ /170 with 65-35 Pos Mix 4400 (Am) ated (Am) Dowe/// (AM) ated (AM)	<u>150</u> s _additi Date PM) Da PM) Da PM) Da	acks neat ves No. of Witness te te Witness Date	cement ar <u>81</u> Sacks <u>3</u> ed by <u>B1</u> top ce ed by	ound she 5 <u>SX</u> <u>VWeave</u> ment@	>e ·/					
	TD of hole <u>J</u> New-used csg. + <u>400</u> sax Plug down @ Cement circul Cemented by Temp. Survey Casing test @ Method Used Checked for s Method used	168 Set 11.70 Ea @ 11.70 With	<u>150</u> s _additi) Date PM) Da PM) Da PM) Da	acks neat ves No. of Witness te Witness Date Witness	coment an 81 Sacks 34 ed by <u>R1</u> top ce ed by ed by	ound she 5 <u>5X</u> NWeave ment@)e :v					
	TD of hole <u>J</u> New-used csg. + <u>400</u> sax Plug down @ Cement circul Cemented by Temp. Survey Casing test @ Method Used Checked for s Method used	(68 Set 1.70 Ea @ /170 with 65-35 Pos Mix 4400 (Am) ated (Am) Dowe/// (AM) ated (AM)	<u>150</u> s _additi) Date PM) Da PM) Da PM) Da	acks neat ves No. of Witness te Witness Date Witness	coment an 81 Sacks 34 ed by <u>R1</u> top ce ed by ed by	ound she 5 <u>5X</u> NWeave ment@)e :v					
	TD of hole <u>J</u> New-used csg. + <u>400</u> sax Plug down @ Cement circul Cemented by Temp. Survey Casing test @ Method Used Checked for s Method used	168 Set 11.70 Ea @ 11.70 With	150 s additi) Date PM) Da PM) Da PM) Da M) (PM) Syeak (acks neat ves No. of Witness te Witness Date Witness ///65	coment an <u>RI</u> Sacks <u>3</u> ed by <u>RI</u> top ce ed by ed by	ound she 5 <u>SX</u> <u>NWeave</u> ment@)e :v					