			ver DD	
Form 3160-5 June 1990)	UNITED STA DEPARTMENT OF TI BUREAU OF LAND M	HE INTERIOR	Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. LC 067136	
SUNDRY NOTICES AND REPORTS ON WELLS 2 1904 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals SUBMIT IN TRIPLICATE			6. If Indian, Allottee or Tribe Name	
			7. If Unit or CA, Agreement Designation	
1. Type of Well X Oil Gas Well Vell S	X Other RECOMPLETION	1	8. Weil Name and No.	
2. Name of Operator	UM CORPORATION	(505) 748-1471)	Scout EH Federal #5	
3. Address and Telephone No.	St., Artesia, NM 882		30-015-23726 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FNL, 1980' FWL (Unit F), Section 34-T18S-R25E			11. County or Parish, State	
			Eddy County, NM	
12. CHECK AP	PROPRIATE BOX(s) TO IN	DICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA	
TYPE OF SU	TYPE OF SUBMISSION TYPE OF ACTIO		٧	
Notice of In	itent	Abandonment	Change of Plans	
X Subsequent 1	Report	Plugging Back	Non-Routine Fracturing	
		Casing Repair	Water Shut-Off	
Final Aband			Conversion to Injection Dispose Water One (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ing any proposed work. If well is directionally drilled.	
<ul> <li>13. Describe Proposed or Complegive subsurface location</li> <li>12-6-93. RUI</li> <li>ND wellhead a</li> <li>CIBP at 8800</li> <li>with 2-7/8" tubing</li> </ul>	<ul> <li>leted Operations (Clearly state all pertinent d ns and measured and true vertical depths for</li> <li>PU. Loaded tubing with and installed BOP. Unit and dumped 35' cement tubing open-ended to be g. TIH with 4" casing N. TOH with casing graphics</li> </ul>	X Other Plugback, perforate	Dispose Water One (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ing any proposed work. If well is directionally drilled, 1000 psi for 11 minutes. tubing and packer. Set reline and rigged down. That acid at 5690'. TOH with rom 5665-5678' w/5250" K and tested 2-7/8" tubing	
<ul> <li>13. Describe Proposed or Complegive subsurface location</li> <li>12-6-93. RUI</li> <li>ND wellhead a</li> <li>CIBP at 8800</li> <li>with 2-7/8" tubing</li> <li>holes (4 SPF)</li> <li>to 5000 psi.</li> </ul>	<ul> <li>leted Operations (Clearly state all pertinent d ns and measured and true vertical depths for</li> <li>PU. Loaded tubing with and installed BOP. Unit and dumped 35' cement tubing open-ended to be g. TIH with 4" casing N. TOH with casing graphics</li> </ul>	X Other Plugback, perforate and treat Wolfcamp z etails, and give pertinent dates, including estimated date of start r all markers and zones pertinent to this work.)* th 2% KCL water, and tested to nset packer and TOH with 2-7/8" at on top of CIBP. TOH with wi 5690'. Spot 500 gals 15% NEFE g gun and perforated Wolfcamp fun. TIH with Uni VI packer, 6	Dispose Water One (Note: Report results of multiple completion on Well <u>Completion or Recompletion Report and Log form.</u> ) ing any proposed work. If well is directionally drilled, 1000 psi for 11 minutes. tubing and packer. Set reline and rigged down. Thacid at 5690'. TOH with from 5665-5678' w/5250" K and tested 2-7/8" tubing to clean up.	
<ul> <li>13. Describe Proposed or Complegive subsurface location</li> <li>12-6-93. RUI</li> <li>ND wellhead a</li> <li>CIBP at 8800</li> <li>with 2-7/8" tubing</li> <li>holes (4 SPF)</li> <li>to 5000 psi.</li> </ul>	<pre>leted Operations (Clearly state all pertinent d ns and measured and true vertical depths fo PU. Loaded tubing with and installed BOP. Un ' and dumped 35' cemen tubing open-ended to ' g. TIH with 4" casing g. TOH with casing gu Removed BOP and nip ed 12-9-93.</pre>	A Other Plugback, perforate and treat Wolfcamp z etails, and give pertinent dates, including estimated date of start r all markers and zones pertinent to this work.)* th 2% KCL water, and tested to nset packer and TOH with 2-7/8" at on top of CIBP. TOH with wi 5690'. Spot 500 gals 15% NEFE g gun and perforated Wolfcamp f un. TIH with Uni VI packer, 6 opled up wellhead. Flowed well	Dispose Water One (Note: Report results of multiple completion on Well <u>Completion or Recompletion Report and Log form.</u> ) ing any proposed work. If well is directionally drilled, 1000 psi for 11 minutes. tubing and packer. Set reline and rigged down. The acid at 5690'. TOH with from 5665-5678' w/5250" K and tested 2-7/8" tubing to clean up.	
<ul> <li>13. Describe Proposed or Complegive subsurface location</li> <li>12-6-93. RUI</li> <li>ND wellhead a</li> <li>CIBP at 8800</li> <li>with 2-7/8" tubing</li> <li>holes (4 SPF)</li> <li>to 5000 psi.</li> <li>Work complete</li> </ul>	eted Operations (Clearly state all pertinent d ns and measured and true vertical depths for PU. Loaded tubing with and installed BOP. Un ' and dumped 35' cemen tubing open-ended to ' g. TIH with 4" casing 0. TOH with casing gu Removed BOP and nip ed 12-9-93.	X Other       Plugback, perforate and treat Wolfcamp z         etails, and give pertinent dates, including estimated date of start r all markers and zones pertinent to this work.)*         th 2% KCL water, and tested to neset packer and TOH with 2-7/8" at on top of CIBP. TOH with with 5690'. Spot 500 gals 15% NEFE g gun and perforated Wolfcamp f in. TIH with Uni VI packer, 6 ppled up wellhead. Flowed well	Dispose Water One (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) ing any proposed work. If well is directionally drilled, 1000 psi for 11 minutes. tubing and packer. Set reline and rigged down. That acid at 5690'. TOH with rom 5665-5678' w/5250" K and tested 2-7/8" tubing to clean up.	