				λC
m 3160-5	UNITED STATE	s		FORM APPROVED OMB No. 1004-0135
ovember 1994) D	EPARTMENT OF THE BUREAU OF LAND MAN	AGEMENT	I CONS. DIVIS	
		NII SI	NM 88210-28	NMNM 01159 Hindian, Allouce or Tribe Name
Do not use thi abandoned we	s form for proposals to II. :Use Form 3160-3 (AP	drill of to Approxim D) for such proposals	•	
	PUCATE OVIET INSU	uctions on reverse.	diment Heridalistic 7	If Unit or CA/Agreement, Name and/or No.
Type of Well	Other	2 ²² 24		Well Name and No.
1/)il & Gas Company	E O P		Velson Federal No. 7
Audress 0. Box 2267, Mid		30 Phone No. 14-1404 925/686920	ărea gode) 10 60 1	30-015-23845 0. Field and Pool, or Exploratory Area
Location of Well (Footage, Sec.		<u>~</u>		LOCO Hills (Qn./Grbg./S.And.
990' FNL & 330'		12 13 16 16 16 16 16 16 16 16	7 53 ⁴	Eddy County, New Mexico
Sec.3-T18S-R30E	l	15131	LLOP	
12. CHECK AP	PROPRIATE BOX(ES)			PORT, OR OTHER DATA
TYPE OF SUBMISSION	1	<u> </u>	PE OF ACTION	Water Shut-Off
Notice of Inteni	Acidize	Deepen	Production (Start/F Reclaration	Well integrity
Subsequent Report	Alter Casing	New Construction	Recomplete	Other
Final Abandonment Notice	Change Plans	Plug and Abandon Plug Back	Temporarily Abar Water Disposal	
determined that the site is ready	inal Abandonment Notices sha for final inspection.)	ll be filed only after all requ	pletion or recompletion in irements, including reclar	vertical deputs of an shall be filed within 30 day a subsequent reports shall be filed within 30 day a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator ha
 L.)Set CIBP @ 35 2.)Cut-off 4-1/2 3.)Set 100' ceme Tag cement p 4.)Set 100' ceme 	for final handonment Notices sha for final inspection.) 500' + 35' of cem 2" casing at appr ent plug from 150 lug. ent plug from 466	ent on top. oximately 1550' 0' to 1600'. 50 i to 566'. 50	and pull out 50' in and 50' ' in and 50' o	DEDOIL, HEVE DEEL COMPLETE, and an openant
<pre>testing has been completed. P determined that the slic is ready 1.)Set CIBP @ 35 2.)Cut-off 4-1/2 3.)Set 100' ceme Tag cement p 4.)Set 100' ceme 5.)Set 50'cemen 6.)Install dry 1</pre>	for final handonment Notices sha for final inspection.) 500' + 35' of cem 2" casing at appr ent plug from 150 lug. ent plug from 466 t plug from surfa hole marker. Cle	ent on top. oximately 1550' 0' to 1600'. 50 i to 566'. 50	increants, including rectar 50' in and 50' ' in and 50' o location.	of hole. out of 4-1/2" casing stub. ut of 8-5/8" casing shoe.
1.)Set CIBP @ 35 2.)Cut-off 4-1/2 3.)Set 100' ceme Tag cement p 4.)Set 100' ceme	for final handonment Notices sha for final inspection.) 500' + 35' of cem 2" casing at appr ent plug from 150 lug. ent plug from 466 t plug from surfa hole marker. Cle	ent on top. oximately 1550' 0' to 1600'. 50 i to 566'. 50	increases, including rectar 50' in and 50' ' in and 50' o location.	of hole. out of 4-1/2" casing stub.
<pre>testing has been completed. F determined that the site is ready 1.)Set CIBP @ 35 2.)Cut-off 4-1/2 3.)Set 100' ceme Tag cement p 4.)Set 100' ceme 5.)Set 50'cemen 6.)Install dry b See attached we 14. Thereby certify that the foregometer of the set of</pre>	<pre>boold Operation in Notices sha for final inspection.) 500' + 35' of cem 2" casing at appr ent plug from 150 lug. ent plug from 460 t plug from surfa hole marker. Cle 11 diagram.</pre>	ent on top. oximately 1550' 00' to 1600'. 50 ice to 566'. 50 ice to 50'. ean and restore	increases, including rectar 50' in and 50' in and 50' o location. SEC CONDI	of hole. out of 4-1/2" casing stub. ut of 8-5/8" casing shoe. E ATTACHED FOR TIONS OF APPROVAL
 1.)Set CIBP @ 35 2.)Cut-off 4-1/2 3.)Set 100' ceme Tag cement p 4.)Set 100' ceme 5.)Set 50'cemen 6.)Install dry b See attached we 	<pre>boold Operation Notices sha for final inspection.) 500' + 35' of cem 2" casing at appr ent plug from 150 lug. ent plug from 460 t plug from surfa hole marker. Cle 11 diagram.</pre>	in the filed only after all requirement on top. Toximately 1550 00' to 1600'. 50 10' to 566'. 50 10ce to 50'. 10ce to 50'.	increases, including rectar 50' in and 50' ' in and 50' o location.	of hole. out of 4-1/2" casing stub. ut of 8-5/8" casing shoe. E ATTACHED FOR TIONS OF APPROVAL
 1.)Set CIBP @ 35 2.)Cut-off 4-1/2 3.)Set 100' ceme Tag cement p 4.)Set 100' ceme 5.)Set 50' cemen 6.)Install dry b See attached we 	<pre>boold Operation in Notices sha for final inspection.) 500' + 35' of cem 2" casing at appr ent plug from 150 lug. ent plug from 460 t plug from surfa hole marker. Cle 11 diagram.</pre>	ent on top. oximately 1550' 00' to 1600'. 50 ice to 566'. 50 ice to 50'. ean and restore	increases, including rectar 50' in and 50' in and 50' o location. SEC CONDI	of hole. out of 4-1/2" casing stub. ut of 8-5/8" casing shoe. E ATTACHED FOR TIONS OF APPROVAL
<pre>testing has been completed. F determined that the site is ready 1.)Set CIBP @ 35 2.)Cut-off 4-1/2 3.)Set 100' ceme Tag cement p 4.)Set 100' ceme 5.)Set 50'cemen 6.)Install dry b See attached we 14. Thereby certify that the foregon Name (Printed/Typed) M.</pre>	bind Abadonment Notices sha for final inspection.) 500' + 35' of cem 2" casing at appr ent plug from 150 lug. ent plug from 466 t plug from surfa hole marker. Cle 11 diagram.	in the filed only after all requirement on top. Toximately 1550 00' to 1600'. 50 10' to 566'. 50 10ce to 50'. 10ce to 50'.	increases, including rectar 50' in and 50' in and 50' o location. CONDI Engineer Tech.	of hole. out of 4-1/2" casing stub. ut of 8-5/8" casing shoe. E ATTACHED FOR TIONS OF APPROVAL
<pre>testing has been completed. r determined that the site is ready 1.)Set CIBP @ 35 2.)Cut-off 4-1/2 3.)Set 100' ceme Tag cement p 4.)Set 100' ceme 5.)Set 50'cemen 6.)Install dry I See attached we 14. Ihereby certify that the foregon Name (Prinsed/Typed) M. Signature M. Signature M. Signature M. M. Signature M. Signature M. M. M. Signature M. Signature</pre>	bind Abadonment Notices sha for final inspection.) 500' + 35' of cem 2" casing at appr ent plug from 150 lug. ent plug from 466 t plug from surfa hole marker. Cle 11 diagram. bing is true and correct Lee Roark	in the filed only after all requirement on top. Toximately 1550' 10' to 1600'. 50' 10' to 566'. 50' 10' to 50'. 50'. 50'. 50' 10' to 50'. 50'. 50'. 50'. 50'. 50'. 50'. 50'.	increases, including rectar 50' in and 50' in and 50' o location. COND Engineer Tech. 12/21/99	of hole. out of 4-1/2" casing stub. ut of 8-5/8" casing shoe. E ATTACHED FOR HONG OF APPROVAL
testing has been completed. determined that the site is ready 1.)Set CIBP @ 35 2.)Cut-off 4-1/2 3.)Set 100' ceme Tag cement p 4.)Set 100' ceme 5.)Set 50' cemen 6.)Install dry b See attached we 14. Thereby certify that the foregone Name (Prinzed/Typed) M. Signature M. Signature M. Conditions of approval, if any, and certify that the applicant holds be	bind Abadonment Notices sha for final inspection.) 500' + 35' of cem 2" casing at appr ent plug from 150 lug. ent plug from surfa hole marker. Cle 11 diagram. 500' is true and correct Lee Roark 11 diagram. 11 diagram. 11 diagram. 12 diagram. 13 diagram. 14 diagram. 14 diagram. 15 diagram. 16 diagram. 17 diagram. 18 diagram. 19 diagram. 19 diagram. 19 diagram. 10 diagram. 10 diagram. 10 diagram.	I be filed only after all requirement on top. toximately 1550' 10' to 1600'. 50' 10' to 566'. 50'	increases, including rectar of in and 50' of location. SECONDI Engineer Tech. 12/21/99 STATE OFFICE USE Title FETROLEUM Office	of hole. out of 4-1/2" casing stub. ut of 8-5/8" casing shoe. E ATTACHED FOR TIONS OF APPROVAL
<pre>testing has been completed. F determined that the site is ready 1.)Set CIBP @ 35 2.)Cut-off 4-1/2 3.)Set 100' ceme Tag cement p 4.)Set 100' ceme 5.)Set 50'cemen 6.)Install dry f See attached we Name (Prinzed/Typed) M. Signature M. Signature M. Conditions of approval, if any, m Conditions of approval, if any, m</pre>	bind Abadonment Notices sha for final inspection.) 500' + 35' of cem 2" casing at appr ent plug from 150 lug. ent plug from surfa hole marker. Cle 11 diagram. 500' is true and correct Lee Roark 11 diagram. 11 diagram. 11 diagram. 12 diagram. 13 diagram. 14 diagram. 14 diagram. 15 diagram. 16 diagram. 17 diagram. 18 diagram. 19 diagram. 19 diagram. 19 diagram. 10 diagram. 10 diagram. 10 diagram.	I be filed only after all requirement on top. toximately 1550' 10' to 1600'. 50' 10' to 566'. 50'	increases, including rectar of in and 50' of location. SECONDI Engineer Tech. 12/21/99 STATE OFFICE USE Title FETROLEUM Office	of hole. out of 4-1/2" casing stub. ut of 8-5/8" casing shoe. E ATTACHED FOR HONG OF APPROVAL

~

ROSASSINGERS HUUDEC SS V & 2P UECEIAED

•