	A HER PERIOD			•		
.GY AND	MINERALS DEPARTMENT		merican care to some fire and some	· · · · · · · · · · · · · · · · · · ·		Form C-103
J. OF COP	IES RECEIVED	OIL CONSERVATIO	M DIVISION LED L.	•		Revised 10-1-78
DISTRI	BUTION	P.O. Box	2088	I		
SANTA FE	ivi		EXICON 13 1994		5a. Indicate	Type of Lease
FILE	141	-	1404 TO 180.		State	Fee X
U.S.G.S			O. C. D.			h
LAND OFFIC			ARTESIA OFFICE		5. State 011 6	Gas Lease No.
OPERATOR	141				2, 5 2, 5	-
	SUMPRY NOTICE	S AND REPORTS ON WELLS			~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	***************************************
(DO NOT US	THIS FORM FOR PROPOSAL		OP DING DACY TO A D	A FEEDENT	xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx	
				1	i	
1, 01L	SERVOIR. USE MAPPLICATI	ON FOR PERMITS" (FORM C	-1011 FOR SUCH PROPO	SALS.)	7. Unit Agreement Name	
WELL T		OTHER Service	_1_	!	/. Unit Agreer	ment Name
	WELL	OTHER Dry h	018			-
2. Name of Operator					8. Farm or Lease Name	
Read & Stevens, Inc. 🗸					Fair	
3. Address of Operator					9. Well No.	
P.O. Box	1518, Roswell, NM 8820	1				1
4. Location of Well					10. Field and	Pool, or Wildcat
INIT LETTED E 1000 FEET FROM THE MONTH AND 1000 FEET FROM				26. 1. 2 1		
UNIT LETTER F . 1980 FEET FROM THE West LINE AND 1980 FEET FROM				Wildcat		
THE Nort	LINE. SECTION 30	TOWNSHIP 18S	RANGE 27E	NMPM		**************
XXXXXXXXXX	xxxxxxxxxxxxxxxxxxxxxxxxxxxxx	Elevation(Show whether	DF,RT,GR,etc.)		12. County	XXXXXXXXXXXXXX
XXXXXXXXXX	KXXXXXXXXXXXXXXXXXX	3279.31 GR			Eddy	XXXXXXXXXXXXXX
	Check Appropr	iate Box To Indicate Na	ture of Notice, Repo	rt or Oth	er Data	
	NOTICE OF INTENTION	TO:	SUBS	EQUENT RE	PORT OF:	
	<u></u>					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK					ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.					PLUG AND ABANDONMENT X	
PULL OR A	LTER CASING		CASING TEST AND CE	MENT JOB		
OTHER			OTHER			
Describe Pro	posed or Completed Oper					
	poole of completely open	ations(Clearly state al	l nertinent details.	and alve	nertinent date	e including seti-
	f starting any proposed		I pertinent details,	and give	pertinent date	es, including esti-
	f starting any proposed		I pertinent details,	and qive	pertinent date	es, including esti-
11-8-84		work) SEE RULE 1103.	I pertinent details,	and qive	pertinent date	es, including esti-
11-8-84	f starting any proposed RU unit, pulled rods	work) SEE RULE 1103.	I pertinent details,	and qive	pertinent date	es, including esti-
	RU unit, pulled rods	work) SEE RULE 1103.				
11-8-84	RU unit, pulled r∞ds	work) SEE RULE 1103. , SDON. mp, hauled to yard, tri				
	RU unit, pulled rods	work) SEE RULE 1103. , SDON. mp, hauled to yard, tri				
11-9-84	RU unit, pulled rods Trip out w/rods & pur pluq, circ hole w/15	work) SEE RULE 1103. , SDON. mp, hauled to yard, tri sx FW mud, SDON.	p out w/tbq, set CIB	P @ 3100';	, dump 35' cmt	on top of
	RU unit, pulled rods Trip out w/rods & pur pluq, circ hole w/15: Welded onto 5 1/2" c	work) SEE RULE 1103. , SDON. mp, hauled to yard, tri sx FW mud, SDON. sq, pulled slips, pulle	p out w/tbg, set CIB d stretch, stuck @ 1	P @ 3100', 550', cut	, dump 35' cm† ∉ 1850', pulle	on top of ed 44jts,
11-9-84	RU unit, pulled rods Trip out w/rods & pur pluq, circ hole w/15: Welded onto 5 1/2" c: 5 1/2"-17#, J-55, tr	work) SEE RULE 1103. , SDON. mp, hauled to yard, tri sx FW mud, SDON.	p out w/tbg, set CIB d stretch, stuck @ 1	P @ 3100', 550', cut	, dump 35' cm† ∉ 1850', pulle	on top of ed 44jts,
11-9-84	RU unit, pulled rods Trip out w/rods & pur pluq, circ hole w/15: Welded onto 5 1/2" c	work) SEE RULE 1103. , SDON. mp, hauled to yard, tri sx FW mud, SDON. sq, pulled slips, pulle	p out w/tbg, set CIB d stretch, stuck @ 1	P @ 3100', 550', cut	, dump 35' cm† ∉ 1850', pulle	on top of ed 44jts,
11-9-84 11-10-84	RU unit, pulled rods Trip out w/rods & pur pluq, circ hole w/15: Welded onto 5 1/2" c: 5 1/2"-17#, J-55, tr SOON.	work) SEE RULE 1103. , SDON. mp, hauled to yard, tri sx FW mud, SDON. sq, pulled slips, pulle lp in w/2 3/8" tbq, spo	p out w/tbq, set CIB d stretch, stuck @ 1 tted 65sx cmt, 1890'	P @ 3100'; 550', cut -1648', pi	, dump 35' cmt € 1850', pulle ulled out of ho	on top of ed 44jts, ole, WOC,
11-9-84	RU unit, pulled rods Trip out w/rods & pur plua, circ hole w/15: Welded onto 5 1/2" c: 5 1/2"-17#, J-55, tr SOON. Trip in w/ 2 3/8" tbs	work) SEE RULE 1103. , SDON. mp, hauled to yard, tri sx FW mud, SDON. sq, pulled slips, pulle lp in w/2 3/8" tbq, spo	p out w/tbg, set CIB d stretch, stuck @ 1 tted 65sx cmt, 1890'	P @ 3100'; 550', cut -1648', pi	, dump 35' cmt € 1850', pulle ulled out of ho	on top of ed 44jts, ole, WOC,
11-9-84 11-10-84	RU unit, pulled rods Trip out w/rods & pur plua, circ hole w/15: Welded onto 5 1/2" c: 5 1/2"-17#, J-55, tr SOON. Trip in w/ 2 3/8" tbs	work) SEE RULE 1103. , SDON. mp, hauled to yard, tri sx FW mud, SDON. sq, pulled slips, pulle lp in w/2 3/8" tbq, spo	p out w/tbg, set CIB d stretch, stuck @ 1 tted 65sx cmt, 1890'	P @ 3100'; 550', cut -1648', pi	, dump 35' cmt € 1850', pulle ulled out of ho	on top of ed 44jts, ole, WOC,
11-9-84 11-10-84 11-11-84	RU unit, pulled rods Trip out w/rods & pur pluq, circ hole w/15: Welded onto 5 1/2" cs 5 1/2"-17#, J-55, tr SOON. Trip in w/ 2 3/8" tbs pull tbq, spot 15sx s	work) SEE RULE 1103. , SDON. mp, hauled to yard, tri sx FW mud, SDON. sq, pulled slips, pulle ip in w/2 3/8" tbq, spo a, tag plug # 1620', pu surface plug w/dry hole	p out w/tbg, set CIB d stretch, stuck @ 1 tted 65sx cmt, 1890'	P @ 3100'; 550', cut -1648', pi	, dump 35' cmt € 1850', pulle ulled out of ho	on top of ed 44jts, ole, WOC,
11-9-84 11-10-84	RU unit, pulled rods Trip out w/rods & pur plua, circ hole w/15: Welded onto 5 1/2" c: 5 1/2"-17#, J-55, tr SOON. Trip in w/ 2 3/8" tbs	work) SEE RULE 1103. , SDON. mp, hauled to yard, tri sx FW mud, SDON. sq, pulled slips, pulle ip in w/2 3/8" tbq, spo a, tag plug # 1620', pu surface plug w/dry hole	p out w/tbg, set CIB d stretch, stuck @ 1 tted 65sx cmt, 1890'	P @ 3100'; 550', cut -1648', pi	, dump 35' cmt € 1850', pulle ulled out of ho	on top of ed 44jts, ole, WOC,
11-9-84 11-10-84 11-11-84	RU unit, pulled rods Trip out w/rods & pur pluq, circ hole w/15: Welded onto 5 1/2" cs 5 1/2"-17#, J-55, tr SOON. Trip in w/ 2 3/8" tbs pull tbq, spot 15sx s	work) SEE RULE 1103. , SDON. mp, hauled to yard, tri sx FW mud, SDON. sq, pulled slips, pulle ip in w/2 3/8" tbq, spo a, tag plug # 1620', pu surface plug w/dry hole	p out w/tbg, set CIB d stretch, stuck @ 1 tted 65sx cmt, 1890'	P @ 3100'; 550', cut -1648', pi	, dump 35' cmt € 1850', pulle ulled out of ho	on top of ed 44jts, ole, WOC,
11-9-84 11-10-84 11-11-84	RU unit, pulled rods Trip out w/rods & pur pluq, circ hole w/15: Welded onto 5 1/2" cs 5 1/2"-17#, J-55, tr SOON. Trip in w/ 2 3/8" tbs pull tbq, spot 15sx s	work) SEE RULE 1103. , SDON. mp, hauled to yard, tri sx FW mud, SDON. sq, pulled slips, pulle ip in w/2 3/8" tbq, spo a, tag plug # 1620', pu surface plug w/dry hole	p out w/tbg, set CIB d stretch, stuck @ 1 tted 65sx cmt, 1890'	P @ 3100'; 550', cut -1648', pi	, dump 35' cmt € 1850', pulle ulled out of ho	on top of ed 44jts, ole, WOC,
11-9-84 11-10-84 11-11-84	RU unit, pulled rods Trip out w/rods & pur pluq, circ hole w/15: Welded onto 5 1/2" cs 5 1/2"-17#, J-55, tr SOON. Trip in w/ 2 3/8" tbs pull tbq, spot 15sx s	work) SEE RULE 1103. , SDON. mp, hauled to yard, tri sx FW mud, SDON. sq, pulled slips, pulle lp in w/2 3/8" tbq, spo a, tag plug @ 1620', pu surface plug w/dry hole rep for inspection.	p out w/tbg, set CIB d stretch, stuck @ 1 tted 65sx cmt, 1890'	P @ 3100'; 550', cut -1648', pi	, dump 35' cmt @ 1850', pulle ulled out of ho	on top of ed 44jts, ole, WOC,
11-9-84 11-10-84 11-11-84 11-12-84 SIGNED	RU unit, pulled rods Trip out w/rods & pur pluq, circ hole w/15: Welded onto 5 1/2" cs 5 1/2"-17#, J-55, tr SOON. Trip in w/ 2 3/8" tbs pull tbq, spot 15sx s Cleaning location, pr	work) SEE RULE 1103. , SDON. mp, hauled to yard, tri sx FW mud, SDON. sq, pulled slips, pulle lp in w/2 3/8" tbq, spo a, tag plug @ 1620', pu surface plug w/dry hole rep for inspection. TITLE	p out w/tbq, set CIB d stretch, stuck @ 1 tted 65sx cmt, 1890'	P @ 3100'; 550', cut -1648', pi	, dump 35' cmt @ 1850', pulle ulled out of ho	on top of ed 44jts, ole, WOC,
11-9-84 11-10-84 11-11-84 11-12-84 SIGNED	RU unit, pulled rods Trip out w/rods & pur pluq, circ hole w/15: Welded onto 5 1/2" cs 5 1/2"-17#, J-55, tr SOON. Trip in w/ 2 3/8" tbs pull tbq, spot 15sx s Cleaning location, pr	work) SEE RULE 1103. , SDON. mp, hauled to yard, tri sx FW mud, SDON. sq, pulled slips, pulle lp in w/2 3/8" tbq, spo a, tag plug @ 1620', pu surface plug w/dry hole rep for inspection.	p out w/tbq, set CIB d stretch, stuck @ 1 tted 65sx cmt, 1890'	P @ 3100'; 550', cut -1648', pi	, dump 35' cmt @ 1850', pulle ulled out of ho	on top of ed 44jts, ole, WOC,

Post 10-24