STATE OF NEW MEXICO		•	~	. 30 - 0	15-24915	5
VERGY AND MINERALS DEPARTMENT	OIL CONSERVAT	ION DIVISION	N	Form C-101		
	P. O. BOX		VED BY	levised 10-	1-78	
DISTRIBUTION	SANTA FE, NEW MEXICO 87501			SA. Indicute Type of Lease		
SANTAFE V	—	1	9 100 4	BTATE Z	K 100	
FILE		JUL 0	J 1984	5. Etato Oli 6	Gue Lorine No.	.
U.S.G.S			C. D.			i.
LAND OFFICE		1		mm	///////////////////////////////////////	$\overline{\mathbf{x}}$
	DUUT TO DUUL DEEDEN		OFFICE	HHHH	MMMMM	N
APPLICATION FOR PL	ERMIT TO DRILL, DEEPEN	, OK PLUG DACK		7. Unit Acree	NATTA Fame	<u>.</u>
. TALE OF MOIN				•		
DRILL X	DEEPEN	PLU		8. Farm of Le	ote Note	
. Type of Well		SINGLE TT			JL 36	
	(CR	SINGLE X	ZONE	9. Well No.		· · ·
Nanie of Operator						i
Tenneco Oil Company 🖌				3		- ·
Address of Operator					Pool, or Wildzat Une	
7990 IH 10 West, San Ar				eo Queen	, So. (Graybu	rg)
Location of Weli UNIT LETTER J	LOCATED 1980/88	FLET FROM THE -Bas	+ South	HHH		
1990	'net			HHHH		N.
D 1880 FEET FROM THE	the une or sec. 36	TWP. 185 RGE.	29E NMPM	HHHH	MANNI	
			<u>UUUUU</u>	12, County		
i ////////////////////////////////////				Eddy		
****	tttittittittitti	TTTTTTTTTTTT	thini i	TITTI;	THUM ITT	
1111/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1			HHHHH	iIIIII.	HHHHHH	1. 1. 1. 1.
	ttttttttttttttttttt	19. Proposed Depth	19A. Fermation		20. Repary to C.N.	•`··
41111111111111111111111111111111111111		2900	Grayburg		Rotary	1
Elevations (show whether DF, KT, etc.)	21A. Kind & Status Plug. Bond	21B. Drilling Contracto	r		Date Work will start	,
3438' GL	Blanket			15	July 1984	

PROPOSED CASING AND CEMENT PROGRAM

SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SET ING DEPTH	SACKS OF CEMENT	EST, TOP
124	8 5/8	24 lbs.	3('	190	Surf.
7 7/8	51/2	14.5 lbs.	2900'	427	Surf.
		I 1	1	ŧ i	ł

- 1. Construct suitable location. Reserve pits, working pits, rat hole, mouse hole, cellar may be provided by operator or drilling contractor, and will be determined in conjunction with selection of drilling contractor/rig.
- 2. MIRU. Drill 12 1/4" hole to 300' +/-. BHA: Slick

- 3. CCM to run casing. SLM out of hole. Set 8 5/8" compression at 300 +/-. Run casing, cement and centralize. Set 8 5/8" casing in full
- 4. WOC 12 hours. Cut off 8 5/8" casing. Install (See Note #1) wellhead. test well to 680 psi (1/2 of csg. collapse strength for SOW heads).

test well to boo par (1/2 of cag. corrupad adrengen for				
Continued on back of page.	APPROVAL VALID FOR <u>180</u> DAYS PERMIT EXPIRES <u>1-3-85</u>			
Wolchum WOC time/8 hrs.	UNLESS DRILLING UNDERWAY			
A BOVE SPACE DESCRIRE PROPOSED PROGRAM: IF PROPOSAL IS TO DEEREN OR PLUE BACK, GIVE DATA ON PL E 20NE. GIVE BLOWDIT PROVENTER PROGRAM, IF ANY.	NESENT PRODUCTIV	E ZONE AND PROPOSED NEW PRODUC-		
treby certify they the information above is true and complete to the best of my knowledge and belief.				
ned the winner Tule Drilling Engineer	Dare	29 June 1984		
(This space for State U.e.) What when OIL AND GAS INSPECTOR		JUL 0 5 1984		
PROVED BY TALA MARAMA TITLE	DATE_			
NDITIONS OF APPROVAL, IF ANTI		Post a ky b k De- 10 h B k		

- 5. NU following BOPE: 3M Double Ram BOPE (pipe on BTM. Blinds on top) Test to 1500 PSIG when testing casing.
- 6. PU 7 7/8 bit and following BHA: Slick RIH to top of float collar. Test casing to 1000 psi for 30 minutes. Test is satisfactory if pressure does not decrease more than 10% of test pressure by end of test. Record test on IADC Report and include details in daily drilling report to TOC SWD. Insure compliance with State of NM Rule 107 before testing and drilling out.
- 7. Drill 7 7/8" hole to +/- 2900. Log, core, as outlined in step 8 and per GE.
- 8. Will shoot sidewall cores in the Penrose @ 2463'.
- 9. RIH w/DP and bit to TD. CCM to run 5 1/2" casing, or to P & A. If well is to be P & A'd, RIH open - ended and set cement plugs in accordance with regulatory agency instructions. Also, if P & A's, set EZSV-type cement retainer approximately 50' above last casing show and place 50 sacks of cement below and above retainer.
- 10. If not P & A'd, set 5 1/2" production casing at 2900'. Run casing, cement and centralize. Fill casing every 20 joints while running in hole. Set full casing weight on slips. Check float equipment operation.
- 11. C.O. casing. ND BOPE and install (See Note 2 below) tubing head. Test to 1500 psi. NU dry hole tree. Release rig.
- NOTES: 1. 8 5/8" x 11" 3M SOW csg. head w/2 2" LPO, 1-solid bull plug & 1-3M ball valve.

2. 11" x 7 1/16" 3M tbg. head w/2 - 2" LPO, 1-solid bull plug & 1-3M ball valve.

0903Z