## Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICTI

## State of New Mexico ergy, Minerals and Natural Resources Depar

## OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe. New Mexico 87504-2088

C 151	Revise	4 1.1-89
VELL API NO.	·	
30-015-252	38	
5. Indicate Type of	Lease	FEE _

P.O. Drawer D	DD, Artesia, NM 88210	Santa 1 c, 1 cw	111070-		5. Indicate Type of La	STATE X FEE	
DISTRICT III 1000 Rio Braz	os Rd., Azzec, NM 87410				6. State Oil & Gas Le		
	CUNDRY NO	TICES AND DEPORTS	ON W	FUS			
SUNDRY NOTICES AND REPORTS ON WELLS  ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name				
1. Type of We					771 (7)		
METT X	WELL	OTHER			El Cheapo		
2. Name of O	perator				& Well No.		
Salkar	Inc.				9. Pool name or Wildca	ı	
3. Address of		1 N M 98201			Artesia, Q,		
4. Well Location	ox 2488, Roswel	T N.11. 00201					
		Feet From The North	th	Line and1650	Feet From The		
Section	<b>.</b> 35	Township 18S	R	ange 27E	IMPM	Eddy County	
		10. Elevation (Show	whether	DF, RKB, RT, GR, etc.)			
					Oil Por	<u>/////////////////////////////////////</u>	
11.	Check A NOTICE OF INT	Appropriate Box to Inc	licate	Nature of Notice, Re	port, or Other Dai SEQUENT REPO	a DRT OF:	
PERFORM REM		PLUG AND ABANDON		REMEDIAL WORK	ALTE	RING CASING	
TEMPORARILY		CHANGE PLANS		COMMENCE DRILLING	OPNS. PLUG	AND ABANDONMENT $\stackrel{ ext{N}}{=}$	
PULL OR ALTER	CASING	•		CASING TEST AND CEM	ENT JOB	۲	
OTHER:				OTHER:			
12. Describe Propo work) SEE RU	osed or Completed Operation	ons (Clearly state all pertinent de	etails, an	d give pertinent dates, includin	g estimated date of startin	g any proposed	
6-11-98	MIRU-Unset Rod Pump-Pull out of hole w/77 5/8" rods & pump.  Nipple up B.O.P POOH w/62 joints 2 3/8" tubing. Ran tubing to 1800'.  Spotted 40 Sx Cl.C. cement plug at 1800'. W.O.C. Tag TOC at 1916'.  Set tubing at 1800'. Spotted 40 Sx cement plug. W.O.C. Shut down until A.M.						
6-12-98	R.I.H. with tubing & tagged TOC at 1520'. Spotted 25 Sx cement plug at 1520'. W.O.C. Tagged TOC at 1140'. Circulated 10# brine gel to 680+. Set tubing at 680'. Pumped 53 Sx Cl.C. Bring cement to surface. P.O.O.H. with tubing & topped hole to surface with 5 Sx cement. Erect dry hole marker. Clear location.						
	P & A complete	<b>.</b>					
		i complete to the best of my knowled	ge and be	iid.		June 30, 1998	
SIGNATURE TOOL	elshold 22		_ mle	Field Rep II	DATI	E Galle 30, 233	
	Mike Stubblefi				TELE	PHONE NO.	
(This space for State U							
				Fill D. A T		AL1 18-98	
APPROVED BY	ce Stubblefield		. TILE	Field Repo I	DATE		