iubmit copies 5 Appropriate Vistrict Office	State of New		c <sup>15</sup>			orm C-103 evised 1-1-89
<u>)IŞTRICT  </u> P.O. Box 1980, Hobbs NM 88240	Energy, Minerals and Natural			ELE APENO.		
DISTRICT II P.O. Drawer DD, Artesia NM 88210	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088			30-015-25665 <sup>5</sup> Indicate "ype of Lease State X FEE		
NSTRICT III 1000 Rio Brazos Rd., Aztec NM 87410						
SUNDRY NO (DO NOT USE THIS FOR DIFFERENT (FORM C-1	DTICES AND REPORTS ON WELLS M FOR PROPOSALS TO DRILL OR T RESERVOIR. USE "APPLICATION I 101) FOR SUCH PROPOSALS.)		 Z:	Lease Name or Unit	<u>UUIIII</u>	
I, Type of Well: DIL GAS WELL WELL	OTHER X SWD			Compr	omise SV	<u>VD</u>
2. Name of Operator Yate	s Petroleum Corporation		8.	Well No	#1	
	South 4th., Artesia. NM 882	10	G.	Pool Name or Wildca Wild	at cat Strawn	
4. Well Location Unit Letter $\underline{H}$ : 1980	Feet From The North	Line and 80	0 <sup>°</sup> Feet F	rom The	East	Line
Section 30 Townshi	p 185 Range 27E	NMPM	I	Eddy	(	COUNTY
10. E	levation (Show whether DF, R	RKB, RT, GR, etc.)				
NOTICE OF INTEN	TION TO: PLUG AND ABANDON	SUB REMEDIAL WORK COMMENCE DRILLING C CASING TEST AND CEM	DPNS.	PORT OF: ALTERING CASING PLUG AND ABANE		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING ( CASING TEST AND CEM OTHER	DPNS. IENT JOB	ALTERING CASING		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Comp date of starting any proposed 11/29/01-Rigged up pul good. Tested 8-5/8" cas 500 psi. 11/30/01 Braden headsq Left 700 psi on 8 -5/8" 12/31/01 Returned to in	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING O CASING TEST AND CEM OTHER Il pertient details, and give casing to 500 psi. 30 mins-tested goo annulus with 100 s oduction.	NENT JOB Workover We pertinenet dat held for 30 od. Tested 8	altering casing plug and abane c es, including e mins – teste ~5/8″ casir	Stimated	water.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Comp date of starting any proposed 11/29/01-Rigged up pul good. Tested 8-5/8" cas 500 psi. 11/30/01 Braden headsq Left 700 psi on 8 -5/8" 12/31/01 Returned to in 1/29/02-It was retested	PLUG AND ABANDON CHANGE PLANS Deted Operations (Clearly state al work) SEE RULE 1103. ling unit. Tested 5-1/2" sing to 500 psi. held for 3 queeze. on 8 5/8 x 5 1/2 casing. Turned well to pro- ijection. Final report.	REMEDIAL WORK COMMENCE DRILLING O CASING TEST AND CEM OTHER Il pertient details, and give casing to 500 psi. 30 mins-tested good annulus with 100 s oduction. awkins of the OCD.	DPNS. Workove Werkove We pertinenet dat held for 30 od. Tested 8 sx 'C: Neat.	altering casing plug and abang es, <i>including e</i> mins – teste -5/8" casir Flushed wit	Sonment X stimated ed ed ed ed ed ed ed ed ed ed ed ed e	ARTEST
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 12. Describe Proposed or Comp date of starting any proposed 11/29/01-Rigged up pul good. Tested 8-5/8" cas 500 psi. 11/30/01 Braden headsq Left 700 psi on 8 -5/8" 12/31/01 Returned to in 1/29/02-It was retested	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING O CASING TEST AND CEM OTHER Il pertient details, and give casing to 500 psi. 30 mins-tested good annulus with 100 s oduction. awkins of the OCD.	NENT JOB Workover We pertinenet dat held for 30 od. Tested 8	altering casing plug and abang es, <i>including e</i> mins – teste -5/8" casir Flushed wit	Sonment X stimated ed ed ed ed ed ed ed ed ed ed ed ed e	ARTEST 29/02







