Form 3160-5 lovember 1983) Formerly 9-331)	BURE	UNITED STATIMENT OF THI	E INTERI	1	Expires 5. LEASE DESIGN NM 68040	proved. Bureau No. 1004-0: August 31, 1985 ENATION AND SEAIAL B	10.	
SUI (Do not use thi	UDRY NO	TICES AND RECATION FOR PERMIT	PORTS (ON WELLS pack to a different reservoir. proposals.)	_			
OIL X WELL PANS OF OPERATOR Harvey E. Ya	OTHER			ECEWED	8. FARK OR LA Parker 5	SAGE HAME		
D A Roy 193	3 Roswell	New Mexico 88202		an 02 '89	9. WBLL 80. #1			
4. LOCATION OF WELL (See also space 17 be At surface 530' FWL & 3	Report location low.)	Unit Letter	ner with any	State requirements.* O. C. D. ARTESIA, OFFICE	North Shug	eart Bone Spring		
		15. ELEVATIONS (Sh	an whether DP	PT CR etc.)	Sec. 5, Tl	8S, R31E		
14. FERMIT NO. 30-015-25908	ı	3666.6			Eddy	NM	_	
16.	Check A	• • •	Indicate N	ature of Notice, Report, or	Other Data			
FRACTURE TREAT BHOUT OR ACIDIZE REPAIR WELL PULL OR ALTER CASINO MULTIPLE COMPLETE ABANDON* CHANGE PLANS			•	WATER BHOT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (NOTE: Report resu	X ABA	of multiple completion on Well		
proposed work. I nent to this work.)	t men in divect	ionally drined, give su	Deminace local	Completion or Recount details, and give pertinent date ions and measured and true vertices (24' - 49 holes). (Perfs	es, including estimatical depths for all	ated date of starting markers and sones p	aas irti-	
5-7-89: Pmp		50# gelled 20% NE		00 SCF Nitrogen per barr				
5-10-89 Aci NEF	d w/10 BW & E, 250# rocl	30 BS follow w/2 c salt, pump 700	000 gals l gals same	5% NEFE and 130 BS. Pump acid, pmp 750# rock salt	o 500 gals 30# : & 1800 gals s	gelled 15% ame.		
5-12-89: Set	anchor 7530)'. Run 2" X 1 1	/2" X 24'	pump and rods. Hang wel	ll on and turn	over to pumper.		
				WCCEPTES FO	NERT CONS		Tu .	
					J 1383		EOEIVE	
				CARESBAD, NE	3 Ewalen		VED	
						ر ال	_	

TITLE _

(This space for Federal or State office use)

Production Analyst

May 16, 1989