

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP DATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Harvey E. Yates Company

3. ADDRESS OF OPERATOR

P.O. Box 1933, Roswell, New Mexico 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)

At surface

635' FNL & 685' FEL

RECEIVED

OCT 14 '88

O. C. D.

ARTESIA, OFFICE

14. PERMIT NO.

30-015-25913

15. ELEVATIONS (Show whether DP, RT, OM, etc.)

3701.5 GL

5. LEASE DESIGNATION AND SERIAL NO.

NM 33837

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

4

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

FMS 8 Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

North Shugart *Boye Spring*

11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA

Sec. 8, T18S, R31E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRAC TURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRAC TURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Completion Sundry

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

8-13-88 MI RU completion equip, run production logs. PBID @ 8919. Perf. 8694-8712 (2 SPF). Acidize w/250 gal HCL. Swab test.

8-19-88 Set CIBP @ 8668 (new PBID) perf @ 7877-8308 (1 SPF). Breakdown perfs w/3500 gal Nars & ball sealers. Swab test..

8-25-88 Acid w/5000 gal HCL & ball sealers. Swab test.

8-28-88 Frac w/97,500 gal BS 40 & 195,000 lbs, 16/30 sand. Test for production.

9-28-88 Set CIBP @ 7850' & perf 2 SPF from 7700 - 7712', 25 holes. Acid w/3750 gals 20% HCL & swab to test. Put on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Manager/Engineer

DATE 9-30-88

RECEIVED

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

OCT 13 1988

\*See Instructions on Reverse Side

SJS  
CARLSBAD, NEW MEXICO