		n 0	
orm 3160-5	UNITED STAT		FORM APPROVED
(une 1990)	DEPARTMENT OF THE		Budget Bureau No. 1004–0135
	BUREAU OF LAND MAI	NAGEMENT	Expires: March 31, 1993
	SUNDRY NOTICES AND REP	ODTS ON WELLS	5. Lease Designation and Serial No.
		pen or reentry to a different rese	<u>NM-28095</u>
	"APPLICATION FOR PERMI		ervoir 6. If Indian, Allotte or Tribe Name
· · · ·	SUBMIT IN TRI		7. If Unit or CA, Agreement Designation
Fype of Well		n na star star star star star star star sta	
X Oil Well Ga	s Well Other		A
Name of Operator			8. Well Name and No.
Harvey E. Yates	Company		CAN-KEN 4 FED. # 2
-		and the second second	9. AP1 Well No.
Address and Telephone No.			
•	Roswell, NM 88202 1-505	5-623-6601	VI Shugart
т. О. DOX 1775 у	NUSWCH, 14141 00202 1-303		10 Viele and Poli, or the planatory Area
			<u>UND.</u> DELAWARE
• • •	T., R., M, or Survey Description)		11. County or Parish, State
1980' FN & EL			
G, SEC. 4, T-185	5, K-31E		EDDY
			REPORT, OR OTHER DATA
TYPE OF SUBMIS	SION	TYPE OF AC	CTION
Notice of Intent	Abandonment		Change in Plans
	X Recompletion		
X Subsequent Report	Plugging Back		New Construction
Subsequent Report			Non-Routine Fracturing
Final Abandoment	Casing Repair		Water Shut-Off
Final Abandoment	Altering Casing		Conversion to Injection
	Other	······································	Dispose Water
	<u> </u>		(Note: Report results of multiple completion on Well
			Completion or Recompletion Report and Log Form.)
		pertinent dates, including estimated date of starting	Completion or Recompletion Report and Log Form.)
	perations (Clearly state all pertinent details, and give nd measured and true vertical depths for all markers		Completion or Recompletion Report and Log Form.)
give subsurface locations an	nd measured and true vertical depths for all markers		Completion or Recompletion Report and Log Form.)
	nd measured and true vertical depths for all markers		Completion or Recompletion Report and Log Form.)
give subsurface locations an	nd measured and true vertical depths for all markers	s and zones pertinent to this work.)	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled,
give subsurface locations at OLD PERFS: 80 3-18-97 SET CH	nd measured and true vertical depths for all markers 068'-8335' 3P @ 8026', PLUS MADE 2 DU	s and zones pertinent to this work.)	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, F ON TOP. (NEW PBTD @ 7976')
give subsurface locations an OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D	nd measured and true vertical depths for all markers 168'-8335' BP @ 8026', PLUS MADE 2 DU ELAWARE @ 4624-28'.	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, F ON TOP. (NEW PBTD @ 7976')
give subsurface locations an OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID	nd measured and true vertical depths for all markers 168'-8335' BP @ 8026', PLUS MADE 2 DU ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS.	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled,
give subsurface locations an OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID FRAC	nd measured and true vertical depths for all markers)68'-8335' BP @ 8026', PLUS MADE 2 DU ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF C w/ 15000 GALS 30 # X-LINK &	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD.	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, F ON TOP. (NEW PBTD @ 7976')
give subsurface locations an OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID FRAC	nd measured and true vertical depths for all markers 168'-8335' BP @ 8026', PLUS MADE 2 DU ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD.	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, FON TOP. (NEW PBTD @ 7976') RECEIVED
give subsurface locations an OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID FRAC	nd measured and true vertical depths for all markers)68'-8335' BP @ 8026', PLUS MADE 2 DU ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF C w/ 15000 GALS 30 # X-LINK &	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD.	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, F ON TOP. (NEW PBTD @ 7976')
give subsurface locations an OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID FRAC	nd measured and true vertical depths for all markers)68'-8335' BP @ 8026', PLUS MADE 2 DU ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF C w/ 15000 GALS 30 # X-LINK &	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD.	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, F ON TOP. (NEW PBTD @ 7976') RECEIVED D.) DAYID R GIAM APR 10 37
give subsurface locations an OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID FRAC	nd measured and true vertical depths for all markers)68'-8335' BP @ 8026', PLUS MADE 2 DU ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF C w/ 15000 GALS 30 # X-LINK &	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD.	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, TON TOP. (NEW PBTD @ 7976') RECEIVED D.). DAVID.R. GIAMAR 10 97 BLM
give subsurface locations an OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID FRAC 3-27-97 PUT ON	nd measured and true vertical depths for all markers ()68'-8335' BP @ 8026', PLUS MADE 2 DU ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF C w/ 15000 GALS 30 # X-LINK & V PRODUCTION: SN @ 4395 &	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD. & TAC @ 4063'	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, F ON TOP. (NEW PBTD @ 7976') RECEIVED D). DAVID.R. GLAMMAR 10 97 BLM ROSWELL, NM
give subsurface locations an OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID FRAC 3-27-97 PUT ON NOTE: LEFT P	nd measured and true vertical depths for all marker ()68'-8335' BP @ 8026', PLUS MADE 2 DU ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF C w/ 15000 GALS 30 # X-LINK & V PRODUCTION: SN @ 4395 & IT OPEN BUT FENCED WHIL	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD. : TAC @ 4063'	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, F ON TOP. (NEW PBTD @ 7976') RECEIVED D). DAVID.R. GLAMMAR 10 97 BLM ROSWELL, NM
give subsurface locations an OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID FRAC 3-27-97 PUT ON NOTE: LEFT P	nd measured and true vertical depths for all markers ()68'-8335' BP @ 8026', PLUS MADE 2 DU ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF C w/ 15000 GALS 30 # X-LINK & V PRODUCTION: SN @ 4395 &	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD. : TAC @ 4063'	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, F ON TOP. (NEW PBTD @ 7976') RECEIVED D). DAVID.R. GLAMMAR 10 97 BLM ROSWELL, NM
give subsurface locations an OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID FRAC 3-27-97 PUT ON NOTE: LEFT P	nd measured and true vertical depths for all marker ()68'-8335' BP @ 8026', PLUS MADE 2 DU ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF C w/ 15000 GALS 30 # X-LINK & V PRODUCTION: SN @ 4395 & IT OPEN BUT FENCED WHIL	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD. : TAC @ 4063'	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, F ON TOP. (NEW PBTD @ 7976') RECEIVED D). DAVID.R. GLAMMAR 10 97 BLM ROSWELL, NM
give subsurface locations an OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID FRAC 3-27-97 PUT ON NOTE: LEFT P	nd measured and true vertical depths for all marker ()68'-8335' BP @ 8026', PLUS MADE 2 DU ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF C w/ 15000 GALS 30 # X-LINK & V PRODUCTION: SN @ 4395 & IT OPEN BUT FENCED WHIL	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD. : TAC @ 4063'	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, F ON TOP. (NEW PBTD @ 7976') RECEIVED D). DAVID.R. GLAMMAR 10 97 BLM ROSWELL, NM
give subsurface locations and OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID FRAC 3-27-97 PUT ON NOTE: LEFT P IF NOT NEE	nd measured and true vertical depths for all marker)68'-8335' BP @ 8026', PLUS MADE 2 DL ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF C w/ 15000 GALS 30 # X-LINK & PRODUCTION: SN @ 4395 & IT OPEN BUT FENCED WHIT DED FOR ADDITIONAL TES	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD. : TAC @ 4063'	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, F ON TOP. (NEW PBTD @ 7976') RECEIVED D). DAVID.R. GLAMMAR 10 97 BLM ROSWELL, NM
give subsurface locations and OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID FRAC 3-27-97 PUT ON NOTE: LEFT P IF NOT NEE	nd measured and true vertical depths for all marker)68'-8335' BP @ 8026', PLUS MADE 2 DL ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF C w/ 15000 GALS 30 # X-LINK & PRODUCTION: SN @ 4395 & IT OPEN BUT FENCED WHIT DED FOR ADDITIONAL TES	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD. : TAC @ 4063'	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, F ON TOP. (NEW PBTD @ 7976') RECEIVED D). DAVID.R. GLAMMAR 10 97 BLM ROSWELL, NM
give subsurface locations an OLD PERFS: 80 3-18-97 SET CIH 3-20-97 PERF D ACID FRAC 3-27-97 PUT ON NOTE: LEFT P IF NOT NEE	nd measured and true vertical depths for all marker)68'-8335' BP @ 8026', PLUS MADE 2 DL ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF C w/ 15000 GALS 30 # X-LINK & PRODUCTION: SN @ 4395 & IT OPEN BUT FENCED WHIT DED FOR ADDITIONAL TES	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD. TAC @ 4063' LE TESTING WELL. WILL BE TING.	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, TON TOP. (NEW PBTD @ 7976') RECEIVED DAVID R GIAMAR 10 97 BLM ROSWELL, NM RECEATMED WITHIN 30 DAYS
give subsurface locations at OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID FRAC 3-27-97 PUT ON NOTE: LEFT P IF NOT NEE	nd measured and true vertical depths for all marker ()68'-8335' BP @ 8026', PLUS MADE 2 DU ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF W/ 15000 GALS 30 # X-LINK & V PRODUCTION: SN @ 4395 & IT OPEN BUT FENCED WHIL DED FOR ADDITIONAL TES'	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD. : TAC @ 4063'	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, TON TOP. (NEW PBTD @ 7976') RECEIVED DAVID R GLAMADR 10 97 BLM ROSWELL, NM ROSWELL, NM
give subsurface locations an OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID FRAC 3-27-97 PUT ON NOTE: LEFT P IF NOT NEE	nd measured and true vertical depths for all marker ()68'-8335' BP @ 8026', PLUS MADE 2 DU ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF W/ 15000 GALS 30 # X-LINK & V PRODUCTION: SN @ 4395 & IT OPEN BUT FENCED WHIL DED FOR ADDITIONAL TES'	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD. TAC @ 4063' LE TESTING WELL. WILL BE TING.	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, TON TOP. (NEW PBTD @ 7976') RECEIVED DAVID R GIAMAR 10 97 BLM ROSWELL, NM RECEATMED WITHIN 30 DAYS
give subsurface locations at OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID FRAC 3-27-97 PUT ON NOTE: LEFT P IF NOT NEE	nd measured and true vertical depths for all marker ()68'-8335' BP @ 8026', PLUS MADE 2 DU ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF W/ 15000 GALS 30 # X-LINK & V PRODUCTION: SN @ 4395 & IT OPEN BUT FENCED WHIL DED FOR ADDITIONAL TES'	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD. TAC @ 4063' LE TESTING WELL. WILL BE TING.	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled, TON TOP. (NEW PBTD @ 7976') RECEIVED DAVID R GIAMAR 10 97 BLM ROSWELL, NM RECEATMED WITHIN 30 DAYS
give subsurface locations and OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID FRAC 3-27-97 PUT ON NOTE: LEFT P IF NOT NEE t hereby certify that the forego Signed	nd measured and true vertical depths for all marker 068'-8335' BP @ 8026', PLUS MADE 2 DU ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF W/ 15000 GALS 30 # X-LINK & V PRODUCTION: SN @ 4395 & IT OPEN BUT FENCED WHIL DED FOR ADDITIONAL TES Ing of true and correct Ing of true and Ing o	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD. TAC @ 4063' LE TESTING WELL. WILL BE TING. Title PROD. MGR./ EN	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled. TON TOP. (NEW PBTD @ 7976') RECEIV COMPLETED OF DECEIV COMPLETED OF DECEIV RECEIV BLM ROSWELL, NM RECEIVENT BLM ROSWELL, NM RECEIVENT BLM ROSWELL, NM COMPLETED OF DECEIVENT BLM ROSWELL, NM
give subsurface locations and OLD PERFS: 80 3-18-97 SET CH 3-20-97 PERF D ACID FRAC 3-27-97 PUT ON NOTE: LEFT P IF NOT NEE IF NOT NEE	nd measured and true vertical depths for all marker 068'-8335' BP @ 8026', PLUS MADE 2 DU ELAWARE @ 4624-28'. IZED w/ 2000 GALS 15% NEF W/ 15000 GALS 30 # X-LINK & V PRODUCTION: SN @ 4395 & IT OPEN BUT FENCED WHIL DED FOR ADDITIONAL TES Ing of true and correct Ing of true and Ing o	s and zones pertinent to this work.) JMP RUNS TO DUMP 50 ' CMT E ACID & BS. & 36000# SD. TAC @ 4063' LE TESTING WELL. WILL BE TING. Title PROD. MGR./ EN	Completion or Recompletion Report and Log Form.) any proposed work. If well is directionally drilled. TON TOP. (NEW PBTD @ 7976') RECEIV COMPLETED OF DECEIV BLM ROSWELL, NM RECELAIMED WITTHIN 30 DAYS

* See Intruction on the Reverse Side

=