		N.M. Oil Cons. Division
Form 3160-5	UNITED STATES	B11 S. 1st Street Cl
100116 10000		Budget Bureau No. 1004-0135
BO	REAU OF LAND MANAGEMENT	Expires: March 31, 1993
CUNDD	Y NOTICES AND REPORTS ON WELLS	6.2
	proposals to drill or to deepen or reentry to a different reserve	cir.
	LICATION FOR PERMIT " for such proposals	6. Shaian, Shottee or Tribe Name
		WELLER If Unit or CA, Agreement Designation
1. Type of Well: OIL WELL		DOW B 33 FEDERAL
2. Name of Operator	FEB 1 9 1	997
···· · · · · · · · · · · · · · · · · ·	O EXPLORATION & PRODUCTION INC.	2
3. Address and Telephone No. 205 E. I	Bender, HOBBS, NM 88240 🛛 🛛 🗍 🗋 C 🔿 🚧	41 0 4. API Well No. 30-015-27675
4. Location of Well (Footage, Sec., T.,	R., M., or Survey Description) DIST	
Unit Letter C : 660 F	Feet From The NORTH Line and 2310 Feet From	
MENT 15- Autor 20		11. County or Parish, State
WEST Line Section 33	Township <u>17S</u> Range <u>31E</u>	EDDY , N.M.
^{12.} Check App	propriate Box(s) To Indicate Nature of Noti	ice. Report, or Other Data
TYPE OF SUBMISSION		TYPE OF ACTION
	Abandonment	Change of Plans
8	Recompletion	New Construction
Notice of Intent	Plugging Back	Non-Routine Fracturing
Subsequent Report	Casing Repair	Water Shut-Off
Final Abandonment Notice	Atlering Casing	Conversion to Injection
—	OTHER:	Dispose Water
		(Note: Report results of multiple completion on Weil Completion or Recompletion Report and Log Form.)
work. If well is directionally drilled,	perations (Clearly state all pertinent details, and give pertinent give subsurface locations and measured and true vertical dep PLETED IN THE CEDAR LAKE MORROW ZONE. THE FO IN THE WILDCAT ATOKA ZONE.	ths for all markers and zones pertinent to this work,)*.
1. MIRU. Bleed off pressure & kill we	ell w/ 10 lb. brine. ND tree & NU 5,000# BOP. Test BOP.	
2. Release packer, pull tubing, on/off	tool, & packer assembly from 11,624'.	
	• •	
	ove Morrow perforations (11,735'-11,754'). TIH w/ bailer & d	
	• • • • • • • • • • • • • • • • • • •	7.000#. Hang packer @ app 11.100'.
4. TIH w/ on/off tool, 1.875" 'F' profile	a nipple, packer & wireline entry guide. Test tubing in hole to	Charles Carles
 TIH w/ on/off tool, 1.875" 'F' profile Circulate fluid around backside. Set 	et packer @ 11,100'. Test CIBP & backside to 2,000#.	
 TIH w/ on/off tool, 1.875" 'F' profile Circulate fluid around backside. Set 	et packer @ 11,100'. Test CIBP & backside to 2,000#.)#. Swab fluid down to 8,500'. Using high pressure lubricate	
 TIH w/ on/off tool, 1.875" 'F' profile Circulate fluid around backside. Set ND BOP & NU tree. Test to 5,000 tubing from 11,242'-11,248' w/ 1-1 	et packer @ 11,100'. Test CIBP & backside to 2,000#.)#. Swab fluid down to 8,500'. Using high pressure lubricate 1/16" strip guns.	or & grease injector, perforate 2 SPF through 2-7/8"
 TIH w/ on/off tool, 1.875" 'F' profile Circulate fluid around backside. St ND BOP & NU tree. Test to 5,000 tubing from 11,242'-11,248' w/ 1-1 If stimulation is necessary, acidize 	 packer @ 11,100'. Test CIBP & backside to 2,000#. W. Swab fluid down to 8,500'. Using high pressure lubricate 1/16" strip guns. perforations w/ 500 gals 7-1/2% HCL @ 2 to 3 bpm. Hold 	or & grease injector, perforate 2 SPF through 2-7/8"
 TIH w/ on/off tool, 1.875" 'F' profile Circulate fluid around backside. St. ND BOP & NU tree. Test to 5,000 tubing from 11,242'-11,248' w/ 1-1 If stimulation is necessary, acidize 	et packer @ 11,100'. Test CIBP & backside to 2,000#.)#. Swab fluid down to 8,500'. Using high pressure lubricate 1/16" strip guns.	or & grease injector, perforate 2 SPF through 2-7/8"
 TIH w/ on/off tool, 1.875" 'F' profile Circulate fluid around backside. St. ND BOP & NU tree. Test to 5,000 tubing from 11,242'-11,248' w/ 1-1 If stimulation is necessary, acidize 	 packer @ 11,100'. Test CIBP & backside to 2,000#. W. Swab fluid down to 8,500'. Using high pressure lubricate 1/16" strip guns. perforations w/ 500 gals 7-1/2% HCL @ 2 to 3 bpm. Hold 	or & grease injector, perforate 2 SPF through 2-7/8"
 TIH w/ on/off tool, 1.875" 'F' profile Circulate fluid around backside. St. ND BOP & NU tree. Test to 5,000 tubing from 11,242'-11,248' w/ 1-1 If stimulation is necessary, acidize 	 packer @ 11,100'. Test CIBP & backside to 2,000#. W. Swab fluid down to 8,500'. Using high pressure lubricate 1/16" strip guns. perforations w/ 500 gals 7-1/2% HCL @ 2 to 3 bpm. Hold 	or & grease injector, perforate 2 SPF through 2-7/8"
 TIH w/ on/off tool, 1.875" 'F' profile Circulate fluid around backside. St. ND BOP & NU tree. Test to 5,000 tubing from 11,242'-11,248' w/ 1-1 If stimulation is necessary, acidize 	 packer @ 11,100'. Test CIBP & backside to 2,000#. W. Swab fluid down to 8,500'. Using high pressure lubricate 1/16" strip guns. perforations w/ 500 gals 7-1/2% HCL @ 2 to 3 bpm. Hold 	or & grease injector, perforate 2 SPF through 2-7/8"
 TIH w/ on/off tool, 1.875" 'F' profile Circulate fluid around backside. St ND BOP & NU tree. Test to 5,000 tubing from 11,242'-11,248' w/ 1-1 If stimulation is necessary, acidize 5,000#. Flush to bottom perf w/ K0 	et packer @ 11,100'. Test CIBP & backside to 2,000#.)#. Swab fluid down to 8,500'. Using high pressure lubricate 1/16" strip guns. perforations w/ 500 gals 7-1/2% HCL @ 2 to 3 bpm. Hold CL water. Swab back well until flowing and return well to pro	or & grease injector, perforate 2 SPF through 2-7/8" 1,000# throughout job. Max pressure not to exceed oduction in Wildcat Atoka.
 TIH w/ on/off tool, 1.875" 'F' profile Circulate fluid around backside. Sr ND BOP & NU tree. Test to 5,000 tubing from 11,242'-11,248' w/ 1-1 If stimulation is necessary, acidize 5,000#. Flush to bottom perf w/ K0 	et packer @ 11,100'. Test CIBP & backside to 2,000#. #. Swab fluid down to 8,500'. Using high pressure lubricate 1/16" strip guns. perforations w/ 500 gals 7-1/2% HCL @ 2 to 3 bpm. Hold CL water. Swab back well until flowing and return well to pro TITLE Engr Asst	or & grease injector, perforate 2 SPF through 2-7/8"
 TIH w/ on/off tool, 1.875" 'F' profile Circulate fluid around backside. St. ND BOP & NU tree. Test to 5,000 tubing from 11,242'-11,248' w/ 1-1 If stimulation is necessary, acidize 5,000#. Flush to bottom perf w/ K0 	iet packer @ 11,100'. Test CIBP & backside to 2,000#. #. Swab fluid down to 8,500'. Using high pressure lubricate 1/16" strip guns. perforations w/ 500 gals 7-1/2% HCL @ 2 to 3 bpm. Hold CL water. Swab back well until flowing and return well to pro Performance TITLE Engr Asst Monte C. Duncan	or & grease injector, perforate 2 SPF through 2-7/8" 1,000# throughout job. Max pressure not to exceed oduction in Wildcat Atoka. DATE2/12/97
 4. TIH w/ on/off tool, 1.875" 'F' profile Circulate fluid around backside. St 5. ND BOP & NU tree. Test to 5,000 tubing from 11,242'-11,248' w/ 1-1 6. If stimulation is necessary, acidize 5,000#. Flush to bottom perf w/ K0 	Title Engr Asst Title Engr Asst PetroLEUM PetroLEUM	or & grease injector, perforate 2 SPF through 2-7/8" 1,000# throughout job. Max pressure not to exceed Date
 TIH w/ on/off tool, 1.875" 'F' profile Circulate fluid around backside. Sr ND BOP & NU tree. Test to 5,000 tubing from 11,242'-11,248' w/ 1-1 If stimulation is necessary, acidize 5,000#. Flush to bottom perf w/ K0 	et packer @ 11,100'. Test CIBP & backside to 2,000#. #. Swab fluid down to 8,500'. Using high pressure lubricate 1/16" strip guns. perforations w/ 500 gals 7-1/2% HCL @ 2 to 3 bpm. Hold CL water. Swab back well until flowing and return well to pro TITLE Engr Asst	or & grease injector, perforate 2 SPF through 2-7/8" 1,000# throughout job. Max pressure not to exceed oduction in Wildcat Atoka. DATE2/12/97