(June 1990) DEPARTMEN' BUREAU OF L SUNDRY NOTICES A Do not use this form for proposals to dri	ED STATES T OF THE INTERIOR AND MANAGEMENT AND REPORTS ON WELL Il or to deepen or reenty ED PERMIT—'' for such proto	S a dilleje W leservoli.	
SUBMIT	IN TRIPLICATE S	EP 1 9 1995	7. If Unit or CA, Agreement Designation
 Type of Well Oil Well Well Other Name of Operator YATES PETROLEUM CORPORATION Address and Telephone No. 105 South 4th St., Artesia, N Location of Well (Footage, Sec., T., R., M., or Survey De 990' FSL & 2145' FWL of Section 	(505) 748 (M 88210 scription)	CON. DIV. Patt. 2	 8. Well Name and No. <u>Sand Tank APS Fed Com #</u>1 9. API Well No. 30-015-28692 10. Field and Pool, or Exploratory Area W11dcat Sand Tank Morrow/Strate 11. County or Parish, State Eddy Co., NM
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE	OF NOTICE, REPO	
TYPE OF SUBMISSION		TYPE OF ACTION	
X Notice of Intent	Abandonment XX Recompletion / I Plugging Back	Dual Commingle	Change of Plans
Final Abandonment Notice	Casing Repair Altering Casing Other		Water Shut-Off Conversion to Injection Dispose Water (Nute: Report results of multiple completion on Well
 Describe Proposed or Completed Operations (Clearly state all give subsurface locations and measured and twe vertice. Propose to temporarily isolate plete to Strawn 10326-10484', and produce Morrow up annulus 1. Load well with 2% KCL wat 11197'. POOH with packer and 2. TIH with production packer load off Morrow and restore p 3. Set plug in packer to iso up hole to 10480'. Spot 200 4. Perforate 10326-10484' w/ 10432-10484'. Straddle and a 5. Straddle perforations 10% be necessary. 6. ND wellhead, NU and test 7. TIH with on/off tool over dual packer will be set at 10% ND BOP & NU wellhead. 8. Set plug in packer at 10% sleeve. Pull plug from packer 14 Thereby certify that the foregoing is not and correct prosigned with the foregoing is not and correct pros	al deputs for all markers and zones perime te perforations 11120 , test and evaluate S s and Strawn up tubin ter. Release packer d RBP. er with on/off tool. production in order to olate Morrow perfs 11 gallons 15% inhibited /50 holes as follows: acidize each zone ind 326-10484' and swab/f BOP. POOH with trea rshot, 800' tubing, d 0290'. Open sliding s er @ 10290'. Swab in oduce Strawn up tubin	<pre>ht to this work)' -11163' (Morrow trawn perforation g as follows: at 11033'. TIH Set packer at 1 o prevent damage 120-11163'. Rei d iron control H 10326-10332'; ividually. low test. Addit ting packer and ual packer and slatched into bot leeve. Swab in Strawn. Produc g. NOTE: Have Technician</pre>	- producing) and recom- ons, make dual completion and retrieve RBP at 11190'. Swab Morrow e. lease on/off tool. Pull ACL acid. POOH w/tubing. 10389-10398' and tional stimulation may RBP. sliding sleeve so that ttom packer at 11090'. Morrow. Close sliding ce Morrow up annulus &

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitions or fraudulent statements or representations as to any matter within its jurisdiction.