 	•				
Submit 3 Copies to Appropriate District Office	State of Nev E ^r 79, Minerals and Natur		015	Form C-103 Revised 1-1-	
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88 240	OIL CONSERVAT		WELL API NO		
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mex		30-015-29 5. Indicate Type	of Lease	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Ga		EE L
(DO NOT USE THIS FORM FOR PE DIFFERENT RESE	ICES AND REPORTS ON V OPOSALS TO DRILL OR TO DEEL RVOR. USE "APPLICATION FOR 2-101) FOR SUCH PROPOSALS.)	PEN OR PLUG BACK TO A	7. Lease Name or	Unit Agreement Name	
1. Type of Well: OIL WELL X WELL	OTHER	RECEIVER	State 647	AC 711	
2. Name of Operator SDX Resources, Inc.		MAR 0 3 1997	8. Well No. 132)	
3. Address of Operator P. O. Box 5061, Midla	nd, TX. 79704		9. Pool name or W	Vildcat	
4. Well Location	Feet From The South	11 1. () -	9 g	QN-GR-SA	
			E J		_ L
Section 27	Township 188 10. Elevation (Show whet	Range 28E her DF, RKB, RT, GR, etc.)	NMPM EO		County
	GR 3551' Appropriate Box to Indicat ENTION TO: PLUG AND ABANDON				
NOTICE OF IN ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING ULL OR ALTER CASING THER: Add additional 12 Describe Proposed or Completed Opera work) SEE RULE 1103. Well w 8-5/8" csg @ 388', cm 300 sxs 50/50 Poz. H 20% HCl & 5000 g. hea Propose to TIH w/RBP to 1000 psi. Tubing Acidize all perfs w/3 frac w/40,000# 20/40	Appropriate Box to Indicat ENTION TO: PLUG AND ABANDON CHANGE PLANS	SUB REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: , and give perinent dates, include of completed and r 5-1/2" csg @ 3049" ced w/2500 g. 15% Test for 5 BO, ga cc hole clean w/2% 00 psi. Perf 1 sp ay stabilizer XP. 1. Flow back frace	SEQUENT R COPNS.	EPORT OF: ALTERING CASING PLUG AND ABANDONM starting any proposed luce 10/20/96. 75 sxs 65/35 Pos l w/5000 g. heat 3W, filed on 11, RBP, csg, & BOI 4', total 21 ho 000 g. 25# Delta a clean to RBP	z + ced /15/ p
NOTICE OF IN ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING ULL OR ALTER CASING Well v. 8–5/8" csg @ 388', cm 300 sxs 50/50 Poz. H 20% HC1 & 5000 g. head Propose to TIH w/RBP to 1000 psi. Tubing Acidize all perfs w/3 frac w/40,000# 20/40 and retrieve RBP. Put I hereby certify that the information above is true SKONATURE MODEL ON THE CASING MODEL ON THE CASING	Appropriate Box to Indicat FENTION TO: PLUG AND ABANDON CHANGE PLANS perfs in Grayburg fions (Clearly state all perinent details ras spudded 9/05/96 ar ted w/350 sxs Cl C; 5 Perfs 2842-2897, treat ted 40# gelled wtr. & set @ ± 2650'. Cin will be tested to 250 6000 g. 15% NEFE w/cla sd & 60,000# 12/20 sc tt on pump to test.	SUB REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: and give periment dates, included of completed and r 5-1/2" csg @ 3049" ted w/2500 g. 15% Test for 5 BO, gat ted w/2500 g. 15% ted w/2500 g. 15% ted w/25% ted w/25%	SEQUENT R COPNS.	EPORT OF: ALTERING CASING PLUG AND ABANDONM starting any proposed luce 10/20/96. 75 sxs 65/35 Pos l w/5000 g. heat 3W, filed on 11, RBP, csg, & BOI 4', total 21 ho 000 g. 25# Delta a clean to RBP	z + :ed /15/ 2