

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE \*  
(Other Instructions on  
reverse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS


(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT - " for such proposals.)

1. OIL ☒ WELL GAS ☐ WELL OTHER ☐

2. NAME OF OPERATOR  
The Wiser Oil Company

3. ADDRESS OF OPERATOR  
P.O. Box 2568 Hobbs, New Mexico 88241

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface  
1303' FNL & 1306' FEL  
Unit A



5. LEASE DESIGNATION AND SERIAL NO.  
LC-029418(b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME  
Lea "D"

8. WELL NAME AND NO.  
10

9. API WELL NO.  
30-015-29704

10. FIELD AND POOL, OR WILDCAT  
Grayburg Jackson 7-Rivers-QN-GB-SA

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA  
Sec. 26-T17S-R31E

14. PERMIT NO

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3761'

12. COUNTY OR PARISH  
Eddy

13. STATE  
NM

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF ☐ PULL OR ALTER CASING ☐  
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐  
SHOOT OR ACIDIZE ☐ ABANDON\* ☐  
REPAIR WELL ☐ CHANGE PLANS ☐

(Other) Temporary Abandon

MIT

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐  
FRACTURE TREATMENT ☐ ALTERING CASING ☐  
SHOOTING OR ACIDIZING ☐ ABANDONMENT \* ☐

(Other)

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Wiser requests approval to Temporary Abandon the well by the procedure listed below.

Perforations: 3467'-4056'

1. MIRU unit. POH & LD equipment.

2. 11H & set CIBP @ 3400'. Dump 10 sks. cement on CIBP.

3. Pressure test plug & csg. to 3000' 500#

4. If holds circulate pkr. fluid.

5. Pressure test csg. to 300# with a pressure recorder.

6. Shut well n. 500# for 30 minutes

\*Note: Call OCD before beginning work.

18. I hereby certify that the foregoing is true and correct.

SIGNED [Signature] TITLE Superintendent DATE June 28, 2002

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE Deputy Superintendent DATE 7/18/02

CONDITIONS OF APPROVAL, IF ANY:

\*See Instruction On Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Notify OGD 48 hrs. prior to any work done