

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. <b>30-015-30177</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>James Garvin 22 State</b>
8. Well No. <b>1</b>
9. Pool name or Wildcat <b>Turkey Track North Morrow</b>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>GL 3586' KB 3604'</b>

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator <b>Marathon Oil Company</b>
3. Address of Operator <b>P.O. Box 2490 Hobbs, NM 88240</b>	4. Well Location Unit Letter <b>0</b> : <b>660</b> Feet From The <b>South</b> Line and <b>1980</b> Feet From The <b>East</b> Line Section <b>22</b> Township <b>18-S</b> Range <b>28-E</b> NMPM <b>Eddy</b> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>GL 3586' KB 3604'</b>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **New Well Completion** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/15/98 MIRU PU. NU BOBE. RIH w/bit on 2 7/8" prod tbg. Start drilling cement.

7/17 DO to PBD 11,081'. Circ clean. Pickle tbg w/800 gals 15% acid. Spot 500 gals perf fluid from 10,850-11,081'. Run logs. POOH.

7/19 RIH w/perf guns & pkr on 2 7/8" prod tbg. ND BOPE. Set pkr at 10,628'. NU tree. Perf 10,817-25', 10,832-36', 10,843-53', 10,886-71' w/6 SPF, 60 deg phas, 162 holes. Flow well to test tank. RD PU.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 8/3/98  
TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

APPROVED BY SUPERVISOR, DISTRICT II TITLE  DATE 8-4-98  
CONDITIONS OF APPROVAL, IF ANY: