

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

CONFIDENTIAL

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30015-30961
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: SOUTHERN CROSS '29' STATE
8. Well No. 1
9. Pool name or Wildcat ANTELOPE SINK N. MORROW
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3798' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other ☐
2. Name of Operator
CONCHO RESOURCES INC.
3. Address of Operator
110 W. LOUISIANA STE 410; MIDLAND TX 79701
4. Well Location

Unit Letter B : 800 feet from the North line and 1500 feet from the EAST line
Section 29 Township 18S Range 24E NMPM EDDY County

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Lack of reservoir rock. Well **Drilled and Abandoned**, approved by Gerry Guy, OCD, according to the following procedure:

Set 100' plug @ 8103'
Set 100' plug @ 6101'
Set 100' plug @ 4121'
Set 100' plug @ 2110'
Set 200' plug @ 1342'. Tagged @ 1141'.
Set 100' plug @ surface.
Install P&A marker. RDMO.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry Stathem TITLE Production Analyst DATE 11/30/00

Type or print name Terry Stathem Telephone No. 915-683-7443

(This space for State use) **ORIGINAL SIGNED BY TIM W. GUN**
DISTRICT II SUPERVISOR

APPROVED BY [Signature] TITLE [Signature] DATE DEC 04 2000

Conditions of approval, if any: [Signature]