

30-015-31232

OKRTD 10179

PROD 12958

POOL 39516

ARD  
8/20/01

NSL-4589  
6-4-01

AZ LL  
Micro-CFL/Gamma Ray  
3080/11195  
3D/LD/Comp Neut/GR  
200/11203



Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO.  
30-015-31232

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:  
LOCO HILLS WELCH

8. Well No.  
5

9. Pool name or Wildcat  
LOCO HILLS BONE SPRING

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
Harvey E. Yates Company

3. Address of Operator  
P.O. Box 1933, Roswell, New Mexico 88202

4. Well Location  
Unit Letter L : 1450 feet from the SOUTH line and 660 feet from the WEST line  
Section 4 Township 18 S Range 29 E NMPM EDDY County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3540' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

1. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Upon partner approval we plan to plug and abandon the Loco Hills Welch #5 as follows:

1. Set CIBP @ 6300' + 50' cement.
2. Circulate 9# mud.
3. Spot 150' class 'c' cement plug from 4250' - 4100'. 3970 - 4120'
4. Spot 100' class 'c' cement plug from 3130' - 3030'. - TAG
5. Cut & pull approx. 1450' of 5 1/2" csg. Spot 100' plug (50' above & 50' below shoe) @ 1500' - 1400'. Tag plug.
6. Spot 100' cement plug from 450' - 350'. - TAG 160' plug 750' - 850' - TAG
7. Set 20 sx cement surface plug. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jeanetta Atkinson TITLE Production Analyst DATE 10/4/02

Type or print name Jeanetta Atkinson Telephone No. 505-623-6601

(This space for State use)

APPROVED BY [Signature] TITLE Wild Sup ID DATE OCT 18 2002

Conditions of approval, if any: