Submit 3 Copies Office			of New M			Form (-10
District I		Energy, Miner	rals and Nat	ural Resources	r	Revised March 2	
District II	Dr., Hobbs, NM 88240				WELL API NO.		
811 South First, / District III	Artesia, NM 88210	OIL CONSE			30-015-3 5. Indicate Type		
	Rd., Aztec, NM 87410	2040	South Pac	heco	STATE		
District IV		Santa	a Fe, NM 8	7505	6. State Oil &		
2040 South Pache	eco, Santa Fe, NM 8750		01	567	0. State Off &	Gas Lease No.	
DIFFERENTRES	HIS FORM FOR PRO	DTICES AND REPORTS POSALS TO DRILL OR TO D LICATION FOR PERMIT	SON WELLS	UG BACK POA		or Unit Agreement N	ame:
PROPOSALS.) 1. Type of We Oil Well	ell:	Other &	RECE	OR SUCH TP 1930 TP		og State	
2. Name of (Manza	Operator ano 0il Corpo				8. Well No.		<u> </u>
3. Address o	of Operator		122		9. Pool name or	Wildcat	
4. Well Loca	Box 2107, Ro	oswell, NM 88202	-2107	<u>31</u>	Wildcat		
	hion						
Unit I		: 660 feet from t	he <u>North</u>	line and]	feet fro	m the West	line
Sectio	on 30	Township		inge 23E	NMPM Eddy	County NM	
		10. Elevation (Sho	<i>w whether Di</i> 60 ' GL	R, RKB, RT, GR, etc	≈)		
**************************************	11. Check	Appropriate Box to	Indicate N	ature of Notice	Papart or Other	Data	
	NUTICE OF I	NIENHONIO:			SEQUENT REI	Data DODT OF	
PERFORM RE	MEDIAL WORK		ОМ 🔲	REMEDIAL WOR		ALTERING CASIN	GЕ
TEMPORARIL		CHANGE PLANS		COMMENCE DRI	LLING OPNS.	PLUG AND	
				COMMENCE DRI		PLUG AND ABANDONMENT	
TEMPORARIL				COMMENCE DRI CASING TEST AN CEMENT JOB			
		MULTIPLE		CASING TEST AN CEMENT JOB			
PULL OR ALTE OTHER: 12. Describe p	ER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB OTHER:		ABANDONMENT	
PULL OR ALTE OTHER: 12. Describe p	ER CASING	MULTIPLE		CASING TEST AN CEMENT JOB OTHER:		ABANDONMENT	
PULL OR ALTE OTHER: 12. Describe p of starting	ER CASING E proposed or comple any proposed work llation. Day #41.	MULTIPLE COMPLETION	v state all perior Multiple C	CASING TEST AN CEMENT JOB OTHER: tinent details, and gi completions: Attach	ive pertinent dates, wellbore diagram	ABANDONMENT including estimated of proposed complet	[X Late
PULL OR ALTE OTHER: 12. Describe p of starting or recompi	ER CASING E proposed or complet any proposed work ilation. Day #41. R plugs: 1st 20 sks	MULTIPLE COMPLETION eted operations. (Clearly k). SEE RULE 1103. Fo Released rig 8:00	y state all per or Multiple C p.m. 11/	CASING TEST AN CEMENT JOB OTHER: tinent details, and gi completions: Attach 29/00. Well	ive pertinent dates, wellbore diagram	ABANDONMENT including estimated of proposed complet	[X Late ion
PULL OR ALTE OTHER: 12. Describe p of starting or recompi	ER CASING proposed or comple any proposed work lation. Day #41. R plugs: 1st 20 sks 2nd 20 sks	MULTIPLE COMPLETION eted operations. (Clearly k). SEE RULE 1103. Fo Released rig 8:00 - 100' plug from - 100' plug from	p.m. 11/ 7200' ba 5486' ba	CASING TEST AN CEMENT JOB OTHER: timent details, and gr completions: Attach 29/00. Well	ID ive pertinent dates, wellbore diagram of P&A. Set fol	ABANDONMENT including estimated of proposed complet	[X Late ion
PULL OR ALTE OTHER: 12. Describe p of starting or recompi	ER CASING proposed or comple any proposed work lation. Day #41. R plugs: 1st 20 sks 2nd 20 sks	MULTIPLE COMPLETION eted operations. (Clearly k). SEE RULE 1103. Fo Released rig 8:00 - 100' plug from - 100' plug from - 100' plug w/4%	y state all perfor Multiple C p.m. 11/ 7200' ba 5486' ba CaC1 fro	CASING TEST AN CEMENT JOB OTHER: timent details, and gi completions: Attach 29/00. Well ck to 7100' ck to 5386' m 3446' back	ID ive pertinent dates, wellbore diagram of P&A. Set fol	ABANDONMENT including estimated of proposed complet	[X date
PULL OR ALTE OTHER: 12. Describe p of starting or recompi	ER CASING proposed or compleany proposed work any proposed work ilation. Day #41. R plugs: 1st 20 sks 2nd 20 sks 3rd 20 sks	MULTIPLE COMPLETION eted operations. (Clearly k). SEE RULE 1103. Fo Released rig 8:00 - 100' plug from - 100' plug from - 100' plug w/4% Wait 2 hrs. To	y state all perfor Multiple C p.m. 11/ 7200' ba 5486' ba CaC1 fro aq © 3344	CASING TEST AN CEMENT JOB OTHER: timent details, and gi completions: Attach 29/00. Well ck to 7100' ck to 5386' m 3446' back	ID ive pertinent dates, in wellbore diagram of P&A. Set fol to 3346'	ABANDONMENT including estimated of proposed complet	[X Late ion
PULL OR ALTE OTHER: 12. Describe p of starting or recompi	ER CASING proposed or compleany proposed work any proposed work ilation. Day #41. R plugs: 1st 20 sks 2nd 20 sks 3rd 20 sks	MULTIPLE COMPLETION eted operations. (Clearly k). SEE RULE 1103. Fo Released rig 8:00 - 100' plug from - 100' plug from - 100' plug w/4% Wait 2 hrs. Ta - 100' plug w/4%	y state all perfor Multiple C p.m. 11/ 7200' ba 5486' ba CaCl fro ag © 3344 CaCl fro	CASING TEST AN CEMENT JOB OTHER: timent details, and gi completions: Attach 29/00. Well ck to 7100' ck to 5386' m 3446' back '. m 1850' back	ID ive pertinent dates, in wellbore diagram of P&A. Set fol to 3346'	ABANDONMENT including estimated of proposed complet	[X Late ion
PULL OR ALTE OTHER: 12. Describe p of starting or recompi	ER CASING proposed or complete any proposed work ilation. Day #41. F plugs: 1st 20 sks 2nd 20 sks 3rd 20 sks 3rd 20 sks 4th 20 sks 5th 20 sks	MULTIPLE COMPLETION eted operations. (Clearly k). SEE RULE 1103. Fo Released rig 8:00 - 100' plug from - 100' plug from - 100' plug w/4% Wait 2 hrs. Ta - 100' plug ŵ/4% Wait 2 hrs. Ta - 100' plug from	y state all perfor Multiple C p.m. 11/ 7200' ba 5486' ba CaCl fro ag @ 3344 CaCl fro ag @ 1753	CASING TEST AN CEMENT JOB OTHER: timent details, and gi completions: Attach 229/00. Well ck to 7100' ck to 5386' m 3446' back ' m 1850' back	ID ive pertinent dates, in wellbore diagram of P&A. Set fol to 3346'	ABANDONMENT including estimated of proposed complet	[X Late ion
PULL OR ALTE OTHER: 12. Describe p of starting or recompi	ER CASING proposed or complete any proposed work ilation. Day #41. F plugs: 1st 20 sks 2nd 20 sks 3rd 20 sks 3rd 20 sks 4th 20 sks 5th 20 sks	MULTIPLE COMPLETION eted operations. (Clearly k). SEE RULE 1103. Fo Released rig 8:00 - 100' plug from - 100' plug from - 100' plug w/4% Wait 2 hrs. Ta - 100' plug w/4%	y state all perfor Multiple C p.m. 11/ 7200' ba 5486' ba CaCl fro ag @ 3344 CaCl fro ag @ 1753	CASING TEST AN CEMENT JOB OTHER: timent details, and gi completions: Attach 229/00. Well ck to 7100' ck to 5386' m 3446' back ' m 1850' back	ID ive pertinent dates, in wellbore diagram of P&A. Set fol to 3346'	ABANDONMENT including estimated of proposed complet	[X Late ion
PULL OR ALTE OTHER: 12. Describe p of starting or recompi	ER CASING proposed or complete any proposed work ilation. Day #41. F plugs: 1st 20 sks 2nd 20 sks 3rd 20 sks 3rd 20 sks 4th 20 sks 5th 20 sks	MULTIPLE COMPLETION eted operations. (Clearly k). SEE RULE 1103. Fo Released rig 8:00 - 100' plug from - 100' plug from - 100' plug w/4% Wait 2 hrs. Ta - 100' plug ŵ/4% Wait 2 hrs. Ta - 100' plug from	y state all perfor Multiple C p.m. 11/ 7200' ba 5486' ba CaCl fro ag @ 3344 CaCl fro ag @ 1753	CASING TEST AN CEMENT JOB OTHER: timent details, and gi completions: Attach 229/00. Well ck to 7100' ck to 5386' m 3446' back ' m 1850' back	ID ive pertinent dates, in wellbore diagram of P&A. Set fol to 3346'	ABANDONMENT including estimated of proposed complet	[X Late ion
PULL OR ALTE OTHER: 12. Describe p of starting or recompi	ER CASING proposed or complete any proposed work ilation. Day #41. F plugs: 1st 20 sks 2nd 20 sks 3rd 20 sks 3rd 20 sks 4th 20 sks 5th 20 sks	MULTIPLE COMPLETION eted operations. (Clearly k). SEE RULE 1103. Fo Released rig 8:00 - 100' plug from - 100' plug from - 100' plug w/4% Wait 2 hrs. Ta - 100' plug ŵ/4% Wait 2 hrs. Ta - 100' plug from	y state all perfor Multiple C p.m. 11/ 7200' ba 5486' ba CaCl fro ag @ 3344 CaCl fro ag @ 1753	CASING TEST AN CEMENT JOB OTHER: timent details, and gi completions: Attach 229/00. Well ck to 7100' ck to 5386' m 3446' back ' m 1850' back	ID ive pertinent dates, in wellbore diagram of P&A. Set fol to 3346'	ABANDONMENT including estimated of proposed complet	[X date
PULL OR ALTE OTHER: 12. Describe p of starting or recompi 11/30/00	ER CASING proposed or complete any proposed work llation. Day #41. F plugs: 1st 20 sks 2nd 20 sks 3rd 20 sks 3rd 20 sks 4th 20 sks 5th 20 sks 6th 10 sks	MULTIPLE COMPLETION eted operations. (Clearly k). SEE RULE 1103. Fo Released rig 8:00 - 100' plug from - 100' plug from - 100' plug w/4% Wait 2 hrs. Ta - 100' plug w/4% Wait 2 hrs. Ta - 100' plug from - surface plug	p.m. 11/ 7200' ba 5486' ba CaCl fro ag @ 3344 CaCl fro ag @ 1753 500' bac	CASING TEST AN CEMENT JOB OTHER: iment details, and gi completions: Attach 29/00. Well ck to 7100' ck to 5386' m 3446' back im 1850' back k to 400'	ID ive pertinent dates, in wellbore diagram of P&A. Set foll to 3346' to 1750'	ABANDONMENT including estimated of proposed complet	[X Late ion
PULL OR ALTE OTHER: 12. Describe p of starting or recompi 11/30/00	ER CASING proposed or complete any proposed work llation. Day #41. F plugs: 1st 20 sks 2nd 20 sks 3rd 20 sks 3rd 20 sks 4th 20 sks 5th 20 sks 6th 10 sks	MULTIPLE COMPLETION eted operations. (Clearly k). SEE RULE 1103. Fo Released rig 8:00 - 100' plug from - 100' plug from - 100' plug w/4% Wait 2 hrs. Ta - 100' plug ŵ/4% Wait 2 hrs. Ta - 100' plug from	p.m. 11/ 7200' ba 5486' ba CaCl fro ag @ 3344 CaCl fro ag @ 1753 500' bac	CASING TEST AN CEMENT JOB OTHER: iment details, and gi completions: Attach 29/00. Well ck to 7100' ck to 5386' m 3446' back im 1850' back k to 400'	ID ive pertinent dates, in wellbore diagram of P&A. Set foll to 3346' to 1750'	ABANDONMENT including estimated of proposed complet	[X Late ion
PULL OR ALTE OTHER: 12. Describe p of starting or recompi 11/30/00	ER CASING proposed or complete any proposed work llation. Day #41. F plugs: 1st 20 sks 2nd 20 sks 3rd 20 sks 3rd 20 sks 4th 20 sks 5th 20 sks 6th 10 sks	MULTIPLE COMPLETION eted operations. (Clearly k). SEE RULE 1103. Fo Released rig 8:00 - 100' plug from - 100' plug from - 100' plug w/4% Wait 2 hrs. Ta - 100' plug w/4% Wait 2 hrs. Ta - 100' plug from - surface plug	p.m. 11/ 7200' ba 5486' ba CaCl fro ag @ 3344 CaCl fro ag @ 1753 500' bac	CASING TEST AN CEMENT JOB OTHER: iment details, and gi completions: Attach 29/00. Well ck to 7100' ck to 5386' m 3446' back im 1850' back k to 400'	ID ive pertinent dates, in wellbore diagram of P&A. Set foll to 3346' to 1750' e and belief.	ABANDONMENT including estimated of proposed complet	IX date ion
PULL OR ALTE OTHER: 12. Describe p of starting or recompi 11/30/00 hereby certify to GIGNATURE	ER CASING proposed or complete any proposed work ilation. Day #41. F plugs: 1st 20 sks 2nd 20 sks 3rd 20 sks 3rd 20 sks 4th 20 sks 5th 20 sks 6th 10 sks that the/information me	MULTIPLE COMPLETION eted operations. (Clearly k). SEE RULE 1103. Fo Released rig 8:00 - 100' plug from - 100' plug from - 100' plug w/4% Wait 2 hrs. Ta - 100' plug w/4% Wait 2 hrs. Ta - 100' plug from - surface plug	p.m. 11/ 7200' ba 5486' ba CaCl fro ag @ 3344 CaCl fro ag @ 1753 500' bac	CASING TEST AN CEMENT JOB OTHER: iment details, and gi completions: Attach 29/00. Well ck to 7100' ck to 5386' m 3446' back ' m 1850' back k to 400'	ID ive pertinent dates, in wellbore diagram of P&A. Set foll to 3346' to 1750' e and belief. ering	ABANDONMENT including estimated of proposed complet llowing cement 	IX date ion
PULL OR ALTE OTHER: 12. Describe p of starting or recompi 11/30/00 11/30/00	ER CASING proposed or complete any proposed work ilation. Day #41. F plugs: 1st 20 sks 2nd 20 sks 3rd 20 sks 3rd 20 sks 4th 20 sks 5th 20 sks 6th 10 sks that the/information me	MULTIPLE COMPLETION eted operations. (Clearly k). SEE RULE 1103. For Released rig 8:00 - 100' plug from - 100' plug from - 100' plug w/4% Wait 2 hrs. Ta - 100' plug w/4% Wait 2 hrs. Ta - 100' plug w/4% Wait 2 hrs. Ta - 100' plug from - surface plug	p.m. 11/ 7200' ba 5486' ba CaCl fro ag @ 3344 CaCl fro ag @ 1753 500' bac	CASING TEST AN CEMENT JOB OTHER: iment details, and gi completions: Attach 29/00. Well ck to 7100' ck to 5386' m 3446' back ' m 1850' back k to 400'	ID ive pertinent dates, in wellbore diagram of P&A. Set foll to 3346' to 1750' e and belief. ering	ABANDONMENT including estimated of proposed complet llowing cement 	Late ion
PULL OR ALTE OTHER: 12. Describe p of starting or recompi 11/30/00 hereby certify to GIGNATURE	ER CASING proposed or compleany proposed work any proposed work lation. Day #41. Find plugs: 1st 20 sks 2nd 20 sks 3rd 20 sks 4th 20 sks 5th 20 sks 6th 10 sks that the information me State use)	MULTIPLE COMPLETION eted operations. (Clearly k). SEE RULE 1103. For Released rig 8:00 - 100' plug from - 100' plug from - 100' plug w/4% Wait 2 hrs. Ta - 100' plug w/4% Wait 2 hrs. Ta - 100' plug w/4% Wait 2 hrs. Ta - 100' plug from - surface plug	p.m. 11/ 7200' ba 5486' ba CaCl fro ag @ 3344 CaCl fro ag @ 1753 500' bac	CASING TEST AN CEMENT JOB OTHER: iment details, and gi completions: Attach 29/00. Well ck to 7100' ck to 5386' m 3446' back ' m 1850' back k to 400'	ID ive pertinent dates, in wellbore diagram of P&A. Set fol to 3346' to 1750' e and belief. ering Telepho	ABANDONMENT including estimated of proposed complet llowing cement 	IX date ion