form 9-331								
May 1963)					ATE*	Form ap Budget 1	Bureau No.	42-R142
	DEPAR	TMLNT OF THE		≺ verse side)	f_{ℓ} 5.	NM-04		BRIAL NO.
	· ··· · · · · · · · · · · · · · · · ·	GEOLOGICAL SU	RVEY	- Apply	14			·····
	SUNDRY NC	DTICES AND REP	PORTS ON	WELLS	J , 6 .	IF INDIAN, ALLO	PTEE OR T	RIBE NAMI
(Do not us	se this form for pro	posais to drill or to deep ICATION FOR PERMIT-	en or plug back	to a different reservoir.		1		
				Bala, /		UNIT AGREEMEN		
	VELL OTHER							
NAME OF OPERA					8.	FARM OR LEASE	NAME	
S. P. Yates						Yates-Miller		
B. ADDRESS OF OFBRATOR						WELL NO.	Ier	
207 8	South 4th	Street- Arte	sia. New	Mexico 882		1		
LOCATION OF W	ELL (Report location	n clearly and in accordance	ce with any Stat	te requirements.*		. FIELD AND POC	L, OR WILL	CAT
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface					1	McMillan ext.		
1650	FNL & 23	10' FWL of Se	ec. 28-1	9S-27E	11	BEC., T., R., M., SURVET OR	OR BLK. AN	ID
PERMIT NO.						28-195-2		
. PERMIT NO.		10. ELEVATIONS (Show	BLEVATIONS (Show whether DF, RT, GR, etc.)			COUNTY OF PA	RISH 13.	êtate
						Eddez	12	m
•	Check /	Appropriate Box To I	ndicate Natu	ire of Notice, Report,	or Othe	er Data		
	NOTICE OF INT		1			BEPORT OF		
			[]	~				
TEST WATER S		FULL OR ALTER CASING		WATER SHUT-OFF		2 - C - C - C - C - C - C - C - C - C -	ING WELL	
FRACTURE TRE SHOOT OR ACI		MULTIPLE COMPLETE		FRACTURE TREATMENT			NG CARING	
REPAIR WELL		CHANGE PLANS		(Other)	، السما	ABANDO	nment*	F
(Other)				(Other) (Nors: Report 1 Completion or Re	esults of	multiple complet	tion on We	-[] n
This	well was r	olugged on 1	-10-68 :	ag follows.	2 2 2 2			È
Loade #1 - #2 -	ed hole wit Plug - TD Plug - 5 g marker.	890'-790' -	before a 35 sacks of surfa	spotting plug s ace with dry	hole		Lon	
Loade #1 - #2 -	ed hole wit Plug - TD Plug - 5 g marker.	th heavy mud 890'-790' - sacks at top	before a 35 sacks of surfa	spotting plug ace with dry on.	hole	regulati	Lon	
Loade #1 - #2 -	ed hole wit Plug - TD Plug - 5 g marker.	th heavy mud 890'-790' - sacks at top	before a 35 sacks of surfa	spotting plug ace with dry on.	hole	regulati	Lon	
Loade #1 - #2 -	ed hole wit Plug - TD Plug - 5 g marker.	th heavy mud 890'-790' - sacks at top	before a 35 sacks of surfa	spotting plug ace with dry on. 3 1968	hole	regulat:	Lon	
Loade #1 - #2 -	ed hole wit Plug - TD Plug - 5 g marker.	th heavy mud 890'-790' - sacks at top	before a 35 sacks of surfa	spotting plug ace with dry on. 3 1968	hole	regulat:	Lon	
Loade #1 - #2 -	ed hole wit Plug - TD Plug - 5 g marker.	th heavy mud 890'-790' - sacks at top	before a 35 sacks of surfa	spotting plug ace with dry on. 3 1968	hole	regulat: NN 13		
Loade #1 - #2 -	ed hole wit Plug - TD Plug - 5 g marker.	th heavy mud 890'-790' - sacks at top	before a 35 sacks of surfa	spotting plug ace with dry on. 3 1968	hole	regulat:	Lon	
Loade #1 - #2 - The h	ed hole wit Plug - TD Plug - 5 a marker. ole is now	th heavy mud 890'-790' - sacks at top v ready for i	before a 35 sacks of surfa	spotting plug ace with dry on. 3 1968	hole	Fegulat :	Lon	
Loade #1 - #2 - The h	ed hole wit Plug - TD Plug - 5 a marker. ole is now	th heavy mud 890'-790' - sacks at top	before a 35 sacks of surfa	spotting plug ace with dry on. 3 1958	hole	regulat	6 8 SUPP	
Loade #1 - #2 - The h	ed hole wit Plug - TD Plug - 5 a marker. ole is now	th heavy mud 890'-790' - sacks at top v ready for i	before a 35 sacks of surfa	spotting plug ace with dry on. 3 1968	hole	regulat:	Lon 8 9 1-15-	68
Loade #1 - #2 - The h	ed hole wit Plug - TD Plug - 5 a marker. ole is now	th heavy mud 890'-790' - sacks at top v ready for i s is true and correct Factor T	before a 35 sacks of surfa	spotting plug ace with dry on. 3 1958	hole		6 8 SUPP	68
Loade #1 - #2 - The h	ed hole with Plug - TD Plug - 5 s marker. ole is now y that the foregoing r reteral or State of The state of the st	th heavy mud 890'-790' - sacks at top v ready for i s is true and correct Circy use)	before a 35 sacks of surfa	spotting plug ace with dry on. 3 1958	hole		6 8 SUPP	68
Loade #1 - #2 - The h	ed hole with Plug - TD Plug - 5 s marker. ole is now y that the foregoing r reteral or State of The state of the st	th heavy mud 890'-790' - sacks at top v ready for i s is true and correct Correct Total use)	before s 35 sacks of surfa nspectio	spotting plug ace with dry on. 3 1958	hole		6 8 SUPP	68
Loade #1 - #2 - The h	ed hole with Plug - TD Plug - 5 s marker. ole is now y that the foregoing r reteral or State of The state of the st	th heavy mud 890'-790' - sacks at top v ready for i s is true and correct Circy use)	before s 35 sacks of surfa nspectio	spotting plug ace with dry on. 3 1958	hole		6 8 SUPP	68
Loade #1 - #2 - The h The h	ed hole with Plug - TD Plug - 5 s marker. ole is now y that the foregoing r reteral or State of The state of the st	th heavy mud 890'-790' - sacks at top v ready for i v ready for i s is true and correct C	before s 35 sacks of surfa nspectic	Agent	hole		6 8 SUPP	68
Loade #1 - #2 - The h 8. I bereby certif SIGNED	ed hole with Plug - TD Plug - 5 s marker. ole is now y that the foregoing r reteral or State of The state of the st	th heavy mud 890'-790' - sacks at top v ready for i v ready for i s is true and correct C	before s 35 sacks of surfa nspectic	spotting plug ace with dry on. 3 1958	hole		6 8 SUPP	68

•

~ ,

.

•