

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

L CONSERVATION DIVISION

RECEIVED BY SANTA FE, NEW MEXICO 87501 MAY 26 1986 O. C. D. ARTESIA, OFFICE	RECEIVED BY SANTA FE, NEW MEXICO 87501 JUN 12 1986 O. C. D. ARTESIA, OFFICE
---	---

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B 7717

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection Well
2. Name of Operator Herman J. Ledbetter ✓
3. Address of Operator P. O. Box 5879, Abilene, Texas 79608
4. Location of Well UNIT LETTER <u>I</u> , <u>330</u> FEET FROM THE <u>East</u> LINE AND <u>1650</u> FEET FROM THE <u>South</u> LINE, SECTION <u>1</u> TOWNSHIP <u>19S</u> RANGE <u>29E</u> N.M.P.M.

7. Unit Agreement Name
8. Farm or Lease Name Leonard State
9. Well No. 4
10. Field and Pool, or Wildcat East Turkey Track Queen

15. Elevation (Show whether DF, RT, GR, etc.) 3407.6 G L

12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1.* Hook up cementer to oil string and squeeze down casing with Bradenhead open.
When cement returns to surface via annulus between oil string and surface pipe, close in bradenhead and continue squeeze.
2. Let cement set.
3. Drill our cement in casing and test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Herman J. Ledbetter</u> TITLE <u>operator</u>	DATE <u>5-20-86</u>
---	---------------------

APPROVED BY <u>Mike Williams</u> TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>OCT 02 1986</u>
---	-------------------------

CONDITIONS OF APPROVAL, IF ANY: * Depending on where hole is in log

