

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501
APR 23 1987
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
E#1055

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator D.W. Berry	8. From or Lease Name State T
3. Address of Operator 20 Gary Drive, Artesia NM 88210	9. Well No. 1
4. Location of Well UNIT LETTER E 1650 FEET FROM THE North LINE AND 990 FEET FROM THE West LINE, SECTION 12 TOWNSHIP 19S RANGE 29 E N.M.P.M.	10. Field and Pool, or Without Turkey Track Queen East
15. Elevation (Show whether DF, RT, GR, etc.) 3393 GL	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Frac new zone	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

April 25, 1987

1. Pull Rods and tubing out of hole. Run and set Bridge Plug in hole at 2400 ft.
2. Fill Casing with water and perforate casing at 2350 ft. to 2385 ft.
3. Run and set Packer on 3 inch tubing and Acidize to be followed with Frac.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE **Agent** DATE **April 22, 1987**

Original Signed By
Les A. Clements

APPROVED BY [Signature] Supervisor District II

CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE **APR 23 1987**