

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN
(Other ins
verse side)MULTIPLICATE*
(ons on re-)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. LC 047633 (b)	
2. NAME OF OPERATOR Atlantic Richfield Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 1978, Roswell, New Mexico 88201		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL & 1980' FWL Unit letter K		8. FARM OR LEASE NAME E.M. Swearingen "B"	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3703' CTF		10. FIELD AND POOL, OR WILDCAT Shugart-Queen	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 14, T18S, R31E	
		12. COUNTY OR PARISH Eddy	
		13. STATE New Mex.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Production on this well has declined to less than 1 BOPD & 15 BWPD and it is no longer economical to produce. We propose to plug and abandon as follows:

Shoot off and recover 7" casing from free point.
Set 30 sx cement from 3250' to 3150'.
Set 30 sx cement across 7" stub.
Set 30 sx cement across 8-5/8" shoe @ 881'.
Set 10 sx cement in top of well.
9#/gal gel mud will be used to spot all plugs.
8-5/8" casing @ 881' will remain intact.

Dry hole marker will be erected and location cleared and levelled.

18. I hereby certify that the foregoing is true and correct

SIGNED

A.D. Hetches

TITLE

Dist. Drlg. Supervisor

DATE

10-29-70

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

OCT 30 1970

R. L. BEEKMA

ACTING DISTRICT SUPERVISOR