

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN
(Other inst.
verse side)PLICATE
s on reForm approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC 047633 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Swearingen "B"

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Shugart

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 14, T18S, R31E

12. COUNTY OR PARISH 13. STATE

Eddy N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. NAME OF OPERATOR Atlantic Richfield Company	3. ADDRESS OF OPERATOR P. O. Box 1978, Roswell, New Mexico 88201	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 660' FWL (Unit Letter D)	14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3713' GR
--	---	---	--	----------------	--

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

This well was shut in during November, 1969 after production had declined to 1/2 BOPD + 97% water. We now propose to P & A as follows:

Shoot off and recover 7" casing from as deep as possible. Spot these cement plugs w/9#/gal salt gel mud:

30 sx 3390-3260'

30 sx 2610-2480'

30 sx In and out of 7" stub

30 sx Across 8-5/8" shoe @ 797'

10 sx In top of well

8-5/8" casing string will remain intact. A depth hole marker will be erected and location cleared & levelled.

18. I hereby certify that the foregoing is true and correct

SIGNED

O. D. Litcher

TITLE

Dist. Drlg. Supervisor

DATE

6-1-70

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side