

DEPARTMENT OF THE INTERIOR (Form 6-69)
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. LC 047633 (4)
2. NAME OF OPERATOR Atlantic Richfield Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 1978, Roswell, New Mexico 88201		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 660' FEL (Unit letter A)		8. FARM OR LEASE NAME L.M. Swearingen "A"
14. PERMIT NO.		9. WELL NO. 2
15. ELEVATIONS (Show whether DF, RT, CR, etc.) 3733' GR		10. FIELD AND POOL, OR WILDCAT Shugart
		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec. 14, T-18S, R-31E
		12. COUNTY OR PARISH Eddy
		13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐
(Other) ☐		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Production on this well dropped to 1/2 BOPD w/a 98% water cut and well was shut in on 1/19/70. We propose to plug & abandon the well as follows:

1. Set 30 sack cement plug half in and out of 5 1/2" shoe @ 3324'.
2. Shoot off and recover 5 1/2" casing from free point.
3. Set these cement plugs w/salt gel mud.
 - a. 30 sx in and out of 5 1/2" stub.
 - b. 30 sx in and out of 8-5/8" shoe @ 819'.
 - c. 10 sx in top of well.

Dry hole marker will be installed and location cleared and levelled. 8-5/8" casing will remain intact.

RECEIVED
MAY 27 1970
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct
SIGNED W. L. Ditcher TITLE Dist. Drlg. Supervisor DATE 5/26/70

(This space for Federal or State office use)

APPROVED BY H. L. BECKMA
CONDITIONS OF APPROVAL, IF ANY:
MAY 27 1970
H. L. BECKMA
ACTING DISTRICT SUPERVISOR

TITLE _____ DATE _____

RECEIVED
MAY 28 1970
O. C. C.
ARTESIA, OFFICE

*See Instructions on Reverse Side