

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPI
(Other instructions
verse side)

TE
Re

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

dsf

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR William A. & Edward R. Hudson ✓
3. ADDRESS OF OPERATOR Box 9, Maljamar, New Mexico 88264 O. C. D.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
1980' from north and 660' from east lines of
Sec. 15-18S-31E
14. PERMIT NO.
15. ELEVATIONS (Show whether DP, RT, GR, etc.)

5. LEASE DESIGNATION AND SERIAL NO.
LC-062052
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Shugart "B"
9. WELL NO.
5
10. FIELD AND POOL, OR WILDCAT
Shugart Queen
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 15-18S-31E
12. COUNTY OR PARISH
Eddy
13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐
REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well pumps about 1 barrel of oil + 1 barrel of water per month, and is uneconomical to operate. We propose to plug and abandon well as follows:

1. Set bridge plug in 5½" casing at about 3262' with 35' of cement on top.
2. Fill hole with salt gel mud to 2050'.
3. Place 100' of cement from 2050' to 1950'.
4. Fill hole with salt gel mud to 740'. Fill hole to surface with fresh water.
5. Perforate 5½" casing at approximately 890' and circulate cement to surface behind 5½" casing. Leave 100' of cement inside 5½" casing across 8 5/8" casing shoe. Spot 50' of cement at surface.
6. Clean location and re-seed in accordance with BLM regulations.

TAG

Notify BLM at 887-6544 prior to commencing P & A operations.


18. I hereby certify that the foregoing is true and correct

SIGNED Dwaine Kuerste TITLE Prod. Supt. DATE Mar. 21, 1989

(This space for Federal or State office use)


APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side



WILLIAM A. & EDWARD R. HUDSON
Shugart B #5

SKETCH



William A. & Edward R. Hudson
Shugart B Lease
Well # 5

Completed: July 28, 1957

Total depth: 4145'

Casing: 8 5/8" 24# at 783' with 200 sx.
5 1/2" 15.5# at 4144' with 1,200 sx.

Bridge plug at 3430'

5 1/2" casing perforated at 3362'-72 and 3388-96'

Treated with 10,000 gals. Redi-frac + 12,000# sd.
in first stage and 5,000 gals. Redi-frac +
8,000# sd. in second stage with 50# moth
balls between stages.

Top of Anhydrite - 730'

Top of salt - 900'

Base of salt - 2,000'

Top of Queen - 3354'