Form 3160-5 (June 1990)

## JITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Oil Cons.
M. DIV-Dist PRM APPROVED
1301 W. Grand Appen March 31, 1993
Artesia, NM 1882 appretion and Serial No.
LC 2029392 B

		LC - 029392 B
SUNDRY NOTICES AND REPORTS ON WELLS o not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals		6. If Indian, Allottee or Tribe Name
SUBMIT	T IN TRIPLICATE	7. If Unit or CA, Agreement Designation
pe of Well		
⊠ Welt		8. Well Name and No.
ame of Operator	00DID # 455045	Hinkle B-26 #4
adel and Gussman Permian, L.L.C. Idress and Telephone No.	OGRID # 155615	9. API Well No. 30-015-05611
11 N. Marienfeld, Suite 508, Midland, TX 79	9701 915-682-4429	10. Field and Pool, or Exploratory Area
cation of Well (Footage, Sec., T., R., M., or Survey D		Shugart YT, 7R, QN, GB
550' FSL & 2310' FWL nit K, Sec. 26 - 18S - 31E		11. County or Parish, State  Eddy Co., NM
CHECK APPROPRIATE BOX(	s) TO INDICATE NATURE OF NOTICE, REPORT,	<del>                                     </del>
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
	Altering Casing	Conversion to Injection
Final Abandonment Notice	· • • • • • • • • • • • • • • • • • • •	
Describe Proposed or Completed Operations (Clearly irectionally drilled, give subsurface locations and mea	state all pertinet details, and give pertinent dates, including estimated date assured and true vertical depths for all markders and zones pertinent to this ced flowline. Put well back on production.	
Describe Proposed or Completed Operations (Clearly	state all pertinet details, and give pertinent dates, including estimated date asured and true vertical depths for all markders and zones pertinent to this ked flowline. Put well back on production.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  e of starting any proposed work. If well is
Describe Proposed or Completed Operations (Clearly irrectionally drilled, give subsurface locations and mean decay of the completed of the complete of the com	state all pertinet details, and give pertinent dates, including estimated date as used and true vertical depths for all markders and zones pertinent to this ked flowline. Put well back on production.  3 bw, tstm gas.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  e of starting any proposed work. If well is swork.)*
Describe Proposed or Completed Operations (Clearly irrectionally drilled, give subsurface locations and mean decay of the completed of the complete of the com	state all pertinet details, and give pertinent dates, including estimated date asured and true vertical depths for all markders and zones pertinent to this ked flowline. Put well back on production.  3 bw, tstm gas.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  e of starting any proposed work. If well is
Describe Proposed or Completed Operations (Clearly irrectionally drilled, give subsurface locations and mean decay of the completed of the complete of the com	state all pertinet details, and give pertinent dates, including estimated date as used and true vertical depths for all markders and zones pertinent to this ked flowline. Put well back on production.  3 bw, tstm gas.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  e of starting any proposed work. If well is swork.)*
Describe Proposed or Completed Operations (Clearly irrectionally drilled, give subsurface locations and mean decay of the completed of the complete of the com	state all pertinet details, and give pertinent dates, including estimated date asured and true vertical depths for all markders and zones pertinent to this ked flowline. Put well back on production.  3 bw, tstm gas.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  e of starting any proposed work. If well is swork.)*
Describe Proposed or Completed Operations (Clearly irrectionally drilled, give subsurface locations and mean decay). 23-01 Serviced pumping unit and check decay. 24-01 On 24 hour test, made 1 bo and 3 hereby certify that the foregoing is true and correct med	state all pertinet details, and give pertinent dates, including estimated date asured and true vertical depths for all markders and zones pertinent to this ced flowline. Put well back on production.  3 bw, tstm gas.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  e of starting any proposed work. If well is swork.)*
Describe Proposed or Completed Operations (Clearly lirectionally drilled, give subsurface locations and mean decay). 23-01 Serviced pumping unit and check decay. 24-01 On 24 hour test, made 1 bo and 3 hereby certify that the foregoing is true and correct	state all pertinet details, and give pertinent dates, including estimated date asured and true vertical depths for all markders and zones pertinent to this ked flowline. Put well back on production.  3 bw, tstm gas.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  e of starting any proposed work. If well is swork.)*
Describe Proposed or Completed Operations (Clearly irrectionally drilled, give subsurface locations and mean decay). 23-01 Serviced pumping unit and check decay. 24-01 On 24 hour test, made 1 bo and 3 hereby certify that the foregoing is true and correct med	state all pertinet details, and give pertinent dates, including estimated date asured and true vertical depths for all markders and zones pertinent to this ked flowline. Put well back on production.  3 bw, tstm gas.  **  **  **  **  **  **  **  **  **	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  e of starting any proposed work. If well is swork.)*

\*See Instruction on Reverse Side

