	<u>,</u> ,		. –	4
)'wy-5 mher INNY	DEPARTMENT C	STATES	RECEIVED	FORM APPROVED Budget Bureau No. 1004-1135 Expires September 30, 1990
		ID MANAGEMENT	0	5 Lease Designation and Serial No NM-10190
s	UNDRY NOTICES AN	D REPORTS ON W	EELs 5 11 27 AM '90	6 If Indian, Allonee or Tribe Name
not use this form	for proposals to drill o "APPLICATION FOR P	r to deepen or reentry	Clona different reservour	
	SUBMIT IN	TRIPLICATE	RECEIVED	7. If Unit or CA. Agreement Designation
ype of Well	· · · · · · · · · · · · · · · · · · ·			8910115720
Od Cas Well Well Cother WIW			OCT 17 '90	8. Well Name and No.
ame of Operator	and oil & Can Comm	·	• • • •	East Shugart #3
	ondo Oil & Gas Comp	Jany	C. C. D.	300150568300\$1
ddress and Telephone No.	0. Box 2208, Rosw	vell, NM 88202	(505)625-6735	10. Field and Pool, or Exploratory Area
	Sec., T., R., M., or Survey Descrip			Shugart Yates 7R-Qn-
				11. County or Parish. State
99	0' FNL & 330' FEL;	Sec.34-T18S-R3	LE	
				Eddy Co., NM
CHECK AP	PROPRIATE BOX(s)	O INDICATE NATU	RE OF NOTICE, REP	ORT, OR OTHER DATA
TYPE OF SU			TYPE OF ACTIO	
XXNotice of In		Abandonm	······································	Change of Plans
Notice of In	lient			New Construction
	Report	Plugging E		Non-Routine Fracturing
Subsequent Report	Kepoli			
		Casing Re	peur	Water Shut-Off
Final Aband	sonment Nouce		A1158	Conversion to Injection
Final Aband	ionment Nouce		aug Clean out	Conversion to Injectuon
Describe Proposed of Compl	ered Operations (Clearly state all per	Altering C Other	asing <u>Clean out</u> (Note, Report resul Recompleuon Repo dates, including estimated date of sta	Conversion to Injectuon CSG & reperf existing int is of multiple completion or or and Log form.)
Describe Proposed or Compl give subsurface location		Alterns C Alterns C Other Timent details, and give pertunent epubs for all markers and zones Remove leaking Clean out casi 3316' to 3850' Loc set packer	Asing <u>Clean out</u> (Note. Report resul Recompleuon Repo dates, including estimated date of sta pertinent to this work.)* tubing. Mill ove ng, reperforate ex . Acid stimulate @ 3260' with new	Conversion to Injectuon <u>csg & reperf existing int</u> its of multiple completion or Well Completion or
Describe Proposed or Compl give subsurface location PI	eted Operations (Clearly state all per and measured and true vertical d	Alterns C Alterns C Other Timent details, and give pertunent epubs for all markers and zones Remove leaking Clean out casi 3316' to 3850' Loc set packer	Asing <u>Clean out</u> (Note. Report resul Recompleuon Repo dates, including estimated date of sta pertinent to this work.)* tubing. Mill ove ng, reperforate ex . Acid stimulate @ 3260' with new	Conversion to Injectuon Conversion to Injectuon Conversion to Injectuon its of multiple completion or or and Log form.) rrung any proposed work If well is directionally drutte rr Model D packer @ 2870'. isting intervals from to remove scale. Set ceramic coated tubing.
Describe Proposed or Compl give subsurface location PI	eted Operations (Clearly state all per ns and measured and true vertical d coposed procedure:	Aitenag C Aitenag C Coher Timent details, and give pertunent epths for all markers and zones Remove leaking Clean out casi 3316' to 3850' Loc set packer Test annulus t	Asing <u>Clean out</u> (Note. Report resul Recompleuon Repo dates, including estimated date of sta pertinent to this work.)* tubing. Mill ove ng, reperforate ex . Acid stimulate @ 3260' with new	Conversion to Injectuon Conversion to Injectuon Conversion to Injectuon its of multiple completion or or and Log form.) rrung any proposed work If well is directionally drutte rr Model D packer @ 2870'. isting intervals from to remove scale. Set ceramic coated tubing.
Describe Proposed or Compl give subsurface location PI	eted Operations (Clearly state all per ns and measured and true vertical d coposed procedure:	Aitenag C Aitenag C Coher Timent details, and give pertunent epths for all markers and zones Remove leaking Clean out casi 3316' to 3850' Loc set packer Test annulus t	Asing <u>Clean out</u> (Note. Report resul Recompleuon Repo dates, including estimated date of sta pertinent to this work.)* tubing. Mill ove ng, reperforate ex . Acid stimulate @ 3260' with new	Conversion to Injectuon Conversion to Injectuon Conversion to Injectuon its of multiple completion or or and Log form.) rrung any proposed work If well is directionally drutte rr Model D packer @ 2870'. isting intervals from to remove scale. Set ceramic coated tubing.
Describe Proposed or Compl give subsurface location PI	eted Operations (Clearly state all per ns and measured and true vertical d coposed procedure:	Aitenag C Aitenag C Coher Timent details, and give pertunent epths for all markers and zones Remove leaking Clean out casi 3316' to 3850' Loc set packer Test annulus t	Asing <u>Clean out</u> (Note. Report resul Recompleuon Repo dates, including estimated date of sta pertinent to this work.)* tubing. Mill ove ng, reperforate ex . Acid stimulate @ 3260' with new	Conversion to Injectuon Conversion to Injectuon Conversion to Injectuon its of multiple completion or or and Log form.) rrung any proposed work If well is directionally drutte rr Model D packer @ 2870'. isting intervals from to remove scale. Set ceramic coated tubing.
Describe Proposed or Compl give subsurface location PI	ered Operations (Clearly state all per ns and measured and true vertical d coposed procedure:	Aitenag C Aitenag C Coher Timent details, and give pertunent epths for all markers and zones Remove leaking Clean out casi 3316' to 3850' Loc set packer Test annulus t	Asing <u>Clean out</u> (Note. Report resul Recompleuon Repo dates, including estimated date of sta pertinent to this work.)* tubing. Mill ove ng, reperforate ex . Acid stimulate @ 3260' with new	Conversion to Injectuon Conversion to Injectuon Conversion to Injectuon its of multiple completion or or and Log form.) rrung any proposed work If well is directionally drutte rr Model D packer @ 2870'. isting intervals from to remove scale. Set ceramic coated tubing.
Describe Proposed or Compl give subsurface location PI	eted Operations (Clearly state all per ns and measured and true vertical d coposed procedure:	Aitenag C Aitenag C Coher Timent details, and give pertunent epths for all markers and zones Remove leaking Clean out casi 3316' to 3850' Loc set packer Test annulus t	Asing <u>Clean out</u> (Note. Report resul Recompleuon Repo dates, including estimated date of sta pertinent to this work.)* tubing. Mill ove ng, reperforate ex . Acid stimulate @ 3260' with new	Conversion to Injectuon Conversion to Injectuon Conversion to Injectuon its of multiple completion or or and Log form.) rrung any proposed work If well is directionally drutte rr Model D packer @ 2870'. isting intervals from to remove scale. Set ceramic coated tubing.
Describe Proposed or Compl give subsurface location PI PI	ered Operations (Clearly state all per ns and measured and true vertical d coposed procedure:	Alterna C Alterna C Coher Timent details, and give pertunent epths for all markers and zones Remove leaking Clean out casi 3316' to 3850' Loc set packer Test annulus t	Asing <u>Clean out</u> (Note. Report resul Recompleuon Repo dates, including estimated date of sta pertinent to this work.)* tubing. Mill ove ng, reperforate ex . Acid stimulate @ 3260' with new	Conversion to Injection <u>csg & reperf existing int</u> its of multiple completion or or and Log form.) rung any proposed work If well is directionally drulte er Model D packer @ 2870'. tisting intervals from to remove scale. Set ceramic coated tubing. nin. return to injection.
Describe Proposed or Compl give subsurface location Pr Pr	ered Operations (Clearly state all per ns and measured and true vertical d coposed procedure:	Alterna C Alterna C Coher Tunent details, and give pertunent epths for all markers and zones Remove leaking Clean out casi 3316' to 3850' Loc set packer Test annulus t 10/08/90.	Asing <u>Clean out</u> (Note. Report resul Recompleuon Repo dates, including estimated date of sta pertinent to this work.)* tubing. Mill ove ng, reperforate ex . Acid stimulate @ 3260' with new	Conversion to Injectuon Conversion to Injectuon Conversion to Injectuon its of multiple completion or or and Log form.) rrung any proposed work If well is directionally drutte rr Model D packer @ 2870'. isting intervals from to remove scale. Set ceramic coated tubing.
Describe Proposed or Compl give subsurface location Pr Pr Pr Pr Pr Pr Pr Pr Pr Pr Pr Pr Pr	eied Operations (Clearly state all per ns and measured and true vertical d coposed procedure: roposed date:	Alterna C Alterna C Coher Tunent details, and give perunent epths for all markers and zones Remove leaking Clean out casi 3316' to 3850' Loc set packer Test annulus t 10/08/90.	Asing <u>Clean out</u> (Note. Report resul Recompletion Repo dates, including estimated date of sta- pertiment to this work)* tubing. Mill ove ng, reperforate ex . Acid stimulate @ 3260' with new o 300 psi for 15 m .eum Engineer	Conversion to Injection <u>csg & reperf existing int</u> is of multiple completion or or and Log form.) rung any proposed work If well is directionally drute er Model D packer @ 2870'. Sisting intervals from to remove scale. Set ceramic coated tubing. in. return to injection. <u>Date 10/04/90</u>
Describe Proposed or Compl give subsurface location Pr Pr Pr Pr Pr Pr Pr Pr Pr Pr Pr Pr Pr	eied Operations (Clearly state all per ns and measured and true vertical d coposed procedure: roposed date:	Alterna C Alterna C Coher Tunent details, and give perunent epths for all markers and zones Remove leaking Clean out casi 3316' to 3850' Loc set packer Test annulus t 10/08/90.	Asing <u>Clean out</u> (Note. Report resul Recompletion Repo dates, including estimated date of sta- pertiment to this work)* tubing. Mill ove ng, reperforate ex . Acid stimulate @ 3260' with new o 300 psi for 15 m .eum Engineer	Conversion to Injection <u>csg & reperf existing int</u> its of multiple completion or or and Log form.) rung any proposed work If well is directionally drulte er Model D packer @ 2870'. tisting intervals from to remove scale. Set ceramic coated tubing. nin. return to injection.