

NO. OF COPIES RECEIVED	1
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION
JUN 2 1971

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

O. C. C.
ARTESIA, OFFICE

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-7904

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sun Oil Company	8. Farm or Lease Name N. M. Kewanee St. Com.
3. Address of Operator P. O. Box 1861 Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>2</u> TOWNSHIP <u>20S</u> RANGE <u>23E</u> NMPM.	10. Field and Pool, or Wildcat Cass Ranch Morrow Gas
15. Elevation (Show whether DF, RT, GR, etc.) 4038 GR	12. County Eddy

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Casing pullers: C. E. Knight & Co., Box 86, Snyder, Texas.

5/26/71 - Load hole with 9.5# brine. Set bridge plug @ 8434 with 3 sacks cement on top.
Top of cement 8404.

5/27/71 - Shoot 4 1/2" casing at 5503. Pull & lay down.

5/28/71 - Spot 35 sack cement plugs as follows: 5402-5502, 3600-3700, 2045-2145, 550-650.

5/31/71 - Spot 10 ft. cement plug at surface. Set marker & clear location.

Pipe left in hole:

20" 20'
8-5/8 2095'
4-1/2 2998' from 5503-8501

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ruth Hughes TITLE Proration Clerk DATE June 1, 1971

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE JUN 4 1971

CONDITIONS OF APPROVAL, IF ANY: