Form 3160-5

## **UNITED STATES**

M	OIL	CONS	COMMISSION
			ODM ADDDOVED

June 199	DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT		Artes	Bia, Bigget Barres Nov 1004-0135  Expires: March 31, 1993		
			T	5. Lease Designation and Serial No.	_	
	SUNDRY NOTICES		NMNM-0107697	_		
Do no	ot use this form for proposals to d	rill or to deepen or reentry to a different res R PERMIT—" for such proposals	servoir.	6. If Indian, Allottee or Tribe Name		
<u></u>	SUBMI		7. If Unit or CA, Agreement Designation	_		
1. Type						
<u>X</u>			8. Well Name and No.			
	of Operator /nx Petroleum Consulta	ļ.	<u>Jones B Federal #1</u> 9. API Well No.	_		
-	ess and Telephone No.		30-015-10056			
Р.	O. Box 1979, Hobbs, N. ion of Well (Footage, Sec., T., R., M., or Survey D.		10. Field and Pool, or Exploratory Area			
	ion of Well (Footage, Sec., Ť., R., M., or Súrvey D nit Letter I	<u> </u>	Lusk Strawn 11. County or Parish, State	_		
	980' FSL & 660' FEL		,,,			
	ec. 25, T-19S, R-31E		Eddy, NM	_		
12.	CHECK APPROPRIATE BOX	s) TO INDICATE NATURE OF NOTICE,	REPORT	r, OR OTHER DATA	_	
	TYPE OF SUBMISSION	ACTION				
	Notice of Intent	Abandonment		Change of Plans		
		Recompletion		New Construction		
	Subsequent Report	Plugging Back Casing Repair		Non-Routine Fracturing Water Shut-Off		
	Final Abandonment Notice	Altering Casing		Conversion to Injection		
		Other		Dispose Water (Note: Report results of multiple completion on Well		
13 Descr	ribe Proposed or Completed Operations (Clearly state a	Il pertinent details, and give pertinent dates, including estimated da	te of starting ar	Completion or Recompletion Report and Log form.)  ny proposed work. If well is directionally drille	_	
.s. Desc.	give subsurface locations and measured and true verti	cal depths for all markers and zones pertinent to this work.)*	_			
<ol> <li>Determine if 5 1/2" casing is in place. If it is, go to Step #3.</li> <li>If not, proceed to Step #2.</li> </ol>						
2.	Locate 5 1/2" casing as necessary.	stub. Test liner top to 50	)0 psi.	. Squeeze		
3.	Clean out 5 1/2" to 6	7				
4.	Set CIBP @ 6892' w/35					
5.	Block squeeze Delawar		APR PR			
6.	Perforate Delaware 46	1 5 199	··· i 1)			
7.	Swab test and stimula	te as necessary. Off ©	(Čuka - i	$f(x) = \frac{f}{m}$		
		The state of the s	987. 2			
		ں جے				
14 1 her	eby certify that the foregoing is true and correct				=	
Signe	Mer 11 Jane	Tide Vice President	<u>-</u>	Date4/12/95	_	
	space for Federal or State office use) Ong Signed by Shannon J. Shaw	PETROLEUM ENGINE	ED .	5/11/95		
	roved by	Tide PETROLEIAM ENGINE	ER	Date	-	