

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVED
OFFICE FOR NM
OF COPIES REQUIRED
(Other instructions on re-
lease and/or

BLM Roswell District
Modified Form No.
NM 06813

4158

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		2. NAME OF OPERATOR Marbob Energy Corporation		3a. Area Code & Phone No. 505-748-3303	
3. ADDRESS OF OPERATOR P. O. Drawer 217, Artesia, NM 88210		4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650 FSL 330 FWL		5. RECEIVED JUL 17 1992 O. C. D. ARTESIA OFFICE	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.)		6. LEASE DESIGNATION AND SERIAL NO. NM 06813	
				7. IF INDIAN, ALLOTTEE OR TRIBE NAME	
				7. UNIT AGREEMENT NAME	
				8. FARM OR LEASE NAME Tidewater FE	
				9. WELL NO. 3	
				10. FIELD AND POOL, OR WILDCAT Hackberry Yates SR-North	
				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 19-T19S-R31E	
				12. COUNTY OR PARISH Eddy	
				13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☒
☐

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

We propose to plug and abandon as follows:

NOTIFY BLM AT (505) 887-6544 PRIOR TO ANY WORK.

Set cmt plug from 2124' to 1956'. Tag plug @ 1956'. Set cmt plug from 1800' to 1700'. (Base Salt). Perf csg from 550' and circ cmt to surface. In the event we cannot circ cmt to surface, we will squeeze perf @ 550' w/50 sx cmt and tag plug @ 500'. Set surface plug and dry hole marker and clean location. 50'

FILL WELL BORE (BETWEEN PLUGS) WITH 9 PPG MUD.

USE CLASS "C" CEMENT MIXED WITH 6.3 GALS. OF FRESH WATER PER SACK.

18. I hereby certify that the foregoing is true and correct

SIGNED Robin Smith

TITLE Production Clerk

DATE 7/8/92

(This space for Federal or State office use)

APPROVED BY Adam Selameli

TITLE

DATE 7/15/92

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side