

Form 3160-5
(July 1989)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT REF. NO.
OFFICE FOR REVISION
OF COPIES REQUIRED
(Other instructions on reverse side)

BLM Roswell District
Modified Form No.
NM60-3160-4

clsr

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. LEASE DESIGNATION AND SERIAL NO.

NM 06813

2. IF INDIAN, ALLOTTEE OR TRIBE NAME

3. UNIT AGREEMENT NAME

4. FARM OR LEASE NAME

Tidewater Federal

5. WELL NO.

3

6. FIELD AND POOL, OR WILDCAT

Hackberry Yates SR, North

7. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 19, T19S, R31E

8. COUNTY OR PARISH

Eddy

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Marbob Energy Corporation

3a. Area Code & Phone No.

505-748-3303

3. ADDRESS OF OPERATOR

P. O. Drawer 217, Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

RECEIVED

SEP 30 1992

O. C. D.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

- 1) Spot 25 sacks cement plug at 2124' W.O.C. Tag at 1950'.
- 2) Lead hole with mud.
- 3) Spot 25 sacks cement plug at 1800'.
- 4) Perforate 4-1/2" casing at 550' Braiden head squeeze with 168 sacks. Cement to surface and set up P&A marker.

1-SA on 9/11/92

Post FD-2
10-9-92
P&A

Approved to be plugged by the well owner.
Liability for lands to be plugged with
surface restoration is completed.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Supervisor

DATE 9/14/92

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE 9/28/92

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side