	.** -		RECEIVEL	els
Form 3160-5 (December 1989)	UNIIED ST	HE INTERIOR	JUN 1 5 1992	FORM APPROVED Budget Bureau No. 1004-0135 Expires: September 30, 1990
	BUREAU OF LAND M	IANAGEMENT	O. C. D.	5 Lease Designation and Serial No. $CC - 029387 - D$
	SUNDRY NOTICES AND RI			6 If Indian. Allottee or Tribe Name
	m for proposals to drill or to a e "APPLICATION FOR PERMI			
SUBMIT IN TRIPLICATE				7. If Unit or CA. Agreement Designation
1. Type of Well Oil Well Well				8. Well Name and No.
2. Name of Operator				Kenwood No. 2
Xeric Oil & 3. Address and Telephone No	Gas Company			9. API Well No.
•	lland, TX 79710, 9	15-683-3171		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Shugart (Y.SR.Q GB)
	330' FSL 834' FWL T-18-S, R-31-E			Eddy County, NM
	DEPODELATE DOVAL TO IN			
	PPROPRIATE BOX(S) TO IN	ND-CATE NATURE		HI, OR OTHER DATA
TYPE OF SI		[]	TYPE OF ACTION	
Notice of 1	Intent	Abandonment Recompletion		Change of Plans
Subsequent	Report	Plugging Back		New Construction
		Can ng Repair		Water Shut-Off
🔲 Final Aban	ndonment Notice	Altering Casing	PSA	Conversion to Injection
3. Describe Proposed or Comp give subsurface location 1. We prop	leted Operations (Clearly state all pertinent de ins and measured and true certical depths for DOSE to P&A the sub	Tails and give pertinent dates, in all markers and zones pertiner ject well as	Recompletion Report a neluding estimated date of startin nt to this work it SOON as this t	of multiple completion on Well Completion or and Log form.) g any proposed work. If well is directionally drilled
3. Describe Proposed or Comp give subsurface location 1. We prop 2. Move in 3. Set CIB 4. Circ cs 5. Spot 15 6. Weld st This w surfac	Neted Operations (Clearly state all pertinent de ns and measured and true central depths for pose to P&A the sub rig up & pull 2 3, P @ 3350' (top of (g, w/65 BBLS 10# b) sx from 30' to su eel plate w/dry ho rell has 8 5/8" 28# e and 5 1/2" 14# cs	Dother Tails and give pertinent dates. In all markers and sumes pertiner ject well as /8" Tubing & Queen). Cap rine w/1/2 sx rface. le marker. Surface Csg. sq set at 344	(Note: Report results of Recompletion Report a neluding estimated date of startin to this work it soon as this rods our of he w/20 sx "C" ct salt gel per	of multiple completion on Well Completion or ind Log form.) g any proposed work. If well is directionally drilled proceedure is approved ple. mt. BBL
3. Describe Proposed or Comp give subsurface location 1. We prop 2. Move in 3. Set CIB 4. Circ cs 5. Spot 15 6. Weld st This w surfac to be	ileted Operations (Clearly state all pertinent de ins and measured and true certical depths for pose to P&A the sub rig up & pull 2 3, 3P @ 3350' (top of (ig. w/65 BBLS 10# b) sx from 30' to sub ceel plate w/dry hob	Dother Tails and give pertinent dates. In all markers and sumes pertiner ject well as /8" Tubing & Queen). Cap rine w/1/2 sx rface. le marker. Surface Csg. sq set at 344	(Note: Report results of Recompletion Report a neluding estimated date of startin to this work it soon as this rods our of he w/20 sx "C" ct salt gel per	of multiple completion on Well Completion or ind Log form.) g any proposed work. If well is directionally drilled proceedure is approved ple. mt. BBL
 Describe Proposed or Comp give subsurface location 1. We prop 2. Move in 3. Set CIB 4. Circ cs 5. Spot 15 6. Weld st This w surfactor to be 	Neted Operations (Clearly state all pertinent de ns and measured and true central depths for pose to P&A the sub rig up & pull 2 3, P @ 3350' (top of (g, w/65 BBLS 10# b) sx from 30' to su eel plate w/dry ho rell has 8 5/8" 28# e and 5 1/2" 14# cs	Dother Tails and give pertinent dates. In all markers and sumes pertiner ject well as /8" Tubing & Queen). Cap rine w/1/2 sx rface. le marker. Surface Csg. sq set at 344	(Note: Report results of Recompletion Report a neluding estimated date of startin to this work it soon as this rods our of he w/20 sx "C" ct salt gel per	of multiple completion on Well Completion or ind Log form.) g any proposed work. If well is directionally drilled proceedure is approved ple. mt. BBL
3. Describe Proposed or Comp give subsurface location 1. We prop 2. Move in 3. Set CIB 4. Circ cs 5. Spot 15 6. Weld st This w surfac to be	Neted Operations (Clearly state all pertinent de ns and measured and true central depths for pose to P&A the sub rig up & pull 2 3, P @ 3350' (top of (g, w/65 BBLS 10# b) sx from 30' to su eel plate w/dry ho rell has 8 5/8" 28# e and 5 1/2" 14# cs	Dother Tails and give pertinent dates. In all markers and sumes pertiner ject well as /8" Tubing & Queen). Cap rine w/1/2 sx rface. le marker. Surface Csg. sq set at 344	(Note: Report results of Recompletion Report a neluding estimated date of startin to this work it soon as this rods our of he w/20 sx "C" ct salt gel per	of multiple completion on Well Completion or ind Log form.) g any proposed work. If well is directionally drilled proceedure is approved ple. mt. BBL
3. Describe Proposed or Comp give subsurface location 1. We prop 2. Move in 3. Set CIB 4. Circ cs 5. Spot 15 6. Weld st This w surfac to be	Neted Operations (Clearly state all pertinent de ns and measured and true central depths for pose to P&A the sub rig up & pull 2 3, P @ 3350' (top of (g, w/65 BBLS 10# b) sx from 30' to su eel plate w/dry ho rell has 8 5/8" 28# e and 5 1/2" 14# cs	Dother Tails and give pertinent dates. In all markers and sumes pertiner ject well as /8" Tubing & Queen). Cap rine w/1/2 sx rface. le marker. Surface Csg. sq set at 344	(Note: Report results of Recompletion Report a neluding estimated date of startin to this work it soon as this rods our of he w/20 sx "C" ct salt gel per	of multiple completion on Well Completion or ind Log form.) g any proposed work. If well is directionally drilled proceedure is approved ple. mt. BBL
3. Describe Proposed or Comp give subsurface location 1. We prop 2. Move in 3. Set CIB 4. Circ cs 5. Spot 15 6. Weld st This w surfac to be	Neted Operations (Clearly state all pertinent de ns and measured and true central depths for pose to P&A the sub rig up & pull 2 3, P @ 3350' (top of (g, w/65 BBLS 10# b) sx from 30' to su eel plate w/dry ho rell has 8 5/8" 28# e and 5 1/2" 14# cs	Dother Tails and give pertinent dates. In all markers and sumes pertiner ject well as /8" Tubing & Queen). Cap rine w/1/2 sx rface. le marker. Surface Csg. sq set at 344	(Note: Report results of Recompletion Report a neluding estimated date of startin to this work it soon as this rods our of he w/20 sx "C" ct salt gel per	of multiple completion on Well Completion or ind Log form.) g any proposed work. If well is directionally drilled proceedure is approved ple. mt. BBL
3. Describe Proposed or Comp give subsurface location 1. We prop 2. Move in 3. Set CIB 4. Circ cs 5. Spot 15 6. Weld st This w surfac to be	Neted Operations (Clearly state all pertinent de ns and measured and true central depths for pose to P&A the sub rig up & pull 2 3, P @ 3350' (top of (g, w/65 BBLS 10# b) sx from 30' to su eel plate w/dry ho rell has 8 5/8" 28# e and 5 1/2" 14# cs	Dother Tails and give pertinent dates. In all markers and sumes pertiner ject well as /8" Tubing & Queen). Cap rine w/1/2 sx rface. le marker. Surface Csg. sq set at 344	(Note: Report results of Recompletion Report a neluding estimated date of startin to this work it soon as this rods our of he w/20 sx "C" ct salt gel per	of multiple completion on Well Completion or ind Log form.) g any proposed work. If well is directionally drilled proceedure is approved ple. mt. BBL
3. Describe Proposed or Comp give subsurface location 1. We prop 2. Move in 3. Set CIB 4. Circ cs 5. Spot 15 6. Weld st This w surfac to be	Neted Operations (Clearly state all pertinent de ns and measured and true control depths for pose to P&A the sub rig up & pull 2 3, P @ 3350' (top of (g, w/65 BBLS 10# b) sx from 30' to su reel plate w/dry ho rell has 8 5/8" 28# re and 5 1/2" 14# cs at 2550' from surfa	Dother Tails and give pertinent dates. In all markers and sumes pertiner ject well as /8" Tubing & Queen). Cap rine w/1/2 sx rface. le marker. Surface Csg. sq set at 344	(Note: Report results of Recompletion Report a neluding estimated date of startin to this work it soon as this rods our of he w/20 sx "C" ct salt gel per	of multiple completion on Well Completion or ind Log form.) g any proposed work. If well is directionally drilled proceedure is approved ple. mt. BBL
3. Describe Proposed or Comp give subsurface location 1. We prop 2. Move in 3. Set CIB 4. Circ cs 5. Spot 15 6. Weld st This w surfac to be	Neted Operations (Clearly state all pertinent de ns and measured and true control depths for pose to P&A the sub rig up & pull 2 3, P @ 3350' (top of (g, w/65 BBLS 10# b) sx from 30' to su reel plate w/dry ho rell has 8 5/8" 28# re and 5 1/2" 14# cs at 2550' from surfa	Dother all markers and give perimen dates. In all markers and dunes perimer ject well as /8" Tubing & Queen). Cap of rine w/1/2 sx rface. le marker. Surface Csg. sg set at 344 ace.	(Note: Report results of Recompletion Report a neloding estimated date of startin to this work " soon as this p rods our of he w/20 sx "C" ct salt gel per set at 734' of 5', Top of cer	of multiple completion on Well Completion or and Log form.) g any proposed work If well is directionally drilled proceedure is approved ole. nt. BBL cemented to nent is estimated
3. Describe Proposed or Comp give subsurface location 1. We prop 2. Move in 3. Set CIB 4. Circ cs 5. Spot 15 6. Weld st This w Surfac to be	leted Operations (Clearly state all pertinent de ns and measured and true -cricial depths for pose to P&A the sub- rig up & pull 2 3, P @ 3350' (top of 0 g. w/65 BBLS 10# bi- sx from 30' to sup cell plate w/dry ho- rell has 8 5/8" 28# e and 5 1/2" 14# cs at 2550' from surfa	Dother Tails and give pertinent dates. In all markers and sumes pertiner ject well as /8" Tubing & Queen). Cap rine w/1/2 sx rface. le marker. Surface Csg. sq set at 344	(Note: Report results of Recompletion Report a neloding estimated date of startin to this work " soon as this p rods our of he w/20 sx "C" ct salt gel per set at 734' of 5', Top of cer	of multiple completion on Well Completion or ind Log form.) g any proposed work. If well is directionally drilled proceedure is approved ple. mt. BBL
 Describe Proposed or Comp give subsurface location We prop Move in Set CIB Circ cs Spot 15 Weld st This w surfac to be Weld st 	leted Operations (Clearly state all pertinent de ins and measured and true -entical depths for pose to P&A the sub a rig up & pull 2 3, PP @ 3350' (top of 0 ig. w/65 BBLS 10# bi is x from 30' to sup cell plate w/dry ho rell has 8 5/8" 28# re and 5 1/2" 14# cs at 2550' from surface (spoing is top-and correct) (at coffice use)	Dother all markers and give perimen dates. In all markers and dunes perimer ject well as /8" Tubing & Queen). Cap of rine w/1/2 sx rface. le marker. Surface Csg. sg set at 344 ace.	(Note: Report results of Recompletion Report a neloding estimated date of startin to this work " soon as this p rods our of he w/20 sx "C" ct salt gel per set at 734' of 5', Top of cer	of multiple completion on Well Completion or and Log form.) g any proposed work. If well is directionally drilled proceedure is approved ole. nt. BBL Cemented to nent is estimated
 13. Describe Proposed or Comp give suburface location 1. We prop 2. Move in 3. Set CIB 4. Circ cs 5. Spot 15 6. Weld st This w surfac to be 4. Thereby certify mark the fore Signed (This space for Federal or Signed) 	leted Operations (Clearly state all pertinent de ins and measured and true -entical depths for pose to P&A the sub a rig up & pull 2 3, PP @ 3350' (top of 0 ig. w/65 BBLS 10# bi is x from 30' to sup cell plate w/dry ho rell has 8 5/8" 28# re and 5 1/2" 14# cs at 2550' from surface (spoing is top-and correct) (at coffice use)	Dother all markers and give perimen dates. In all markers and dunes perimer ject well as /8" Tubing & Queen). Cap of rine w/1/2 sx rface. le marker. Surface Csg. sg set at 344 ace.	(Note: Report results of Recompletion Report a neloding estimated date of startin to this work " soon as this p rods our of he w/20 sx "C" ct salt gel per set at 734' of 5', Top of cer	of multiple completion on Well Completion or and Log form.) g any proposed work If well is directionally drilled proceedure is approved ole. nt. BBL cemented to nent is estimated
 Describe Proposed or Comp give subsurface location We prop Move in Set CIB Circ cs Spot 15 Weld st This w surfac to be Weld st 	Arie office use	Other Halk and give pertinent dates. In all markers and times pertiner ject well as /8" Tubing & Queen). Cap of rine w/1/2 sx rface. le marker. Surface Csg. sg set at 344 ace.	(Note: Report results of Recompletion Report a netuding estimated date of startin to this work '' soon as this t rods our of he w/20 sx "C" ct salt gel per set at 734' of 5', Top of cer	of multiple completion on Well Completion or and Log form.) g any proposed work. If well is directionally drilled proceedure is approved ole. nt. BBL Cemented to nent is estimated