

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

**RECEIVED**  
NEW MEXICO OIL CONSERVATION COMMISSION

AUG 21 1972

O. C. C.

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B9646</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>Monterey State</b>
9. Well No. <b>5</b>
10. Field and Pool, or Wildcat <b>Shugart Yates, SR, Q</b>
12. County <b>Eddy</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator  
**Shenandoah Oil Corporation** ✓

3. Address of Operator  
**1500 Commerce Building, Fort Worth, Texas 76102**

4. Location of Well  
UNIT LETTER **0** **990** FEET FROM THE **south** LINE AND **2310** FEET FROM  
THE **east** LINE, SECTION **32** TOWNSHIP **18S** RANGE **31E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
**3571 G.L.**

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <b>Convert to water injection</b> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**It is planned to start work immediately to convert this well to water injection as follows:**

**T.D. 2691' - PBTD 2688'      Perforations 2652 - 2666'**  
**8 5/8" csg. set @ 920'**  
**5 1/2" csg. set @ 2691'**

1. Pull rods, tubing and C.O. to T.D. 2688'
2. Run internally plastic coated tubing w/tension packer set at approximately 2600'
3. Load annulus w/inert fluid. Install valve and gauge on surface
4. Place well on injection

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED T. L. Bates TITLE Vice President DATE 8/17/72

APPROVED BY A. A. Gressett TITLE OIL AND GAS INSPECTOR DATE AUG 21 1972

CONDITIONS OF APPROVAL, IF ANY: