

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

**RECEIVED**  
NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

OCT 10 1967

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <b>Dry Hole</b>	7. Unit Agreement Name
2. Name of Operator <b>Ernest A. Hanson</b>	8. Farm - Lease Name <b>Santa Fe Land Imp. Co.</b>
3. Address of Operator <b>P. O. Box 1515, Roswell, New Mexico</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>C</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>1980</b> FEET FROM THE <b>West</b> LINE, SECTION <b>17</b> TOWNSHIP <b>19-S</b> RANGE <b>26-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3385' GL</b>	12. County <b>Eddy</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Total Depth: 9490' dolomite  
Casing: 8-5/8" @ 1338' w/760 sx.  
5-1/2" @ 9250' w/525 sx.

Permission to plug the captioned well in the following manner is hereby requested:

1. Pull approximately 5800' of 5-1/2" casing.
2. Set the following cement plugs in heavy mud:  
25 sx. @ 9137-9369'  
25 sx. in-and-out of shot-off 5-1/2" casing approx. 5800'  
25 sx. @ 4136-4056'  
35 sx. @ 1410-1300'  
25 sx. @ 752-672'  
10 sx. @ surface
3. Erect regulation dry hole marker.
4. Clean up location and make ready for OCC inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Ernest A. Hanson* TITLE Explor. Mgr. DATE Oct. 9, 1967

APPROVED BY *W. A. Gressett* TITLE OIL AND GAS INSPECTOR DATE OCT 10 1967