

FIELD REPORT FOR CEMENTING OF WELLS

Plugging 3-2-64, loaded hole with heavy mud. Set 50 sack plugs at 6879, 4501 and 1848. First plug set at 12:45 PM. Last plug 4:45 PM. Well to be taken as a water well by rancher. Monitor to be placed in casing after the