

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

JUL 10 1968

O. C. C.
ARTESIA, OFFICE

5a. Indicate Type of Lease

State ☒ Fee ☐

5. State Oil & Gas Lease No.

E-7256

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Martin Yates, III ✓	8. Farm or Lease Name State N & C
3. Address of Operator 207 S. Fourth, Artesia, N. Mex. 88210	9. Well No. 1
4. Location of Well UNIT LETTER 660 FEET FROM THE South LINE AND 543 FEET FROM THE West LINE, SECTION 6 TOWNSHIP 19 South RANGE 29 East NMPM.	10. Field and Pool, or Wildcat Millman, San Andres, North
15. Elevation (Show whether DF, RT, GR, etc.) 3380' GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to Plug and Abandon as follows:

Pull as much 5½" casing as possible, estimated 1300'.
Set 15 sack cement plug over perforations at 2612' to 2625'.
Fill hole with heavy mud (Aguajel). Spot 25 sack cement plug in stub of 5½" casing.
Spot 25 sack cement plug at base of surface pipe.
Set regulation marker in 10 sack cement plug at surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Nola Carder TITLE Bookkeeper DATE 7-9-68

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE JUL 10 1968

CONDITIONS OF APPROVAL, IF ANY: