

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985
c/5f

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Chevron U.S.A. Inc. ✓

3. ADDRESS OF OPERATOR

P.O. Box 670, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit K, 1650 FSL and 1650 FWL

RECEIVED

APR 05 '89

O. C. D.

ARTESIA, OFFICE

5. LEASE DESIGNATION AND SERIAL NO.

NM014103

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Littlefield AB Fed

9. WELL NO.

10. FIELD AND/POOL, OR WILDCAT

Delaware

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 22, T18S, R31E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work performed: 3/17/ thru 3/21/89

POOH w/production equipment. Test tubing to 4500psi. OK. Load and test annulus to 300psi. ok. Frac Delaware perfs down 2 7/8" tubing w/38,300 gallons 40# gel, 73,208# 12/20 Brady sand. Flush w/KCL. Swab. Clean out sand from 4925' to 5016'. RIH w/production tubing to 4882'. Run rods and pump. Space out and hang on. Turn over to production.

18. I hereby certify that the foregoing is true and correct

SIGNED L. K. Emore

TITLE Technical Assistant

DATE 3-27-89

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE

APR 8 1989

*See Instructions on Reverse Side