Form 9-331	-	INITED STATES	SUBMIT IN PLIC	TE. Form approved.
(May 1963)	DEPAR	MENT OF THE INTE		
	(	GEOLOGICAL SURVEY		N. M. 06814
SI	INDRY NOT	ICES AND REPORTS	S ON WELLS	6. IF INDIAN, ALLOTTEE OR TE
			ug back to a different reservoir. ch proposais.)	
1.				7. UNIT AGREEMENT NAME
OIL GAS	LL OTHER	Dry hole		
2. NAME OF OPERATO		/		8. FARM OR LEASE NAME
Hanson ADDRESS OF OPER	n Oil Comp	any /		9. WELL NO.
		Roswell, New M	exico 88201	2
4. LOCATION OF WEL See also space 17	L (Report location of	clearly and in accordance with	any State requirements.*	10. FIELD AND POOL, OR WILDO
At surface 1980' FNL & 660' FEL Sec. 30, T-19-S, R-31-E, N.M.P.M.				NO. Hackberry 11. SEC., T., B., M., OR BLK. AND
		· ·	-	SURVEY OF ARBA
	Eaay	County, New Mex	100	Sec. 30 - 195
14. PERMIT NO.	······································	15. ELEVATIONS (Show whethe		12. COUNTY OR PARISH 13. ST
<u></u>		3455° GL	s	Eddy 🗄 🗍 N.
16.	Check A	ppropriate Box To Indicate	e Nature of Notice, Report,	or Other Data
	NOTICE OF INTER			BSEQUENT REPORT OF :
TEST WATER SHI	JT-OFF	PULL OR ALTER CABING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT		MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTEBING CASING
SHOOT OR ACIDIZ		ABANDON•	BHOOTING OR ACIDIZING	ABANDONMENT
REPAIR WELL		CHANGE PLANS	(Other) (Note: Report_r	sults of multiple completion on Wel
(Other)	D OR COMPLETED OPI	ERATIONS (Clearly state all pert	inent details, and give pertinent	completion Report and Log form.) lates, including estimated date of str ertical depths for all markers and so
8-13-69	WOC 24 h	nours. Drilling	e surface. WOC. out cement plug	
	stuck in	cement cutting	s @ 550' inside o	
8-14-69	Could no be fille the surf	ot recover drill ad with rock and	s @ 550' inside ing tools. Prop a 10 sack cemen	of casing. ose that the casing
8-14-69	Could no be fille the surf	ot recover drill ed with rock and `ace. The rig w re-spudded.	s @ 550' inside ing tools. Prop a 10 sack cemen	of casing. ose that the casing t plug be set at
8-14-69	Could no be fille the surf	ot recover drill ed with rock and `ace. The rig w re-spudded. <b>RE</b>	s @ 550' inside ing tools. Prop a 10 sack cement ill then be skidd	of casing. ose that the casing t plug be set at
8-14-69	Could no be fille the surf	ot recover drill ed with rock and `ace. The rig w re-spudded. RE	s @ 550' inside ing tools. Prop a 10 sack cemen will then be skide CEIVED	of casing. ose that the casing t plug be set at
8-14-69 18. I hereby certify	Could no be fille the surf the well	ot recover drill ed with rock and `ace. The rig w re-spudded. RE	S @ 550' inside ing tools. Prop a 10 sack cement ill then be skide CEIVED UG 2 7 1969 D. C. C. RTESIA, GETICE	of casing. ose that the casing plug be set at led to the west and a set of the set at led to the set at
18. I bereby certify	Could no be fille the surf the well	ot recover drill ed with rock and `ace. The rig w re-spudded. RE	s @ 550' inside ing tools. Prop a 10 sack cement will then be skide CEIVED UG 2 7 1969 D. C. C.	of casing. ose that the casing t plug be set at
18. I hereby certify a SIGNED	Could no be fille the surf the well	t recover drill d with rock and ace. The rig w re-spudded. RE A he true and correct TITLE _	S @ 550' inside ing tools. Prop a 10 sack cement ill then be skide CEIVED UG 2 7 1969 D. C. C. RTESIA, GETICE	of casing. ose that the casing plug be set at led to the west and his set at the casing to the set at the set
18. I hereby certify SIGNED (This space for )	Could no be fille the surf the well	t recover drill d with rock and ace. The rig w re-spudded.	S @ 550' inside ing tools. Prop a 10 sack cement ill then be skide CEIVED UG 2 7 1969 D. C. C. RTESIA, GETICE	of casing. ose that the casing plug be set at led to the west and his set at the casing to the set at the set
18. I hereby certify SIGNED (This space for )	Could no be fille the surf the well	t recover drill d with rock and ace. The rig w re-spudded.	S @ 550' inside ing tools. Prop a 10 sack cement ill then be skide CEIVED UG 2 7 1969 D. C. C. RTESIA, GETICE	of casing. ose that the casing plug be set at led to the west and a set of the set of the barrent of the barrent of the set of the barrent of the barrent of the set of the barrent
18. I hereby certify SIGNED (This space for )	Could no be fille the surf the well	t recover drill d with rock and ace. The rig w re-spudded.	S @ 550' inside ing tools. Prop a 10 sack cement ill then be skide CEIVED UG 2 7 1969 D. C. C. RTESIA, GETICE	of casing. ose that the casing plug be set at led to the west and an an a
18. I hereby certify SIGNED (This space for )	Could no be fille the surf the well	t recover drill d with rock and ace. The rig w re-spudded. RE A ts true and correct TITLE _ Ace use) TITLE _	S @ 550' inside ing tools. Prop a 10 sack cement ill then be skide CEIVED UG 2 7 1969 D. C. C. RTESIA, GETICE	of casing. ose that the casing plug be set at led to the west and a set of the set of the barrent of the barrent of the set of the barrent of the barrent of the set of the barrent