

at end of test. Control valves operated as indicated on closing unit manifold at end of test. Bop extentions were not hooked up. No test desired to the lower kelly cock (not in rig inventory at time of test).

YELLOW JACKET TOOLS AND SERVICES, INC.

ODESSA, TEXAS

Test made by R. E. Daniel *R E Daniel*