

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
310 Old Santa Fe Trail, Room 206  
Santa Fe, New Mexico 87503

RECEIVED

JAN 09 1997

WELL API NO. 30 - 015 - 21244
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-2502
7. Lease Name or Unit Agreement Name Mesa Com #1
8. Well No. 1
9. Pool name or Wildcat Cemetery Morrow

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Rhombus Operating Co., Ltd.
3. Address of Operator 200 N. Loraine, Suite 1270, Midland, TX 79701	4. Well Location Unit Letter <u>F</u> : 1980 Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>20</u> Township <u>20S</u> Range <u>25E</u> NMPM County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3507.1' GR 3522' RKB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP @ 8,400' Capped with 35' cmt  
Cut and pull 5-1/2" csg @ +/- 6,000' by free point  
Set 45 sx cmt plug across 5-1/2" csg stub (50' in & 50' out) Tag  
Set 45 sx cmt plug at 4500' - 4600'  
Set 60 sx cmt plug across 8-5/8" csg shoe at 3,200' - 3,300' Tag  
Set 35 sx cmt plug at 1700' - 1800'  
Set 35 sx cmt plug across 13-3/8" csg shoe at 155' - 255' Tag or bring to surface.  
Set 10 sx cmt plug to surface  
Cap the well, install dryhole marker, and restore surface location.

See wellbore diagrams

25# salt gel per bbl of 10# brine between plugs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lorn C. Painter TITLE PET. ENG. DATE 1/7/97

TYPE OR PRINT NAME LORN C. PAINTER TELEPHONE NO. (95) 683-8873

(This space for State Use)

Jim W. Gurn B6X

APPROVED BY District Supervisor TITLE District Supervisor DATE 1-15-97

CONDITIONS OF APPROVAL, IF ANY: