

State of New Mexico
Energy, Minerals and Natural Resources Department

DISTRICT I

P.O. Box 1980, Hobbs NM 88240

DISTRICT II

P.O. Drawer DD, Artesia NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-22146

5. Indicate Type of Lease
State ☒ FEE ☐

6. State Oil & Gas Lease No.
E-952

7. Lease Name or Unit Agreement Name
STATE HU COM

8. Well No.
1

9. Pool Name or Wildcat
UNDESIGNATED CANYON

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3528' GR

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE " APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL ☐ GAS ☐
WELL ☒ WELL ☐ OTHER ☐

2. Name of Operator
Yates Petroleum Corporation

3. Address of Operator
105 South 4th., Artesia, NM 88210

4. Well Location
Unit Letter N : 660 Feet From The SOUTH Line and 2080 Feet From The WEST Line
Section 7 Township 19S Range 28E NMPM EDDY COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

YATES PETROLEUM CORPORATION requests permission to plug and abandon above well as follows:

MIRU; ND wellhead, NU BOP. If tubing is installed, release packer & TOH w/ tubing.
RU wireline. RIH w/ 5-1/2" CIBP & set @ 8800'. Dump 35' cement on plug. RIH w/ 5-1/2" CIBP & set @ 8500'. Dump 35' cement on plug. RIH w/ casing cutter & cut casing @ 8000'. RD wireline. TOH w/ 5-1/2" casing.
Rig up cementers; TIH w/ tubing to 8050', spot 100' cement plug 8050' to 7950'; WOC & tag.
Spot 100' cement plug 5950-5850'; spot 100' cement plug 3400-3300'; spot 100' cement plug 2250-2150'. WOC & tag. Spot 100' cement plug 450-350'. Spot 60' cement plug @ surface.
Cut off wellhead & install regulation marker.

Notify OCD 24 hrs. prior to any work done

Salt gel mud consisting of 10#
Brine W/25# of gel per bbl
must be placed between each plug

I hereby certify that the information above is a true and complete to the best of my knowledge and belief.

SIGNATURE Donna Clack TITLE Operations Technician DATE 3/11/02

TYPE OR PRINT NAME DONNA CLACK TELEPHONE NO 505-748-1471

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep DATE MAR 15 2002

CONDITIONS OF APPROVAL, IF ANY