

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	<input checked="" type="checkbox"/>
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-2633

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Amoco Production Company <input checked="" type="checkbox"/>	8. Farm or Lease Name State ER #2 Com.
3. Address of Operator P. O. Box 68 Hobbs, NM 88240	9. Well No. 1
4. Location of well UNIT LETTER <u>G</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>6</u> TOWNSHIP <u>19-S</u> RANGE <u>29-E</u> NMPM.	10. Field and Pool, or Wildcat North Turkey Ind. Tract Morrow
11. Elevation (Show whether DF, RT, GR, etc.) 3413 RDB	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST A <input type="checkbox"/>	MENT JOB <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Request permission to plug and abandon well per the following:

Pull 2-3/8" tubing. Set a cast iron bridge plug at 11,100' and cap with 35' of cement. Spot a 25-SX Class H cement plug from 8600' to approximately 8450'. Spot a 20-SX Class H Cement plug from 4230' to approx. 4130'. Rig up and run free point to determine where to cut 5-1/2" casing. Top of cement at approx. 3550'. Cut and pull 5-1/2" casing from above free point. Spot a 35-SX Class H cement plug 50' in and 50' out of 5-1/2" casing stub. Spot a 50-SX Class H cement plug from 475'-375' inside the 9-5/8" casing across the 13-3/8" casing shoe. Spot a 20-SX Class H cement surface plug and weld cap on. Install P X A marker.

RECEIVED

JUL 16 1980

0+4-NMOC, A 1-Hou 1-Susp 1-LBG

O. C. D.
ARTESIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bob Davis TITLE Admin. Analyst DATE 7-15-80

APPROVED BY Mih Wilkin TITLE JUL 17 1980 DATE OIL AND GAS INSPECTOR
CONDITIONS OF APPROVAL, IF ANY: Notify N.M.O.C.C. in sufficient time to witness
Plugging