

Packers failed on DST #1 9390-9726;

TD 9726; DST #2 9412-9726:

TO (30 min) very weak blo, incr to weak blo (1/8" ck)

SI (60 min)

TO (60 min) weak blow

SI 120 min) No gas

Recovered: 375' DF

Bottom

IH 4573

IF 277-277

ISIP 439

2nd F 277-300

FSIP 716

FH 4573

BHT 152 Deg; Sampler: 25 cc DF.

TD 9726'; MW 9; Vis 45; 5 Fil; Ph 9; DST #3 8163-8200 (Cisco)

TO (1½ hrs) weak blo thruout

SI (3 hrs) gas bubbles

TO (1 hr) dead

SI 2 hrs) gas bubbles

Recovered: 7200' water (sulfur)

IH 3909 3894

FH 3831 3778

IF 450-3143 468-3108

ISI 3168 3134

2nd F 3168-3168 3134-3134

FSI 3168 3134