

N. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	/
FILE	/ ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

W MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

APR 06 1981

O. C. D.

ARTESIA, OFFICE

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
Morrison Com.	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Und. W. Four Mile Draw Morrow	
12. County	
Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL <input type="checkbox"/>	GAS WELL <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>
1. Name of Operator		
Dorchester Exploration, Inc. ✓		
2. Address of Operator		
1100 Midland National Bank Tower, Midland, Texas 79701		
3. Location of Well		
UNIT LETTER	L	1980
		FEET FROM THE South LINE AND 660 FEET FROM
THE West	LINE, SECTION 5	TOWNSHIP 19-S RANGE 26-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP at 9080' and spot 10 sxs cement on top. Run free point and cut 4-1/2" csg. at free point. Spot 35 sx plug 50' in and out of 4-1/2" csg. stub. RIH and tag cement plug. Spot a 35 sx plug at each of the following depths. 7250'-7150', 6015'-5915', 4100'-4000', 2500'-2400', 1362'-1262'. RIH and tag cement plug. Spot 35 sx plug at 360'-260' with 10 sx plug at surface. Cut off 8-5/8" wellhead and weld on steel plate. Set dry hole marker as prescribed by NMOCC regulations. Clean up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Rick O'Bannon Rick O'Bannon TITLE Proration Administrator DATE April 3, 1981

APPROVED BY M. Williams TITLE OIL AND GAS INSPECTOR SUPERVISOR, DISTRICT II DATE APR 13 1981

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness

Plugging