STATE OF NEW MEXICO ENERGY and MINERALS DEPARTMENT

	-	_
DISTRIBUTION	i .	
SANTA FE		İ
rice	11	1/
U.S.G.S.		1
LANG OFFICE	I	1
	$\overline{}$	

CONDITIONS OF APPROVAL, IF ANY:

DISTRIBUTION							
	P. O. 80	X 2088 RECEIVED	Farm C-103				
SANTA PE	SANTA FE. NE	V MEXICO 8750 TVED	Revised 10-1-				
PILE !!							
U.S.G.S.			Sd. Indicate Type of Lease				
LANG OFFICE		APP OF 100	State X Fee				
OPERATOR		APR 05 '88	5. State CII & Gas Lease No.				
\			LG0462				
		I WELLS O. C. D.	1 100402				
SUNDR	Y NOTICES AND REPORTS ON	WELLS					
TASIJAda, 360 100 000	OF LOS SEMMIL ILOUM C-1011 LOS 20	CH PHOPOSALS.)					
i			7. Unit Agreement Name				
OIL SAS X	OTHER-		GARDNER DRAW UNIT				
2. Name of Operator							
	/		8. Farm or Lease I-ame				
TOTAL MINATOME CORP	ORATION V		MARONER DRAW UT				
J. Address of Operator			9. Well No.				
500 DALLAS STREET,	SHITE 400		1				
<u> </u>			, ~				
4. Location of well			10. THEDRER "HOTRALL				
C 1	980 PEET PROM THE WEST	660	MORROW				
	7627 7400 742		THE THE PARTY WAS TO BE TO THE PARTY WAS				
NODWY	20 100	0.1-					
THE NORTH LINE, SECTIO	20 TOWNSHIP 19S	RANGE ZIE WM	· ((((((((((((((((((((((((((((((((((((
· ·							
	15. Elevation (Show whether	DF, RT, GR, esc.)	12. County				
	4379' KB						
			EDLY ()				
Check A	appropriate Box To Indicate 🗅	lature of Notice, Report or (Other Data				
NOTICE OF IN			NT REPORT OF:				
		30032402	NI REPORT OF.				
							
PERPORM REMEDIAL WORK	PLUE AND ABANDON X	REMEDIAL WORK	ALTERING CASING				
TEMPORARILY ABANDON		COMMERCE DRILLING SPHS.	PLUE AND ABANDONMENT				
PULL OR ALTER CASING X	CHANGE PLANS	CASING TEST AND CEMENT JOS					
7.000 on melen another							
		OTHER					
OTHER							
17. Describe Proposed or Completed Ope	rations (Clearly state all pertinent det	tils, and give pertinent dates, includi	ng estimated date of starting any proposed				
work) SEE RULE 1103.							
WELL HAS SET OF PER	FORATIONS 7857-67' AND (CIBP ABOVE AT 7800' WIT	H 24' OF CEMENT ON TOP.				
CURRENT PERFORATION	S ARE 7018-7188'.		WELL HAS SET OF PERFORATIONS 7857-67' AND CIBP ABOVE AT 7800' WITH 24' OF CEMENT ON TOP. CURRENT PERFORATIONS ARE 7018-7188'.				
LOAD HOLE WITH 9.5	PPG MUD TO KILL WELL. PO	OOH W/GUIBERSON UNI-PAC	KER VI AND 2 3/8" TBG.				
RIH W/TBG AND SPOT	3 SACKS CEMENT AT PBTD (OF 7776'. POOH. RBIH W	/CIBP AND SET AT 7000'.				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CI	OF 7776'. POOH. RBIH W BP. LOAD HOLE WITH 9.5	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE.				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS	3 SACKS CEMENT AT PBTD (OF 7776'. POOH. RBIH W BP. LOAD HOLE WITH 9.5	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE.				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CII "H" CEMENT AT 5950'. I	OF 7776'. POOH. RBIH W BP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PRO	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CII" "H" CEMENT AT 5950'. I DDUCTION CASING AT 5850	OF 7776'. POOH. RBIH W BP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PROAT 5850'. TAG TOP C	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CIP "H" CEMENT AT 5950'. I DDUCTION CASING AT 5850 OF CEMENT. SPOT 25 SACK	OF 7776'. POOH. RBIH W BP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA S CLASS "H" CEMENT AT I	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PROAT 5850'. TAG TOP COEPTHS: 5600', 4250'	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CII" "H" CEMENT AT 5950'. I DDUCTION CASING AT 5850	OF 7776'. POOH. RBIH W BP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA S CLASS "H" CEMENT AT I	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PROAT 5850'. TAG TOP C	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CIP "H" CEMENT AT 5950'. I DDUCTION CASING AT 5850 OF CEMENT. SPOT 25 SACK	OF 7776'. POOH. RBIH W BP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA S CLASS "H" CEMENT AT I	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PROAT 5850'. TAG TOP COEPTHS: 5600', 4250'	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CIP "H" CEMENT AT 5950'. I DDUCTION CASING AT 5850 OF CEMENT. SPOT 25 SACK	OF 7776'. POOH. RBIH W BP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA S CLASS "H" CEMENT AT I	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PROAT 5850'. TAG TOP COMEPTHS: 5600', 4250' CEMENT.	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CII "H" CEMENT AT 5950'. I DDUCTION CASING AT 5850' OF CEMENT. SPOT 25 SACK AND 3280'. SPOT 35 SA	OF 7776'. POOH. RBIH W BP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA S CLASS "H" CEMENT AT I CKS CLASS "H" CEMENT AT	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING 1765'. TAG TOP OF				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PROAT 5850'. TAG TOP COMEPTHS: 5600', 4250' CEMENT.	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CII"H" CEMENT AT 5950'. I DDUCTION CASING AT 5850' OF CEMENT. SPOT 25 SACK AND 3280'. SPOT 35 SACK 'H" CEMENT AT 10' TO SUR	OF 7776'. POOH. RBIH WBP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA S CLASS "H" CEMENT AT I CKS CLASS "H" CEMENT AT	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING 1765'. TAG TOP OF				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PROAT 5850'. TAG TOP COMEPTHS: 5600', 4250' CEMENT.	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CII "H" CEMENT AT 5950'. I DDUCTION CASING AT 5850' OF CEMENT. SPOT 25 SACK AND 3280'. SPOT 35 SA	OF 7776'. POOH. RBIH WBP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA S CLASS "H" CEMENT AT I CKS CLASS "H" CEMENT AT	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING 1765'. TAG TOP OF				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PROPERTY FOR THE SECOND SE	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CII"H" CEMENT AT 5950'. I DDUCTION CASING AT 5850' OF CEMENT. SPOT 25 SACK AND 3280'. SPOT 35 SACK 'H" CEMENT AT 10' TO SUR	OF 7776'. POOH. RBIH W BP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA S CLASS "H" CEMENT AT CKS CLASS "H" CEMENT AT FACE. MARK WELL WITH A E MEAN GROUND LEVEL. T	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING 1765'. TAG TOP OF 4 4" DIAMETER STEEL THE MARKER SHALL READ:				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PROPERTY FOR THE SECOND SE	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CII"H" CEMENT AT 5950'. I ODUCTION CASING AT 5850' OF CEMENT. SPOT 25 SACK AND 3280'. SPOT 35 SACK AND TOP OF CEMENT AT 10' TO SURE THE EXTENDING TO 4' ABOV	OF 7776'. POOH. RBIH W BP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA S CLASS "H" CEMENT AT CKS CLASS "H" CEMENT AT FACE. MARK WELL WITH A E MEAN GROUND LEVEL. T	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING 1765'. TAG TOP OF 4 4" DIAMETER STEEL THE MARKER SHALL READ:				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PROPERTY FOR THE SECOND SE	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CII"H" CEMENT AT 5950'. I ODUCTION CASING AT 5850' OF CEMENT. SPOT 25 SACK AND 3280'. SPOT 35 SACK AND TOP OF CEMENT AT 10' TO SURE THE EXTENDING TO 4' ABOV	OF 7776'. POOH. RBIH W BP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA S CLASS "H" CEMENT AT CKS CLASS "H" CEMENT AT FACE. MARK WELL WITH A E MEAN GROUND LEVEL. T	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING 1765'. TAG TOP OF 4 4" DIAMETER STEEL THE MARKER SHALL READ:				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PROPERTY FOR THE SECOND SE	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CII"H" CEMENT AT 5950'. I ODUCTION CASING AT 5850' OF CEMENT. SPOT 25 SACK AND 3280'. SPOT 35 SACK AND TOP OF CEMENT AT 10' TO SURE THE EXTENDING TO 4' ABOV	OF 7776'. POOH. RBIH W BP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA S CLASS "H" CEMENT AT CKS CLASS "H" CEMENT AT FACE. MARK WELL WITH A E MEAN GROUND LEVEL. T	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING 1765'. TAG TOP OF 4 4" DIAMETER STEEL THE MARKER SHALL READ:				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PROPERTY FOR THE SECOND SE	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CII"H" CEMENT AT 5950'. I ODUCTION CASING AT 5850' OF CEMENT. SPOT 25 SACK AND 3280'. SPOT 35 SACK AND TOP OF CEMENT AT 10' TO SURE THE EXTENDING TO 4' ABOV	OF 7776'. POOH. RBIH W BP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA S CLASS "H" CEMENT AT CKS CLASS "H" CEMENT AT FACE. MARK WELL WITH A E MEAN GROUND LEVEL. T	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING 1765'. TAG TOP OF 4 4" DIAMETER STEEL THE MARKER SHALL READ:				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PROPERTY FOR THE SECOND SE	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CII"H" CEMENT AT 5950'. I ODUCTION CASING AT 5850' OF CEMENT. SPOT 25 SACK AND 3280'. SPOT 35 SACK AND TOP OF CEMENT AT 10' TO SURE THE EXTENDING TO 4' ABOV	OF 7776'. POOH. RBIH W BP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA S CLASS "H" CEMENT AT CKS CLASS "H" CEMENT AT FACE. MARK WELL WITH A E MEAN GROUND LEVEL. T	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING 1765'. TAG TOP OF 4 4" DIAMETER STEEL THE MARKER SHALL READ:				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PROPERTY FOR THE SECOND SE	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CII"H" CEMENT AT 5950'. I ODUCTION CASING AT 5850' OF CEMENT. SPOT 25 SACK AND 3280'. SPOT 35 SACK AND TOP OF CEMENT AT 10' TO SURE THE EXTENDING TO 4' ABOV	OF 7776'. POOH. RBIH W BP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA S CLASS "H" CEMENT AT CKS CLASS "H" CEMENT AT FACE. MARK WELL WITH A E MEAN GROUND LEVEL. T	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING 1765'. TAG TOP OF 4 4" DIAMETER STEEL THE MARKER SHALL READ:				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PROPERTY FOR THE SECOND SE	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CII "H" CEMENT AT 5950'. I DDUCTION CASING AT 5850' OF CEMENT. SPOT 25 SACK AND 3280'. SPOT 35 SA "H" CEMENT AT 10' TO SUR TE EXTENDING TO 4' ABOV "ELL NO. 1, SECTION 20,	OF 7776'. POOH. RBIH WBP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA S CLASS "H" CEMENT AT H CKS CLASS "H" CEMENT AT FACE. MARK WELL WITH A E MEAN GROUND LEVEL. T T19S, R21E, EDDY COUNTY	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING 1765'. TAG TOP OF 4 4" DIAMETER STEEL THE MARKER SHALL READ:				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PRO AT 5850'. TAG TOP COMENT. SPOT 5 SACKS CLASS "MARKER SET IN CONCREGARDNER DRAW UNIT, W	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CII "H" CEMENT AT 5950'. I DDUCTION CASING AT 5850' OF CEMENT. SPOT 25 SACK AND 3280'. SPOT 35 SA "H" CEMENT AT 10' TO SUR TE EXTENDING TO 4' ABOV "ELL NO. 1, SECTION 20,	OF 7776'. POOH. RBIH WBP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA S CLASS "H" CEMENT AT H CKS CLASS "H" CEMENT AT FACE. MARK WELL WITH A E MEAN GROUND LEVEL. T T19S, R21E, EDDY COUNTY	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING 1765'. TAG TOP OF 4 4" DIAMETER STEEL THE MARKER SHALL READ:				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PRO AT 5850'. TAG TOP COMENT. SPOT 5 SACKS CLASS "MARKER SET IN CONCREGARDNER DRAW UNIT, W	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CIP "H" CEMENT AT 5950'. I ODUCTION CASING AT 5850' OF CEMENT. SPOT 25 SACK AND 3280'. SPOT 35 SACK "H" CEMENT AT 10' TO SUR THE EXTENDING TO 4' ABOV TELL NO. 1, SECTION 20,	OF 7776'. POOH. RBIH WARP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SAS CLASS "H" CEMENT AT ECKS CLASS "H" CEMENT AT EMEAN GROUND LEVEL. TIPS, R21E, EDDY COUNTY	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING 1765'. TAG TOP OF 4 4" DIAMETER STEEL THE MARKER SHALL READ:				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PRO AT 5850'. TAG TOP COMENT. SPOT 5 SACKS CLASS "MARKER SET IN CONCREGARDNER DRAW UNIT, W	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CIP "H" CEMENT AT 5950'. I ODUCTION CASING AT 5850' OF CEMENT. SPOT 25 SACK AND 3280'. SPOT 35 SACK "H" CEMENT AT 10' TO SUR THE EXTENDING TO 4' ABOV TELL NO. 1, SECTION 20,	OF 7776'. POOH. RBIH WBP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SA S CLASS "H" CEMENT AT H CKS CLASS "H" CEMENT AT FACE. MARK WELL WITH A E MEAN GROUND LEVEL. T T19S, R21E, EDDY COUNTY	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING 1765'. TAG TOP OF A 4" DIAMETER STEEL THE MARKER SHALL READ: 7, NEW MEXICO.				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PRO AT 5850'. TAG TOP COMENT. SPOT 5 SACKS CLASS "MARKER SET IN CONCREGARDNER DRAW UNIT, W	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CIP "H" CEMENT AT 5950'. I ODUCTION CASING AT 5850' OF CEMENT. SPOT 25 SACK AND 3280'. SPOT 35 SACK "H" CEMENT AT 10' TO SUR THE EXTENDING TO 4' ABOV TELL NO. 1, SECTION 20,	OF 7776'. POOH. RBIH WARP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SAS CLASS "H" CEMENT AT ECKS CLASS "H" CEMENT AT EMEAN GROUND LEVEL. TIPS, R21E, EDDY COUNTY	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING 1765'. TAG TOP OF 4 4" DIAMETER STEEL THE MARKER SHALL READ:				
RIH W/TBG AND SPOT SPOT 5 SACKS CLASS SPOT 25 SACKS CLASS CASING. CUT 4½" PROPERTY FOR THE SECOND SE	3 SACKS CEMENT AT PBTD ("H" CEMENT ON TOP OF CIP "H" CEMENT AT 5950'. I ODUCTION CASING AT 5850' OF CEMENT. SPOT 25 SACK AND 3280'. SPOT 35 SACK "H" CEMENT AT 10' TO SUR THE EXTENDING TO 4' ABOV TELL NO. 1, SECTION 20,	OF 7776'. POOH. RBIH WARP. LOAD HOLE WITH 9.5 POOH. ATTEMPT TO SAL AND POOH. SPOT 35 SAS CLASS "H" CEMENT AT ECKS CLASS "H" CEMENT AT EMEAN GROUND LEVEL. TIPS, R21E, EDDY COUNTY	/CIBP AND SET AT 7000'. PPG MUD TO SURFACE. VAGE 4½" PRODUCTION CKS CLASS "H" CEMENT EACH OF THE FOLLOWING 1765'. TAG TOP OF A 4" DIAMETER STEEL THE MARKER SHALL READ: 7, NEW MEXICO.				