NEW MEXICO OIL CONSERVATION COMMENSION DRAWER DD ARTESIA, NEW MEXICO

Dorches	ter Erplor	tion Inc.	Lease Liggett	tal C	om.	Well #	* /	
Location of Well	Unit) 1980-50 e	Section	Townsh	nip	Range 26	County EGG	4 4	
Drilling Contractor			Type Folan	of Equ to the	ipment t Byo	t. - <u>2-20</u>	- 78	
* Witnes	L	APPROV	ED CASING PRO	GRAM	,			
Size of Ho	le Size	of Casing	Weight Per Foot	New o	r Used	Depth	Sacks	Cem
17/2"	13	78'	48		19 19 19 19 19 19 19 19 19 19 19 19 19 1	300	350	cù
12/24	8	784	24			1300	750	
77/8"	4	12	11,6			9700	350	
Cementing								
<u>Suctors</u> Inspected	- <u> </u>	<u> </u>	nch <u> </u>)				
				·	date <u>B</u>			
		Size of C	asing <u>8°46</u> S	acks c	ement r	required	650	
			ollar used \underline{I}_{n}					
TD of hole	<u>1900</u> Se	t 300 Fee	t of 8% Inch	LY #	Grade	5-55	Ú.	
<u>New-used</u> c	sg.@\}}((刘 🛛 with 🗺	5 15 0'sacks ne	at cem	ent arc	ound sho	C with 2"	کت د (
	Sax Wall, F	- she	additives $\mathfrak{S}^{\texttt{T}}\mathfrak{o}$	tinodi	C 6# 5	alt Vy	Lougelt	-
+ 200		(334) (034)	. Ω ζ					
Plug down (
Plug down (Cement cir)	culated	Nes	No. o	f Sack	s 80			
Plug down (Cement cir) Cemented b;	culated <u>Addis</u>	Nes	No. o Witne	f Sack ssed b	y Dow	· Lean	er.	
Plug down (Cement cir) Cemented b; Temp. Surve	culated y <u>Hallin</u> ; ey ran @	Jon (AN) (PI	No. o Witne N) Date	f Sack ssed b	y Dow	· Lean	<u>er</u>	
Plug down (Cement cir) Cemented b; Temp. Surv Casing tes	culated y <u>Hollin</u> ey ran @ t @	(AN) (PI (AN) (PI	No. o Witne M) Date M) Date	f Sack ssed b	y <u>b.w</u> top cem	. <u>() es</u> n ient @	-	
Plug down (Cement cir) Cemented b; Temp. Surv Casing tes Method Used	culated y <u>Hollin</u> ey ran @ t @ 1	(AM) (PI (AM) (PI	No. o Witne M) Date M) Date Witne	f Sack ssed b	y <u>S.</u> top cem	nent @		
Plug down (Cement cir Cemented b; Temp. Surv Casing tes Method Used Checked for	culated y Hollin, ey ran @ t @ 1 r shut off	(AM) (PI (AM) (PI (AM) (PI	No. o Witne M) Date M) Date Witne (PM) Date	f Sack ssed b ssed b	y <u>S</u> w top cem y	<u>. Wear</u> nent @		
Plug down (Cement cir Cemented b; Temp. Surv Casing tes Method Used Checked for	culated y Hollin, ey ran @ t @ 1 r shut off	(AM) (PI (AM) (PI (AM) (PI	No. o Witne M) Date M) Date Witne (PM) Date	f Sack ssed b ssed b	y <u>S</u> w top cem y	<u>. Wear</u> nent @		
Plug down (Cement cir Cemented b; Temp. Surv Casing tes Method Used Checked for	culated y Hollin, ey ran @ t @ 1 r shut off	(AM) (PI (AM) (PI (AM) (PI	No. o Witne M) Date M) Date Witne (PM) Date	f Sack ssed b ssed b	y <u>S</u> w top cem y	<u>. Wear</u> nent @		
Plug down (Cement cir Cemented b; Temp. Surv Casing tes Method Used Checked for	culated y Hollin, ey ran @ t @ 1 r shut off	(AN) (PI (AN) (PI (AM) (PI @ (AM)	No. o Witne M) Date M) Date Witne	f Sack ssed b ssed b ssed b	y <u>S</u> top cen y <u></u>	<u>. Wear</u> nent @		